

CARR- 217

ST. PAUL'S LUTHERAN CHURCH

1874

Uniontown

private

**CARR- 217 St. Paul's Lutheran Church**

**St. Paul's Lutheran Church** in Uniontown was organized in 1870 and joined the charge consisting of Baust's, Winter's and Mt. Union churches. By 1874, the congregation was able to build this church. The church cost \$1760 to construct. The small frame structure is representative of late nineteenth century rural ecclesiastical architecture. It has a gable front main facade with a three-story bell tower. The windows on the main facade and tower have pointed arches reminiscent of the popular Gothic style of the period. The side windows, while having rectangular sashes, contain pointed-arch wood cornices to complement the design of the front windows. The Sunday school addition on the east side was constructed in 1950. On the site of the Lutheran Church parking lot stood a two-story log house that Perry and Harriet Jones lived in during the mid-to-late nineteenth century.



DEPARTMENT OF PLANNING AND DEVELOPMENT  
225. N. Center Street  
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

SURVEY NUMBER: CARR-217

NEGATIVE FILE NUMBER:

UTM REFERENCES:  
Zone/Easting/Northing

U.S.G.S. QUAD. MAP: New Windsor

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: church

ORIGINAL USE: church

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:  
Excellent ( ) Good (X)  
Fair ( ) Poor ( )

THEME:

STYLE: Gothic revival - rural

DATE BUILT: 1874

COUNTY: CARROLL

TOWN: Uniontown

LOCATION: 3330 Uniontown Rd

COMMON NAME: St. Paul's Lutheran Church

FUNCTIONAL TYPE: church

OWNER: Trustees of St. Paul's Lutheran Church

ADDRESS: 3330 Uniontown Rd  
Uniontown Md 21157

ACCESSIBILITY TO PUBLIC:  
Yes (X) No ( ) Restricted ( )

LEVEL OF SIGNIFICANCE:  
Local ( ) State ( ) National ( )

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone ( ) Brick (X) Concrete ( ) Concrete Block ( )
- Wall Structure
  - Wood: Log ( ) Post and Beam (X) Balloon ( )
  - Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )
  - Iron ( ) D. Steel ( ) E. Other
- Wall Covering: Weatherboard (X) German Siding ( ) Board and Batten ( )  
Wood Shingle ( ) Shiplap ( ) Novelty ( ) Stucco ( ) Sheet Metal ( )  
Aluminum ( ) Asphalt Shingle ( ) Brick Veneer ( ) Stone Veneer ( )  
Bonding Pattern: Other:
- Roof Structure
  - Truss: Wood (X) Iron ( ) Steel ( ) Concrete ( )
  - Other:
- Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle ( ) Sheet Metal (X)  
Built Up ( ) Rolled ( ) Tile ( ) Other:
- Engineering Structure:
- Other:

Appendages: Porches ( ) Towers (X) Cupolas ( ) Dormers ( ) Chimneys ( ) Sheds ( )  
Ells ( ) Wings ( ) Other:

Roof Style: Gable (X) Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )  
Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( )  
With False Front ( ) Other:

Number of Stories: 1

Number of Bays: 3 x 3

Approximate Dimensions: \_\_\_\_\_

Entrance Location: center

THREAT TO STRUCTURE:  
No Threat (X) Zoning ( ) Roads ( )  
Development ( ) Deterioration ( )  
Alteration ( ) Other:

LOCAL ATTITUDES:  
Positive (X) Negative ( )  
Mixed ( ) Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

church organized 1870, church built 1874  
see U.S. Map - A Walling Town

REFERENCES:

1862 Martenet's Map:  
1877 LG & S Atlas:

SURROUNDING ENVIRONMENT:

Open Lane ( ) Woodland ( ) Scattered Buildings ( )  
Moderately Built Up ( ) Densely-Built Up ( )  
Residential ( ) Commercial ( )  
Agricultural ( ) Industrial ( )  
Roadside Strip Development ( )  
Other:

RECORDED BY:

Jia Betty

ORGANIZATION:

CC Dept. of Planning

DATE RECORDED:

9/84

GE  
EM

77°07'30"  
39°37'30"

4388000m N.


321

# NEW WINDSOR, MD.

## QUADRANGLE

7.5 minute series

CARR-217





1. CARR-217 St. Paul's Lutheran Church
2. Carroll County, Maryland
3. Joe Getty
4. November, 1984
5. Maryland Historical Trust, Annapolis, Md.
6. South & east elevations (camera facing  
northwest)
7. 1/1