

**MARYLAND HISTORICAL TRUST
NR-ELIGIBILITY REVIEW FORM**

NR Eligible: yes ___
no ___

Property Name: Small Structure No. 10083X0 Inventory Number: F-6- 124

Address: MD 77 over Tributary of Owens Creek City: Near Rocky Ridge Zip Code: N/A

County: Frederick USGS Topographic Map: Woodsboro

Owner: MD SHA

Tax Parcel Number: N/A Tax Map Number: N/A Tax Account ID Number: N/A

Project: MD 77 over Tributary of Owens Creek Agency: SHA

Site visit by MHT Staff: ___ no ___ yes Name: _____ Date: _____

Eligibility recommended ___ Eligibility **not** recommended X

Criteria: ___ A ___ B ___ C ___ D Considerations: ___ A ___ B ___ C ___ D ___ E ___ F ___ G ___ None

Is the property located within a historic district? N no ___ yes Name of district: _____

Is district listed? ___ no ___ yes Determined eligible? ___ no ___ yes District Inventory Number: _____

Documentation on the property/district is presented in: Compliance Files

Description of Property and Eligibility Determination: *(Use continuation sheet if necessary and attach map and photo)*


Small Structure No. 10083X0 is a standard concrete slab, with ten-foot span, built in 1924, which has been repaired repeatedly to address scour problems. We have determined that this structure lacks the requisite integrity to be considered eligible for inclusion in the National Register of Historic Places as a type of concrete slab small structure. To be considered for listing, according to the Small Structures on Maryland's Roads, Historic Context Report (p. 4-10) concrete slab small structures should retain integrity of parapets, abutments and wingwalls as primary character defining elements of the substructure. Structural damage requiring past repairs has compromised the integrity of these elements. Recent inspection reports have documented scour, undermining, scaling and extensive honeycombing of the abutments, resulting in a hole (ca. 4 feet by 8 inches). Aggregate is exposed in some areas, and a second hole is opening up in the abutment. The serious scaling of the footing has resulted in considerable loss of material. These defects have undermined the integrity of this structure

Prepared by: Rita M. Suffness

Date Prepared: February 22, 2001

MARYLAND HISTORICAL TRUST REVIEW	
Eligibility recommended ___	Eligibility not recommended <u>X</u>
Criteria: ___ A ___ B ___ C ___ D	Considerations: ___ A ___ B ___ C ___ D ___ E ___ F ___ G ___ None
Comments: _____	
<u>[Signature]</u>	<u>4/4/01</u>
Reviewer, Office of Preservation Services	Date
<u>[Signature]</u>	<u>4/6/01</u>
Reviewer, NR program	Date

Structure No. 10083X0 MD 77 over Tributary of Owens Creek






F-6-124

Small Structure #10083X0

MD 77 over Tributary of Owens Creek

Rocky Ridge vic.



F-6124

Small Structure #10083x0

MD 77 over Tributary of Owens Creek

Rocky Ridge vic.