

MAGI# 1150602304

READ INSTRUCTIONS CAREFULLY BEFORE COMPLETING. RETURN COMPLETED FORM TO APPROPRIATE STATE HISTORIC PRESERVATION OFFICER.

1. Address of property: street NORTH SIDE Main St. at Fifth Alley
 city New Market county Frederick state Maryland zip 21774
 Name of historic district in which property is located: NEW MARKET

2. Description of physical appearance prior to rehabilitation:

The Ursula Plummer House is a two story common bond brick residence, three bays wide with tin hipped roof, front center gable and frame porch which extends across the front on the first level. Attached and to the rear of the brick residence is a small one story frame over log kitchen addition which has been covered with asphalt siding. A tight winder staircase random width flooring and two small brick keystone fireplaces are early 19th century interior architectural features.

3. Statement of significance:

Lot number one (1) Main Street in New Market was one of the earliest structures to be built in Plummer's Part of New Market. The house was apparently built in three (3) stages, rear log part before 1798, center brick portion early 19th century and front porch and center gable c.1900. One of the first owners of the house was Ursula Plummer sister of Samuel Plummer who with Nicholas Hall laid out the town of New Market in 178

Date of construction (if known): _____ Original site Moved _____

4. Name and mailing address of owner

name Mr. + Mrs. William P. Shook
 street 9613 KENTSDALE Drive
 city Potomac, state Maryland zip 20854
 telephone number (during day): area code 301-365-0834

I hereby attest that the information I have provided is, to the best of my knowledge correct, and that I am owner of the property described above.

signature Mrs. Wm. P. Shook date Jan. 23, 1978

For office use only

The structure described above is included within the boundaries of a National Register historic district and contributes does not contribute to the character of the district.

The structure appears does not appear to meet National Register Criteria for Evaluation (36 CFR 60.6) and will likely will not be nominated to the National Register in accord with National Park Service procedures (36 CFR 60).

The structure is located in a district which appears does not appear to meet National Register Criteria for Evaluation (36 CFR 60.6), will likely will not be nominated to the National Register in accord with National Park Service procedures (36 CFR 60), and appears does not appear to contribute to the character of said district.


signature _____ date _____
 State Historic Preservation Officer




This property has been evaluated according to the criteria and procedures set forth by the National Park Service (36 CFR 67) and, if subject to depreciation under section 167 of the Internal Revenue Code of 1954, is hereby certified a historic structure.
does not contribute to the character of the historic district and does not merit certification as a historic structure. Reasons given on the attached sheet.

F-5-60



F-5-60





ROAD CLASSIFICATION

Heavy-duty	4 LANE 6 LANE	Light-duty
Medium-duty	4 LANE 6 LANE	Unimproved dirt
U. S. Route	State Route	Interstate Route

1929
 U.S. GEOLOGICAL SURVEY
 WALKERSVILLE, MARYLAND 22092
 REVISIONS AVAILABLE ON REQUEST

Revisions shown in purple and woodland compiled by the Geological Survey from aerial photographs taken 1980 and other sources. This information not field checked
 Map edited 1986

WALKERSVILLE, MD.
 39077-D3-TF-024
 1953
 PHOTOREVISED 1986
 DMA 5562 IV NE-SERIES V833



F-5-60

Ursula Plummer House (center)

Mankin Shaw

2/74

New Market