

MARYLAND HISTORICAL TRUST ABRIDGED INVENTORY FORM
INTERCOUNTY CONNECTOR PROJECT

Property Name: John Hardisty House
Survey No.: PACS-E19

Resource Summary:

Property Address 3929 Sandy Spring Road, Burtonsville, Montgomery County, Maryland

M:34-39

Historic/Current Function Dwelling/Dwelling

Year Built circa 1920

Property is not individually eligible for National Register because:

It is less than 50 years old and does not meet N.R. exception G

It is an undistinguished example of a common building type or architectural style

Its integrity is compromised by alterations or deterioration

Its historic setting has been compromised by development

Other (explain): _____

Description:

The John Hardisty House is a 1½-story cottage on the south side of Sandy Spring Road in the Burtonsville vicinity, Montgomery County. Constructed circa 1920, the building is an L-shaped plan with wood siding, a metal roof, and a concrete foundation, which is exposed on the north elevation. The windows are double-hung wood sash and there are two brick chimneys; one interior and one exterior.

The structure has five additions: a 1-story, shed-roof porch on the south elevation, which is partially enclosed and supported by concrete piers; a 1-story, shed roof covered-entry porch, also on the south elevation; a deck with an open railing on the west elevation; a 1-story, shed roof addition on the east elevation; and a 1-story, front-gable covered-entry, also on the east elevation.

There are no outbuildings associated with this house.

The property is located on the south side of Sandy Spring Road, with commercial property to the north and east, open space to the south, and residential property to the west. The property's setting is significantly altered by the intrusion of commercial property and a four-lane highway (Route 198).

MHT CONCURRENCE:			
Eligibility	<input type="checkbox"/> Recommended	<input checked="" type="checkbox"/> Not recommended	
Criteria	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	Considerations	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> None
Comments: _____			

Reviewer, Office of Preservation Services		Date	Reviewer, NR Program
			8/27/98
			Date


Preparer:
P.A.C. Spero & Company
October 1996

48t
BM
495
Burtons
Lookout

Inter County Connector Project
Mid-County Alternative
Quad Beltsville
Survey No. ELA M:34-39

John Hardisty House

M:34-39
ELA



BM 364
St Marks
Ch

BM 279

BM 305

BM 219

BM 351

BM 456

BM 482

BM 399



1 ~~PAC 2104~~ M:34-39

2 J. W. Franchly Property

3 Montgomery County

4 Adrienne Couderc

5 February 1996

6 PAC Spew and Company, Towson, MD 21204-

7 3929 Sandy Spring Road, Rear (South) and West
facades

8 1 of 2



1. ~~PAC 417~~ M:34-39

2. John Hardy Property

3. Montgomery County

4. Baltimore County

5. February 1996

6. PAC Service Co., Towson MD 21204

7. 3929 Sandy Spring Road, North east

8. 2 of 2

facades