

File No. 11802 Continued.

CORRESPONDENCE.

a letter from David Peoples, the contractor.

With the return of the enclosures, will you kindly inform me if the stand taken by the contractor, viz: that he is not responsible for the damage on account of change made in the location of the sewer, (amounting to one foot), can be successfully maintained, and what you would advise under the circumstances.

Yours truly,

(Signed) Calvin W. Hendrick,
Chief Engineer.

File No. 11802.

SEWERAGE COMMISSION
OF THE CITY OF BALTIMORE
CHIEF ENGINEER'S OFFICE
AMERICAN BUILDING.

Baltimore, May 5, 1910.

Mr. R. H. Williams,
Asst. Engineer.

Dear Sir:-

I notice that the rear of building No. 1935 Fayette street (back building) is badly cracked, on wall facing Washington street, indicating a settlement of about $\frac{1}{2}$ to 1". This wall was propped before excavation and cannot account for this settlement unless done by jar of driving sheeting. This building is owned by H. C. W. Kumlehn, and living at the above number.

Respectfully,

(Signed) Geo. Robinson,
Inspector.