

File No. 11802 Continged.

CORRESPONDENCE.

tion, has no cellar to it and, therefore, very little foundation, and I also understand there is a very deep well in close proximity to same.

The line was changed from centre of alley to within 2½ feet of building line to centre line and our foreman commenced operations. I will feel very much obliged by your looking into this matter right away, as the Building Inspector is after the proprietor to have same fixed.

I may also inform you that the outside of the house had been painted, and, of course, all cracks covered.

Yours truly,

(Signed) David Peoples,

per Wm. A. Cowie.

File No. 11802.

SEWERAGE COMMISSION
OF THE CITY OF BALTIMORE
CHIEF ENGINEER'S OFFICE
AMERICAN BUILDING.

Baltimore, August 9, 1910.

Mr. A. M. Brosius,
Acting Chief Engineer.

Dear Sir:-

I return herewith letter of David Peoples, dated August 8th, with reference to damage to property in rear of 1935 Fayette street, owned by Mr. H.C.W. Kumlehn. I also send you a report from Inspector Robinson, dated May 5th, and one from Mr. Williams, dated May 7th.

David Peoples is mistaken about the amount of change in the line. The original location was 4 ft. from the north line of Bohemia Court, and the line was moved 1 ft. north or 3 ft. from the north line, in order to avoid a water pipe and also to keep the line away from 146 N. Washington street, which is a three-story building, while the back building in rear of 1935 E. Fayette street is a two-story building. It seemed at the time to be the best location for the sewer and the contractor made no protect.