

DISTRICT MINE INSPECTOR SHALL PROCEED TO THE SCENE OF THE ACCIDENT AND DIRECT THE RESCUE, RELIEF, AND RESTORATION WORK. HE MAY REQUEST THE DIRECTOR OF THE BUREAU TO COME OR DETAIL ADDITIONAL DISTRICT MINE INSPECTORS TO ASSIST IF NECESSARY.

REVISOR'S NOTE: This subsection presently appears as Article 66C, section 647 of the Code. The only changes made are in style.

7-451. CAP LAMPS.—EVERY WORKER AND OTHER PERSON UNDERGROUND SHALL USE ONLY APPROVED ELECTRIC CAP LAMPS FOR PORTABLE ILLUMINATION.

REVISOR'S NOTE: This section presently appears as Article 66C, section 617 of the Code. The final two sentences of this section are proposed for deletion because all mines now have had sufficient time to secure and utilize permissible electric cap lamps. The only other changes made are in style.

7-452. ARCS, SPARKS, AND FLAMES.

BECAUSE OF THE DANGER OF EXPLOSION AND FIRE HAZARDS, EVERY PERSON IN ANY UNDERGROUND WORKING OF A MINE IS PROHIBITED FROM INTENTIONALLY CREATING ANY ARC, SPARK, OR OPEN FLAME, OTHER THAN THOSE WHICH CANNOT BE AVOIDED IN THE NORMAL PERFORMANCE OF WORK.

REVISOR'S NOTE: This section presently appears as Article 66C, section 618 of the Code. The final sentence is proposed for deletion because it appears as section 7-454. The only other changes made are in style.

7-453. WELDING AND CUTTING.

WELDING AND CUTTING WITH ELECTRICITY OR FLAME GENERALLY SHALL BE RESTRICTED TO PLACES WHERE A TROLLEY LOCOMOTIVE IS PERMITTED. WHERE NECESSARY TO WELD AND CUT IN FACE REGIONS, THE WORK SHALL BE UNDER THE DIRECT SUPERVISION OF A CERTIFIED OFFICIAL WHO SHALL TEST FOR GAS BEFORE STARTING OPERATIONS AND FREQUENTLY THEREAFTER. IN EVERY WELDING AND CUTTING OPERATION, PRECAUTION SHALL BE TAKEN AGAINST STARTING A FIRE, AND THE AREA IN WHICH THE OPERATION TAKES PLACE SHALL BE ROCK-DUSTED.

REVISOR'S NOTE: This section presently appears as Article 66C, section 619 of the Code. The