SECTION 1. BE IT ENACTED BY THE GENERAL ASSEMBLY OF MARYLAND, That Section 178(a) of Article 48 — Inspections, of the Annotated Code of Maryland (1971 Replacement Volume and 1976 Supplement) be and it is hereby repealed and reenacted, with amendments, to read as follows:

Article 48 - Inspections

178.

- (a) The owner or user of a boiler or pressure vessel required by this subtitle to be inspected by the chief boiler inspector, or his deputy boiler inspectors, [shall pay] PAYS directly to the chief boiler inspector, upon completion of inspection, fees in accordance with the following schedule:
- (1) Power boilers and high pressure, high temperature water boilers:

Certificate inspections-

Boilers of 50 sq. ft. of heating surface or less.....[\$7.00] \$7

Boilers over 50 sq. ft. of heating surface and less than 4,000 sq. ft. of heating surface.[15.00] \$15

Boilers of 4,000 sq. ft. of heating surface or more and less than 10,000 sq. ft. of heating surface......[20.00] \$20

Boilers of 10,000 sq. ft. of heating surface or more.....[25.00] \$25

External inspections—

Boilers of 50 sq. ft. of heating surface or less.....[5.00] \$5

(2) Heating boilers:

Certificate inspections--

Heating boilers without a manhole.....[7.00] \$7