

(i) Initial certificate inspection of a boiler or pressure vessel not previously registered in Maryland..... no charge

(ii) Certificate inspection of a boiler or pressure vessel, other than a pressure vessel attached to an air compressor, previously registered in Maryland..... \$40.00

(iii) Certificate inspection of a pressure vessel previously registered in Maryland attached to an air compressor..... \$10.00

(iv) Certificate inspection of an additional boiler or pressure vessel previously registered in Maryland, at the same location, on the same date.... \$10.00

(v) Follow-up inspection to determine ~~in~~ compliance..... ~~no charge~~ \$50.00

(2) Inspection of antique or model steam boiler or pressure vessel. \$15.00

(3) Investigation of accident or complaint..... no charge

(4) Special inspections, such as inspection at fabrication or repair facility, ASME joint review, or National Board of ~~Boiler Rules Audit~~ INSPECTION CODE REPAIR REVIEW shall be charged at the following rate, and all expenses such as travel and hotel costs:

(i) Half day (up to 4 hours).....~~\$125.00~~ \$250.00

(ii) Full day (up to ~~7-1~~ 8 hours).....~~\$250.00~~ \$500.00.↓

~~(1) THE COMMISSIONER MAY SET REASONABLE FEES FOR THE ISSUANCE AND RENEWAL OF SPECIAL INSPECTOR COMMISSIONS, INSPECTIONS, AND ITS OTHER SERVICES.~~

~~(2) THE FEES CHARGED SHALL BE SET TO PRODUCE FUNDS TO APPROXIMATE THE COST OF MAINTAINING THE SPECIAL INSPECTOR COMMISSION PROGRAM ESTABLISHED UNDER § 172 OF THIS SUBTITLE AND FOR THE COSTS ASSOCIATED WITH INSPECTING BOILERS AND PRESSURE VESSELS AND ISSUING INSPECTION CERTIFICATES~~

(B) SPECIAL INSPECTOR COMMISSION FEES SHALL BE PAID IN ACCORDANCE WITH THE FOLLOWING SCHEDULE:

(1) COMPETENCY EXAM OR REEXAM.....\$50.00

(2) SPECIAL INSPECTOR COMMISSION.....\$50.00

(3) SPECIAL INSPECTOR COMMISSION RENEWAL OR REPLACEMENT OF IDENTIFICATION CARD.....\$50.00.

~~(b)~~ (C) All moneys received by the Chief Boiler Inspector from [inspection] fees shall be deposited in the General Fund of the State [treasury].

[179.

The Chief Boiler Inspector and the deputy boiler inspectors will, upon entering