

DISTRICT MINE INSPECTOR A GOOD BLUEPRINT OR OTHER EXACT COPY OF THE ORIGINAL MAP FOR HIS OFFICIAL USE. EVERY SIX MONTHS THE OPERATOR SHALL FURNISH AN ADDITIONAL COPY SHOWING ANY EXTENSICNS. THE BLUEPRINT OR OTHER COPY SHALL REMAIN IN THE BUREAU'S CUSTODY AND MAY NOT BE MADE PUBLIC WITHOUT THE OPERATOR'S CONSENT.

REVISOR'S NOTE: This subsection presently appears as Article 66C, section 520 of the Code. The only changes made are in style.

(F) WHEN WORK ON MINE ENDS; ENDORSEMENT AND SIGNING MAP.--IF A MINE IS WORKED OUT OR ABANDONED, WITHIN 60 DAYS, THE OPERATOR SHALL EXTEND THE MAP OF THE MINE TO SHOW CLEARLY ALL WORKED OUT OR ABANDONED TERRITORY. HE SHALL FURNISH THE DISTRICT MINE INSPECTOR WITH A GOOD COPY OF THE MAP, AND A COPY SHALL BE SENT TO THE BUREAU TO BE KEPT AS A PUBLIC DOCUMENT. THE ORIGINAL MAP AND EVERY COPY SHALL CONTAIN A CERTIFICATE SIGNED BY THE MINING ENGINEEP OR SURVEYOR WHO PREPARED IT. THE CERTIFICATE SHALL PROVIDE THAT THE MAP AND COPY ARE EXACT DUPLICATES AND ACCURATELY SHOW THE LINES PORTRAYED. THE DISTRICT MINE INSPECTOR SHALL REVIEW THE COPY TO INSURE THAT IT INCLUDES A SIGNED STATEMENT OF THE MINE FOREMAN STATING THAT HE HAS CAREFULLY EXAMINED THE MAP AND COPY AND THAT IT IS AN ACCURATE COPY OF THE ORIGINAL MAP AND REPRESENTS THE MINE PROPERTY ACCORDING TO HIS PERSCNAL KNCWLEDGE.

REVISOR'S NOTE: This subsection presently appears as Article 66C, section 521 of the Code. The only changes made are in style.

(G) WORKINGS APPROACHING DANGEROUS WATER OR GASES.--IF THE DISTRICT MINE INSPECTOR SUSPECTS THAT ANY MINE WORKING APPROACHES DANGEROUS ACCUMULATIONS OF WATER OR GAS, HE MAY REQUIRE BY SPECIAL SAFETY ORDER THAT THE OPERATOR CAUSE THE SUSPECTED PORTION OF THE MINE TO BE SURVEYED IMMEDIATELY AND ENTERED ON THE MAP OF THE MINE. IF HE SUSPECTS AN EXCESSIVE PROPORTION OF CARBON DIOXIDE OR INSUFFICIENT OXYGEN IN THE ATMOSPHERE OF ANY MINE, HE SHALL TAKE THE TEST PRESCRIBED BY THE BUREAU. IF THE TEST DISCLOSES A VENTILATING CURRENT BELOW OR APPROACHING THE MINIMUM STANDARD, HE SHALL REQUIRE THE OPERATOR, BY WRITTEN SAFETY ORDER, TO IMPROVE IMMEDIATELY THE MINE'S VENTILATION.

REVISOR'S NOTE: This subsection presently appears as Article 66C, section 522 of the Code.