	•	
	Equipment	70,000
(2)	Preparation of detailed plans and	
72/	specifications and construction of a	
	replacement facility within the enhanced	
	secured area at the Maryland Training School.	
	The replacement facility shall contain	
	individual living units, and program space.	
	Construction of the replacement facility	
	shall not begin until the security	
	enhancements on the Fletcher Campus are	
	completed and either the Youth Center to be	
	located at Meadow Mountain in Garrett County	
	or the Youth Center to be located in Charles	
	County or the Youth Center to be located at	
	the Henryton Center in Carroll County is	
	completed, provided, however, that	
	construction shall begin on or after April 1,	
	1984. After construction of the replacement	
	facility is completed, the existing cottage	
	(Unit #13) nearest the school building on the	
	Pratt Campus shall be razed and a portion of	
	this appropriation may be used for that	
	purpose. Representatives of the Juvenile	
	Services Administration, Department of State	
	Planning, and Department of General Services	
	shall meet with appropriate community groups	
	within the vicinity of the Maryland Training	
	School not later than September 1, 1983.	
	(Baltimore County)	2,173,000
(b)	Youth Centers:	
417	-Design,preparedetailedplansand	
(-7-	specifications-for,-and-construct-an-addition	
	tetheexisting-dermitery,-and-renewate-the	
	existing-dormitory,-at-Maple-Run-Youth-Center	
	(Allegany-County)	2167999
	(milegany country)	210,000
(2)	(1) Design, prepare detailed plans and	
ν /	specifications for, and construct a physical	
	activities building at Savage Mountain Youth	
	Center (Garrett County)	195,000
	, , , , , , , , , , , , , , , ,	,
(2)	Design and construct water and sewer systems,	
	a gymnasium, not to exceed 2,600 gross square	
	feet, and make minor repairs to a 40-bed	
	Youth Center at Meadow Mountain Conservation	
	Center (Garrett County). This appropriation	
	is contingent upon certification by the	
	Department of Health and Mental Hygiene to	
	the Budget Committees that there exists a	
	sufficient volume of water at the site to	
	support the facility	735,000