

Dec. 21	3945	James O'Reilly,	do	do	208,	do	-	251	87	
21	3946	William Easby,	Bridges,	Waste and Lock Gates,		do	-	400	00	
21	3947	G. G. Johnston,	For work done on Culvert	237,		-	-	64	00	
21	3948	same,	do	do	234,	-	-	517	25	
21	3949	same,	do	do	239,	-	-	634	00	
21	3950	same,	do	do	241,	-	-	112	00	
21	3951	Rob't P. Dodge,	Services as	assistant Engineer,		-	-			66 66
21	3952	R. Lamar of R.	do	Superintendant of Sections,		-	-			45 00
21	3953	Samuel Chase,	do	Axeman,		-	-			83 00
21	3954	G W Washington	do	Rodman,		-	-			60 00
21	3955	John Hamilton,	do	Axeman,		-	-			34 00
21	3956	Thos. Gore,	do	Rodman,		-	-			90 00
21	3957	George Shafer,	266	20-70 bushels Cement from Hook's Mill,				66	57	
21	3958	B. F. Brannan,	Services as	Rodman,		-	-			45 00
21	3959	H. M. Dungan,	do	assistant Engineer,		-	-			100 00
21	3960	Wm. A. Pratt,	do	pr. do do		-	-			166 66
21	3961	Jno. A. Byers,	do	do do		-	-			500 00
21	3962	Jas. R. Young,	do	Rodman,		-	-			90 00
21	3963	Dan'l Brewer,	do	Cement store keeper,		-	-			90 00
21	3964	Wm. Stait,	do	Rodman,		-	-			90 00
21	3965	John S. Bowls,	do	Chainman,		-	-			61 00
21	3966	J. H. Kidwell,	do	Superintendant of Construction,		-	-			91 50
21	3967	Jno. G. Stone,	do	assistant Engineer,		-	-			200 00
21	3968	L. C. Horter,	do	vol. Rodman,		-	-			60 00
21	3969	C. Weaver,	do	do		-	-			40 00
11	3970	Daniel Pierce,	do	Axeman,		-	-			52 00

147

NC