

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC Clover Hill Farm, McLuckie

AND/OR COMMON Part of Rocky Gap State Park

2 LOCATION

STREET & NUMBER U.S. Route 40 (between Cumberland and Flintstone)

CITY, TOWN Cumberland VICINITY OF Sixth CONGRESSIONAL DISTRICT

STATE Maryland COUNTY Allegany

3 CLASSIFICATION

CATEGORY	OWNERSHIP	STATUS	PRESENT USE	
<input type="checkbox"/> DISTRICT	<input checked="" type="checkbox"/> PUBLIC	<input type="checkbox"/> OCCUPIED	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> MUSEUM
<input checked="" type="checkbox"/> BUILDING(S)	<input type="checkbox"/> PRIVATE	<input checked="" type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL	<input checked="" type="checkbox"/> PARK
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> EDUCATIONAL	<input type="checkbox"/> PRIVATE RESIDENCE
<input type="checkbox"/> SITE	PUBLIC ACQUISITION	ACCESSIBLE	<input type="checkbox"/> ENTERTAINMENT	<input type="checkbox"/> RELIGIOUS
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input checked="" type="checkbox"/> YES: RESTRICTED	<input type="checkbox"/> GOVERNMENT	<input type="checkbox"/> SCIENTIFIC
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> INDUSTRIAL	<input type="checkbox"/> TRANSPORTATION
		<input type="checkbox"/> NO	<input type="checkbox"/> MILITARY	<input checked="" type="checkbox"/> OTHER: storage

4 OWNER OF PROPERTY

NAME Maryland Department of Natural Resources Telephone #:

STREET & NUMBER

CITY, TOWN _____ STATE, zip code _____
VICINITY OF _____

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE, REGISTRY OF DEEDS, ETC. Allegany County Courthouse

Liber #: 366
Folio #: 139

STREET & NUMBER Washington Street

CITY, TOWN Cumberland STATE Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

FEDERAL STATE COUNTY LOCAL

DEPOSITORY FOR SURVEY RECORDS

CITY, TOWN _____ STATE _____

7 DESCRIPTION

AL-III-C-067

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input checked="" type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED DATE _____
<input checked="" type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

On Rocky Gap State Park is a complex known as Clover Hill or the McLuckie farm. It is situated on a hill side just north of U.S. Route 40 with the buildings facing southeast. The complex includes a house, summer kitchen, a cistern, a large barn, wagon sheds and other agricultural buildings. Except for the summer kitchen which is stone and the cistern which is of cast concrete, all the original buildings are of frame construction

The house is a one and a half story three bay bungaloid structure with a deep overhanging porch on three of its four sides. The roof is hipped and steeply pitched. A one story addition also with a hipped roof extends to the northeast from the rear corner of the house. A shed roof extension has been attached to the upper part of the wing giving it a second story. In each of the four slopes of the main section's roof is a hipped roof dormer with double six over two pane sash windows. The entire wall surface of the building is sheathed with german siding.

Windows are long with broad flat topped architraves and two over two pane sashes. There is no evidence of the windows having had shutters. While most windows have two over two pane sashes, two windows in an enclosed porch at the back of the house have four over four panes.

The main entrance is located in the center bay of the front elevation. It is trimmed similarly to the windows and has a four panel door beneath a single pane transom.

The porches which extend around the house are supported by turned posts and enclosed by a balustrade with turned balusters. The roof is sheathed with asphalt shingles and a central chimney of brick has several courses of decorative corbeling. A similar chimney is located at the rear of the house at the kitchen.

The interior of the house is divided into four rooms. The main entrance opens into the south room which is a parlor. It contained a fireplace along its interior wall. Recently the house was vandalized and the fireplace woodwork and trim was removed. Several door architraves were also taken. Remaining woodwork is pine with original painted wood graining. One architrave still in place has symmetrical molding and decorated corner blocks. The mantel piece is said to have been quite elaborate with a mirror above the fire place and numerous moldings.

The main staircase is located in the north room. The hand rail, balustrade and trim have been removed. One notable feature in the stair room is a section of curved wall between a door frame and the back of the staircase.

Behind the parlor is a large bathroom which retains early 20th century fixtures.

Large rooms at the second story are lit by the dormer windows. Their woodwork and trim is similar to that at the first story level.

Behind the house is a stone out kitchen and spring house. It follows the form of the main house, being square with a hipped roof and a brick chimney with corbeling those on the house.

SEE CONTINUATION SHEET #1.
CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input checked="" type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The significance of the McLuckie farm lies in its architectural value as an early 20th century agricultural complex which remains in nearly original condition. It is also important for its contribution to the history of agriculture in Allegany County.

All of the buildings follow a planned form and appear to date from the early 20th century. A.T. McLuckie purchased the farm on October 3, 1911, from Thomas G. Pownall (103/574) and it is presumed that McLuckie had the present improvements built. Thomas Pownall had purchased the property from Matilda H. Bretz in September of 1911. (108/488). In all deeds between 1911 and the present, the property is referred to as "the Whalen or Bretz farm". More recently known as "Clover Hill", the farm was a prominent dairy establishment in the area.

The house is vaguely bungaloid in style although it cannot be clearly defined as a bungalow. It does reflect the popularity of this type of one and a half story house with a sweeping overhanging roof. The house is particularly significant because it retains most of its original interior finishings and evidence remains of those parts that have been removed recently.

Although some vandalism has occurred, the buildings appear to be in good condition and lend themselves to adaptive reuse for the park.

The entire complex with its outbuildings remains intact and it provides a picture of a complete early 20th century farmstead.

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Allegany County Land Records

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATAACREAGE OF NOMINATED PROPERTY Approximately 6 acres

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

11 FORM PREPARED BY

NAME / TITLE

ORGANIZATION

Preservation Associates

DATE

STREET & NUMBER

P. O. Box 202

TELEPHONE

CITY OR TOWN

Sharpsburg

STATE

Maryland

21782

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

AL-III-C-068

CLOVER HILL FARM, McLUCKIE
ALLEGANY COUNTY
MARYLAND
(DESCRIPTION, continued)

On a bluff west of the house is a round cast concrete cistern. It is fed from a stream which is located on the opposite side of US Route 40. The structure has a polygonal roof of wood sheathed with composition paper.

Northeast of the house are agricultural buildings and a barn. The barn is a large frame structure with decorative round ventilators cut in its walls. It also has three gable roofed ventilating towers in the roof. A modern milking barn has been added to one end. Two silos stand against the east end wall. One is of wood construction and the other is tile. A series of windows are present in a work area between the tops of the silos and their roofs. The barn roof is of standing seam sheet metal.

Near the barn is a frame wagon shed with a hipped roof. Other frame agricultural buildings are present including a chicken house and a milk house. Except for the barn all of the buildings in the complex have hipped roofs and appear to have been built following the pattern of the house. With the exception of the modern milking barn, all of the buildings appear to be contemporary and to have been built during the first quarter of the 20th century.

ADDENDA

In 1984 the Department of Natural Resources contracted with Joe Getty to conduct a follow-up survey of selected historic properties on DNR lands. DNR funded the field survey and photography but did not prepare finished copy. The attached photocopy pages were forwarded to the Maryland Historical Trust to supplement existing files. All original material and photographs remain in the possession of the Department of Natural Resources under the supervision of Ross Kimmel (x3771).

To the rear of the farmhouse is a stone dairy and washhouse. It is located ten feet behind the rear wall of the farmhouse. It is constructed of quarry stone with one-foot, eight-inch thick walls. The structure has a hipped roof with a ventilator cupola. The structure has a two-room plan with a stone partition wall running down the center. There is no access between the two rooms. The eastern room has a brick flue that would have served an early twentieth century cast-iron stove. The western room has a concrete trough used for a dairy. The structure had a double entrance on the front and windows into the east room. The west room which contains the dairy had smaller windows for ventilation purposes. The dairy has the trough located on its west wall, constructed ^{of} with stone covered with concrete. The trough opening is about three-feet ^{wide} and runs the full-length of the stone structure. The ceiling of both sections ^{is} tongue and groove board painted white. The roof structure consists of eight rafters from each side of the building rising to the peak of the roof with braces at the middle on each side.

The dairy and other farm buildings on the property received water from a poured-concrete cistern. The cistern was located on a bluff west of the house. It was fed from a stream located on the opposite side of U.S. Route 40. The cistern has a polygonal roof of wood sheathed in asphalt shingles.

The bank barn at Clover Hill is a large ^{frame} structure with a stone foundation. The ^{facade is} ~~structure~~ located on the south facade and is enclosed in wood siding with numerous windows and door openings.

Draft--Clover Hill Farm
Addendum to 1979 Survey Form

The main floor of the barn contained ^{rectangular} ventilator windows ^{with} ~~above~~ ^{located above them} ~~which were~~ circular decorative ventilators with a floral motif. The barn has a gable roof covered in sheet metal. The gable ends have similar ~~ventilator~~ windows with ventilator circles, with a large ventilator circle located in the gable. On the peak of the roof are three ventilator cupolas with gable rooves. At the east end of the barn is a pair of silos. A large one constructed of tile has a collapsed roof. The smaller one is a stave silo.

In the complex of farm buildings is a double-bay wagon shed/corncrib. The structure has a hipped roof covered in asphalt shingles. The north and south facades contained double wagon bays with a corncrib at the east and west ends of the structure. It is a frame structure that is covered in boards on the east and west ends set slightly apart for ventilation of the corncrib. The area on the north and south is covered in German siding.

Between the wagon shed-corncrib and the farmhouse is a frame garage. The garage has a hipped roof with a ventilator cupola that has a hipped roof. It is a frame structure covered in German siding. The garage door opening is double doors on the east facade. The other facades have two windows each.

Southwest of the barn is a small frame structure that served as a toolshed. It has a hipped roof and is covered in wood siding. It is four-bays by one-bay with six-over-six sash windows. This one-story structure appears to have served a number of purposes in the farm complex.

Draft--Clover Hill Farm
Addendum to 1979 Survey Farm

The total complex provides a view of construction and uses for early twentieth century farm buildings in this section of Washington County.

Maryland Historical Trust

State Historic Sites Inventory Form

1. Name (indicate preferred name)

historic

and/or common

Clover Hill Farm

2. Location

north side of
street & numberU. S. Route 40, .5 mile west of Breakneck Valley Rd. not for publication

city, town

Cumberland vicinity of

congressional district

Sixth

state

Maryland

county

Allegany

3. Classification

Category	Ownership	Status	Present Use
<input type="checkbox"/> district	<input checked="" type="checkbox"/> public	<input type="checkbox"/> occupied	<input type="checkbox"/> agriculture
<input checked="" type="checkbox"/> building(s)	<input type="checkbox"/> private	<input checked="" type="checkbox"/> unoccupied	<input type="checkbox"/> commercial
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input checked="" type="checkbox"/> yes: restricted	<input type="checkbox"/> government
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial
	<input type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military
			<input checked="" type="checkbox"/> other: <u>none</u>

4. Owner of Property (give names and mailing addresses of all owners)

name

Department of Natural Resources

street & number

Turner State Office Bldgtelephone no.: 269-3771

city, town

Annapolisstate and zip code MD 21401

5. Location of Legal Description

courthouse, registry of deeds, etc.

Allegany Co. Courthouseliber 366

street & number

Washington Streetfolio 139

city, town

Cumberlandstate MD

6. Representation in Existing Historical Surveys

title

DNR Survey

date

February 1974 federal state county local

depository for survey records

Dept. of Natural Resources

city, town

Annapolisstate MD

7. Description

Survey No. AL-III-C-068

Condition

excellent
 good
 fair

deteriorated
 ruins
 unexposed

Check one

unaltered
 altered

Check one

original site
 moved date of move _____

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

APPENDUM to 1979 SURVEY FORM

8. Significance

Survey No. 42-III-C-228

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates

Builder/Architect

check: Applicable Criteria: A B C D
and/or

Applicable Exception: A B C D E F G



Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.


See 1979 Survey Form.

AK-III-C-068 Clover Hill Farm

top - South Facade
center - South + East Facades
bottom - East Facade




AL-III-C-068 Clover Hill Farm
top - North & West Facades
center - Dairy West and South Facades
bottom - " East and North Facades





L-III-C-068 Lower Hill Farm

top - Cast-Concrete Cistern
center - Wagon Shed / Cow Cub
bottom - Garage



AL-III-C-068 - Clover Hill Farm
 top - Bank Barn South & East Facades
 center - " " North & West Facades
 bottom - " " South & West Facades



INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

AND/OR COMMON

Cloverhill Farm

2 LOCATION

STREET & NUMBER

Rocky Gap State Park

CITY, TOWN

Cumberland

VICINITY OF

CONGRESSIONAL DISTRICT

STATE

Maryland

COUNTY

Allegany

3 CLASSIFICATION

CATEGORY	OWNERSHIP	STATUS	PRESENT USE	
<input type="checkbox"/> DISTRICT	<input type="checkbox"/> PUBLIC	<input type="checkbox"/> OCCUPIED	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> MUSEUM
<input checked="" type="checkbox"/> BUILDING(S)	<input type="checkbox"/> PRIVATE	<input type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL	<input type="checkbox"/> PARK
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> EDUCATIONAL	<input type="checkbox"/> PRIVATE RESIDENCE
<input type="checkbox"/> SITE	PUBLIC ACQUISITION	ACCESSIBLE	<input type="checkbox"/> ENTERTAINMENT	<input type="checkbox"/> RELIGIOUS
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input type="checkbox"/> YES: RESTRICTED	<input type="checkbox"/> GOVERNMENT	<input type="checkbox"/> SCIENTIFIC
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> INDUSTRIAL	<input type="checkbox"/> TRANSPORTATION
		<input type="checkbox"/> NO	<input type="checkbox"/> MILITARY	<input type="checkbox"/> OTHER:

4 OWNER OF PROPERTY

NAME

State of Maryland (DNR)

Telephone #:

STREET & NUMBER

CITY, TOWN

VICINITY OF

STATE, zip code

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,
REGISTRY OF DEEDS, ETC.

Liber #:

Folio #:

STREET & NUMBER

CITY, TOWN

STATE

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

FEDERAL STATE COUNTY LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

AC-III-C-068

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input checked="" type="checkbox"/> UNALTERED	<input type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED DATE _____
<input checked="" type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

CLOVERHILL FARM: An abandoned farm, now part of Rocky Gap State Park. Several buildings, including the main house and barn are still standing. The barn is a large frame structure with gable roof, ventilator panels cut in the gable ends, and three small gabled monitor ventilators on the ridge. The house (dating from the late 19th century or early 20th century) is unusual for the area, a one story frame house, nearly square in plan, with a hipped roof with a very short ridge perpendicular to the facade axis. The building walls on the south (entrance) and west are set well back of the eaves, providing deep porches under the shelter of the main roof. There are hipped dormers on all four slopes of the roof, also set back from the eaves but with their sills at about eave level, creating large cutout spaces in the roof between the former wall and the eaves. The effect is overall one of a play of solids and voids of simple forms which is in contrast to local vernacular and high-style conventions, and presents a strikingly "modern" image. Behind (north of) the house is a stone dairy or smoke house, square in plan, with a pyramidal roof surmounted by a louver-ventilator cupola.

Pyramidal roof with three visible dormers (hipped gable) central chimney in peak, wraparound veranda with posts, roof extends out over porch, four bays, 1 1/2 stories, German siding.

Smokehouse—square with pyramid roof with louvered ventilator in peak. Stone (rock faced ashlar) walls, chimney corbelled brick, tar paper roof.

Barn—large barn with three square gabled ventilators. Rectangular with gabled roof, several cut Penn Patch style vents. Approximately early 20th century.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

PERIOD

AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW

- | | | | | |
|---|--|---|---|--|
| <input type="checkbox"/> PREHISTORIC | <input type="checkbox"/> ARCHEOLOGY-PREHISTORIC | <input type="checkbox"/> COMMUNITY PLANNING | <input type="checkbox"/> LANDSCAPE ARCHITECTURE | <input type="checkbox"/> RELIGION |
| <input type="checkbox"/> 1400-1499 | <input type="checkbox"/> ARCHEOLOGY-HISTORIC | <input type="checkbox"/> CONSERVATION | <input type="checkbox"/> LAW | <input type="checkbox"/> SCIENCE |
| <input type="checkbox"/> 1500-1599 | <input type="checkbox"/> AGRICULTURE | <input type="checkbox"/> ECONOMICS | <input type="checkbox"/> LITERATURE | <input type="checkbox"/> SCULPTURE |
| <input type="checkbox"/> 1600-1699 | <input checked="" type="checkbox"/> ARCHITECTURE | <input type="checkbox"/> EDUCATION | <input type="checkbox"/> MILITARY | <input type="checkbox"/> SOCIAL/HUMANITARIAN |
| <input type="checkbox"/> 1700-1799 | <input type="checkbox"/> ART | <input type="checkbox"/> ENGINEERING | <input type="checkbox"/> MUSIC | <input type="checkbox"/> THEATER |
| <input checked="" type="checkbox"/> 1800-1899 | <input type="checkbox"/> COMMERCE | <input type="checkbox"/> EXPLORATION/SETTLEMENT | <input type="checkbox"/> PHILOSOPHY | <input type="checkbox"/> TRANSPORTATION |
| <input checked="" type="checkbox"/> 1900- | <input type="checkbox"/> COMMUNICATIONS | <input type="checkbox"/> INDUSTRY | <input type="checkbox"/> POLITICS/GOVERNMENT | <input type="checkbox"/> OTHER (SPECIFY) |
| | | <input type="checkbox"/> INVENTION | | |

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE COUNTY

STATE COUNTY

11 FORM PREPARED BY

NAME / TITLE

Mr. John Hnedak

ORGANIZATION

Maryland Historical Trust

DATE

5/78

STREET & NUMBER

21 State Circle

TELEPHONE

269-2438

CITY OR TOWN

Annapolis, MD


STATE

Maryland 21401

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438



PENNSYLVANIA 186
MARYLAND 163

BEDFORD CO
ALLEGANY CO

DNR-11 EVITTS HOME SITE
AL-III-C-143

DNR-29 LESTER RAINE'S
BARN AL-III-C-146

DNR-9 LYNN CABIN AL-III-C-155

DNR-7 PLEASANT VALLEY
SCHOOL HOUSE AL-III-C-142

DNR-13-21 CLOVER
HILL FARM AL-III-C-148

EVITTS
CREEK
QUAD

4399

42'30"

FLINTSTONE 3.3 MI.
HAGERSTOWN 5.6 MI.

4396

(FLINTSTONE)
5263 11 NE

4395



A-5

Rocky Gap St PK

"Clover Hill Farm" - Barn

S.W. view

Aug. 1978

DNR Survey

AL-111-C-068

Paula Stoner

Preservation Associates



A-5

Rocky Gap St. Paul

"Clover Hill Farm" - Barn

E view

Aug. 1973

DNR Survey

AZ-III-C-068

Paula Stoner
Preservation Association



A-5

Rocky Gap St. Ark

"Closest this Farm" barn

N view

Aug. 1973

DNR Survey

AZ-111-C-068

Paula Stoner
Preservation Association



A-5

Rocky Gap St. Park

"Clover Hill Farm" - house

S. view

August, 1975

DNR Survey

12-111-C-068

Paula Stoner
Reservation Associates



A-5

Rocky Gap St. PK

"Clover Hill Farm" - house

S.E. View

August, 1978

DNR SURVEY

AZ-111-C-068

Paula Stoner
Preservation Associates



A-5

Rocky Gap St Park

"Clover Hill Farm" house

2nd floor N Room

Aug. 1973

DNR Survey

AZ-111-C-06F

Paula Stoner
Preservation Associates



A-5

Rocky Gap St. PK

"Clover Hill Farm"

1st floor W. Room - bath

Aug. 1978

DNR Survey

AZ-111-C-068

Paula Stoner
Preservation Association



A-5

Rocky Gap St. Park

"Clover Hill Farm"

1st floor S. room

Aug. 1970

12-111-C-068

DNR Survey

Paula Stoner

Preservation Association



A-5

Rocky Gap St. Park

"Clover Hill Farm" - house

1st Story, N. Room

August 1978

DNR Survey

AZ-111-C-068

Paula Stoner
Preservation Association



A.S

Rocky Gap St. R.

"Clover Hill Farm", barn

N.E. View

Aug. 1973

DNR Survey

AZ-III-C-008

Paula Stoner
Preservation Associates



A-5

Rocky Gap St. PK

"Clow's Hill Farm" - outbuildings

N. View

August, 1978

AZ-III-C-068
DNR Survey

Paula Stoner
Preservation Associates



A-5

Rocky Gap, N. R.

Cistern - SW view

Aug. 1978

"Clover Hill Farm"

DNR SURVEY

AL-111-C-068

Paula Stoner
Preservation Associates



A-5-

Rocky Gap St. Park

"Clover Hill Farm" House

W. View

Aug., 1913

AL-III-C-068

DNR Survey

Paula Stone
Recreation Association