

Maryland Historical Trust State Historic Sites Inventory Form

1. Name (indicate preferred name)

historic

and/or common Buskirk Log Farmhouse and Barn

2. Location

street & number Water Station Run Road, .2 mile north, and approx. 1 3/4 ~~not for publication~~

miles east of Lonaconing

city, town Lonaconing vicinity of congressional district 6th

state Maryland county Allegany

3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input checked="" type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input type="checkbox"/> private residence
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input type="checkbox"/> not applicable	<input checked="" type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

4. Owner of Property (give names and mailing addresses of all owners)

name Pond Hill Association c/o Lee Barnett

street & number 234 Baltimore Street telephone no.: 301-722-2748

city, town Cumberland Maryland state and zip code 21502

5. Location of Legal Description

courthouse, registry of deeds, etc. Allegany County Courthouse liber

street & number 30 Washington Street folio

city, town Cumberland state Maryland 21502

6. Representation in Existing Historical Surveys

title

date federal state county local

depository for survey records

city, town state

7. Description

Survey No. AL-VI-B-231

Condition		Check one	Check one
<input type="checkbox"/> excellent	<input checked="" type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input checked="" type="checkbox"/> original site
<input type="checkbox"/> good	<input type="checkbox"/> ruins	<input checked="" type="checkbox"/> altered	<input type="checkbox"/> moved date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed		

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The Buskirk Log Farmhouse, a 2 story, 3 bay by 1 bay half dove-tail notched log dwelling, is situated on the western slope of Dans Mountain just north of Water Station Run Road. This abandoned dwelling appears to be the shell of an old log house that has been altered, including the addition of a new gable roof. The log walls are covered with asphalt siding, but in places the logs are exposed revealing plaster daubing. The house rests on a stone foundation.

The facade faces east and has a one story shed roof porch covering a double entrance. A 6/6 sash window pierces the facade wall at the first story between the two entrances. The window is situated closest to the southernmost entrance. The remaining windows are 6/6 sash except for two 6/3 sash windows at the second story facade and a 4-pane window at the north gable end peak.

The interior is consists of a hall parlor plan. The northernmost entrance opens into the larger hall. A winder staircase is located at the center of the partition wall. This room has a rear entrance. Behind the staircase is a door opening into the parlor or inner room.

A single pen, v-notched log barn with a frame shed addition on the south elevation lies in ruins just southeast of the house. The west elevation of the log section is supported by flat cut stone pillars. There are 3 frame outbuildings, also in ruins, associated with this site. A dry stone wall and drainage ditch descend the hillside north of the farm.

8. Significance

Survey No. AL-VI-B-231

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400–1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500–1599	<input checked="" type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600–1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700–1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input checked="" type="checkbox"/> 1800–1899	<input type="checkbox"/> commerce	<input checked="" type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input checked="" type="checkbox"/> 1900–	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates

Builder/Architect

check: Applicable Criteria: A B C D
and/or

Applicable Exception: A B C D E F G

Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.

The Buskirk Log Farmhouse has been greatly altered. Its significance therefore lies in the appearance of the basic structure, rather than original details. The farm is significant for retaining a log barn, as well as the log farmhouse. Both structures are severely deteriorated.

The farm is identified on an 1836 Allegany County map as the property of a settler named Buskirk.

The farmhouse displays locally rare half-dovetailed corner notching.

A better example of a log farm complex is the Thomas Wright Farm (AL-VI-B-036).



A1-VI-B-231

Buskirk Log Farmhouse


Allegany County

David Dorsey 10/80

Southern Elev.



AL-VI-B-231
Buskirk Log Farmhouse
Allegany County
David Dorsey 10/80
Eastern elev.



AL-VI-B-231
Buskirk Log Farmhouse
Allegany County
David Dorsey 10/80
Barn West elev.



AL-VI-B-231

Buskirk Log Farm House

Allegheny Co., MD

David A. Dorsey 2/81

Northern elev.



AL-VI-B-231

Buskirk Log Farm House

Allegheny Co., MD

David A. Dorsey 2/81

Notching: West elev.



AL-VI-B-231

Buskirk Log Farm House

Allegany Co., MD

David A. Dorsey .2/81

~~Barn~~ Eastern Facade

Fig # 21

Please
return
to
Survey
file



AL-VI-B-231

Buskirk Log Farm House

Allegany Co., MD

David A. Dorsey 2/81

Western Elevation



AL-VI-B-231

POSKIRK LOG FARM HOUSE AND BARN

2/1991 - David Dorsey



AL-VI-B-231

BUSKIRK LOG FARM HOUSE AND BARU

2/1981 - David Dorsey



AL-VI-B-231

Buskirk Log Farm House

Allegheny Co., MD

David A. Dorsey 2/81

Barn W elev.