

Start Here

Scan One Time Only

And

Copy for Multiple Numbers

AA-461

AND

AA-461A

recent (10/67) sale.

0204612204

Form 10-445 (5/62)

1. STATE Annapolis, Maryland COUNTY TOWN STREET NO. 110-112-114 Duke of Gloucester	HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY
ORIGINAL OWNER John Ridout ORIGINAL USE residences PRESENT OWNER Keester/Slayton/ ^{MANN} Benson PRESENT USE residence WALL CONSTRUCTION brick NO. OF STORIES three	2. NAME Ridout Row Houses DATE OR PERIOD 1774 STYLE Georgian ARCHITECT BUILDER
	3. FOR LIBRARY OF CONGRESS USE


4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION OPEN TO PUBLIC no

110, 112, 114 Duke of Gloucester Street is an excellent example of the Georgian London town house transplanted in America. A straight forward, academic building in 3 parts with a pediment above the central portion, which is a slightly projecting pavillion. Building is symmetrical (note the 4 massive chimneys - superb!) except for present central doorway (probably changed). 110 and 114 have Palladian doorways with pilasters, pediments and semi-circular fanlights. All windows have splayed brick lintels and all are 6/6 except central 2nd (12/8) and 3rd (8/8) storeys. There are belt courses between floors and a simple wood cornice; 114 has granite steps, 110's are marble. Bond is flemish. Important architecturally - would be outstanding even in England. Perhaps earliest row houses in Annapolis.

SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE

5. PHYSICAL CONDITION OF STRUCTURE

good



6. LOCATION MAP (Plan Optional)

7. PHOTOGRAPH

8. PUBLISHED SOURCES (Author, Title, Pages)
INTERVIEWS, RECORDS, PHOTOS, ETC.



Delos Smith,
Historic Annapolis, Inc.
Orlando Ridout IV

connections: H.A. Inc 10/67


9. NAME, ADDRESS AND TITLE OF RECORDER

William D. Morgan
Columbia University
New York City

DATE OF RECORD August 7, 1967



AA 46
ANNAPOLIS HIST. DIST.





AA-461

PHOTOGRAPH BY
WILLIAM D. MORGAN

110-114 Duke Gt. St.
VII/7/67

714

MARYLAND HISTORICAL TRUST
 21 STATE CIRCLE
 SHAW HOUSE
 ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET
 Individual Structure Survey Form

SURVEY NUMBER: <u>AA 461</u>
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP:
PRESENT FORMAL NAME: <u>Ridout Row</u>
ORIGINAL FORMAL NAME: <u>Ridout Row</u>
PRESENT USE: <u>residence</u>
ORIGINAL USE:
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR: <u>John Ridout</u>
PHYSICAL CONDITION OF STRUCTURE: Excellent () Good (x) Fair () Poor: ()
THEME:
STYLE: <u>Georgian</u>
DATE BUILT: <u>1774</u>

COUNTY: <u>Anne Arundel</u>
TOWN: <u>Annapolis</u>
LOCATION: <u>110 Duke of Gloucester</u>
COMMON NAME: <u>Ridout Row</u>
FUNCTIONAL TYPE: <u>RES Map33 Par 117</u>
OWNER: <u>Richard Tyler</u>
ADDRESS: <u>110 Duke of Gloucester</u> <u>Annapolis, MD 21401</u>
ACCESSIBILITY TO PUBLIC: Yes (x) No () ^{HABS} Restricted ()
LEVEL OF SIGNIFICANCE: Local () State () National (x) <input checked="" type="radio"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone () Brick (x) Concrete () Concrete Block ()
- Wall Structure
 - Wood Frame: Post and Beam () Balloon ()
 - Wood Bearing Masonry: Brick (x) Stone () Concrete () Concrete Block ()
 - Iron () D. Steel () E. Other:
- Wall Covering: Clapboard () Board and Batten () Wood Shingle () Shiplap ()
Novelty () Stucco () Sheet Metal () Aluminum () Asphalt Shingle ()
Brick Veneer (x) Stone Veneer () Asbestos Shingle ()
Bonding Pattern: Flemish Other:
- Roof Structure
 - Truss: Wood (x) Iron () Steel () Concrete ()
 - Other:
- Roof Covering: Slate () Wood Shingle () Asphalt Shingle (x) Sheet Metal ()
Built Up () Rolled () Tile () Other:
- Engineering Structure:
- Other:

Appendages: Porches () Towers () Cupolas () Dormers () Chimneys (x) Sheds () Ells (x)
Wings (x) Other: Additions at both ends and rear

Roof Style: Gable () Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead ()
Saw Tooth () With Monitor () With Bellcast () With Parapet () With False Front ()
Other: Gable with pediment

Number of Stories: 3

Number of Bays: 9 x 3

Approximate Dimensions: 50 x 105

Entrance Location: Left

THREAT TO STRUCTURE: No Threat (x) Zoning () Roads () Development () Deterioration () Alteration () Other:	LOCAL ATTITUDES: Positive () Negative () Mixed () Other:
--	---

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

AA-461

Part of Ridout Row, with simple wood cornice, end wall chimney, molded water table, brick belt courses at upper floors, pedimented entrance with round fan, splayed brick arches at windows; marbles stairs.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

One-third of the architecturally most important row in Annapolis, part of the row developed by John Ridout for the use of his children; important as types and critical to streetscape.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

Open Lane() Woodland() Scattered Buildings()
 Moderately Built Up() Densely-Built Up(✓)
 Residential() Commercial()
 Agricultural() Industrial()
 Roadside Strip Development()
 Other:

RECORDED BY:

Russell Wright

ORGANIZATION:

Historic Annapolis, Inc

DATE RECORDED:

Aug. 1983



110 Duke of Gl AA 461
Annapolis, Anne Arundel County
Russell Wright July, 1982
Maryland Historical Trust,
Annapolis, Maryland
SW Elevation/camera facing NE

MARYLAND HISTORICAL TRUST
 21 STATE CIRCLE
 SHAW HOUSE
 ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET
 Individual Structure Survey Form

SURVEY NUMBER:	AA 461
NEGATIVE FILE NUMBER:	
UTM REFERENCES:	Zone/Easting/Northing
U.S.G.S. QUAD. MAP:	
PRESENT FORMAL NAME:	Ridout Row
ORIGINAL FORMAL NAME:	Ridout Row
PRESENT USE:	residence
ORIGINAL USE:	
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	John Ridout
PHYSICAL CONDITION OF STRUCTURE:	
Excellent ()	Good (X)
Fair ()	Poor: ()
THEME:	
STYLE:	Georgian
DATE BUILT:	1774

COUNTY:	Anne Arundel
TOWN:	Annapolis
LOCATION:	112 Duke of Gloucester
COMMON NAME:	Ridout Row
FUNCTIONAL TYPE:	RES Map 33 Par 118
OWNER:	Morgan Slayton
ADDRESS:	112 Duke of Gloucester Annapolis, MD 21401
ACCESSIBILITY TO PUBLIC:	HABS
Yes (X) No () Restricted ()	
LEVEL OF SIGNIFICANCE:	
Local () State () National (X) <input type="radio"/>	

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone () Brick (X) Concrete () Concrete Block ()
- Wall Structure
 - Wood Frame: Post and Beam () Balloon ()
 - Wood Bearing Masonry: Brick (X) Stone () Concrete () Concrete Block ()
 - Iron () D. Steel () E. Other:
- Wall Covering: Clapboard () Board and Batten () Wood Shingle () Shiplap () Novelty () Stucco () Sheet Metal () Aluminum () Asphalt Shingle () Brick Veneer (X) Stone Veneer () Asbestos Shingle ()
 Bonding Pattern: Flemish Other:
- Roof Structure
 - Truss: Wood (X) Iron () Steel () Concrete ()
 - Other:
- Roof Covering: Slate () Wood Shingle () Asphalt Shingle (X) Sheet Metal ()
 Built Up () Rolled () Tile () Other:
- Engineering Structure:
- Other:

Appendages: Porches () Towers () Cupolas () Dormers () Chimneys (X) Sheds () Ells (X)
 Wings (X) Other: Additions at both ends and rear

Roof Style: Gable () Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead ()
 Saw Tooth () With Monitor () With Bellcast () With Parapet () With False Front ()
 Other:

Number of Stories: 3
 Number of Bays: 9 x 3
 Approximate Dimensions: 50 x 106

Entrance Location: Right

THREAT TO STRUCTURE: No Threat (X) Zoning () Roads () Development () Deterioration () Alteration () Other:	LOCAL ATTITUDES: Positive () Negative () Mixed () Other:
--	---

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

AA-461

Central part of three row unit, projecting slightly from the end units and has a full pediment with round window above continuous wood cornice, the profile of which is used at the rakes; molded water-table, brick belt courses, splayed brick arches repeated at all three units; entrance is later, probably early 19thC.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

One third of the architecturally most important row in Annapolis, part of the row developed by John Ridout for the use of his children; important as types and critical to streetscape.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

Open Lane() Woodland() Scattered Buildings()
 Moderately Built Up() Densely-Built Up(✓)
 Residential() Commercial()
 Agricultural() Industrial()
 Roadside Strip Development()
 Other:

RECORDED BY:

Russell Wright

ORGANIZATION:

Historic Annapolis, Inc

DATE RECORDED:

Aug. 1983



AA 461

112 Duke of Gl
Annapolis, Anne Arundel County

Russell Wright July, 1982

Maryland Historical Trust,

Annapolis, Maryland

SW Elevation/camera facing NE



112

Street elevation

Door detail

112 Duke of Gloucester

Annapolis

AA-461

1996



112 Duke of Gloucester
Annapolis

AA-461

Street elevation

1996



AA-461

112 Duke of Gloucester

Annapolis

Early soapstone heating vents,
First floor parlor and stair passage

1996



AA-461

112 Duke of Gloucester

Annapolis

First floor dining room on garden side

1996



AA-461

112 Duke of Gloucester

Annapolis

First floor, small parlor on street side

1996



AA-461

112 Duke of Gloucester

Annapolis

3rd floor bed chamber

1996

Slayton House



AA-461

Slayton House

112 Duke of Gloucester

Annapolis

View of attic and roof framing, facing northwest

1996



AA-461

112 Duke of Gloucester

Annapolis

Slayton House

Stair passage, with early intercom

1996



AA-461

Slayton House

112 Duke of Gloucester

Annapolis

Cellar: Service rooms under porch, facing northeast

1996



AA-461

Slayton House

112 Duke of Gloucester
Annapolis

Attic and enclosure around skylight and stair, facing northeast

1996



AA-461

Slayton House

112 Duke of Gloucester

Annapolis

Detail of roof framing, northeast corner of attic

1996

MARYLAND HISTORICAL TRUST
 21 STATE CIRCLE
 SHAW HOUSE
 ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET
 Individual Structure Survey Form

SURVEY NUMBER: <u>AA 461</u>
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP:
PRESENT FORMAL NAME: Ridout Row
ORIGINAL FORMAL NAME: RIDout Row
PRESENT USE: residence
ORIGINAL USE:
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR: John Ridout
PHYSICAL CONDITION OF STRUCTURE: Excellent () Good (X) Fair () Poor: ()
THEME:
STYLE: Georgian
DATE BUILT: 1774

COUNTY: Anne Arundel
TOWN: Annapolis
LOCATION: 114 Duke of Gloucester
COMMON NAME: Ridout Row
FUNCTIONAL TYPE: RES Map 33Par 119
OWNER: E. Wood & M. Keester ADDRESS: 114 Duke of Gloucester Annapolis, MD 21401
ACCESSIBILITY TO PUBLIC: Yes (X) No () Restricted ()
LEVEL OF SIGNIFICANCE: HABS Local () State () National (✓) ()

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone () Brick (X) Concrete () Concrete Block ()
- Wall Structure
 - Wood Frame: Post and Beam () Balloon ()
 - Wood Bearing Masonry: Brick (X) Stone () Concrete () Concrete Block ()
 - Iron () D. Steel () E. Other:
- Wall Covering: Clapboard () Board and Batten () Wood Shingle () Shiplap ()
 Novelty () Stucco () Sheet Metal () Aluminum () Asphalt Shingle ()
 Brick Veneer (X) Stone Veneer () Asbestos Shingle ()
 Bonding Pattern: Flemish Other:
- Roof Structure
 - Truss: Wood (X) Iron () Steel () Concrete ()
 - Other:
- Roof Covering: Slate () Wood Shingle () Asphalt Shingle (X) Sheet Metal ()
 Built Up () Rolled () Tile () Other:
- Engineering Structure:
- Other:

Appendages: Porches () Towers () Cupolas () Dormers () Chimneys (X) Sheds () Ells (X)
 Wings (X) Other: Additions at both ends and rear

Roof Style: Gable () Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead ()
 Saw Tooth () With Monitor () With Bellcast () With Parapet () With False Front ()
 Other: Gable with pediment

Number of Stories: 3

Number of Bays: 9 x 3

Approximate Dimensions: 50 x 105

Entrance Location: Right

THREAT TO STRUCTURE: No Threat (X) Zoning () Roads () Development () Deterioration () Alteration () Other:	LOCAL ATTITUDES: Positive () Negative () Mixed () Other:
--	---

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

AA-461

Part of Ridout Row, with simple wood cornice, end wall chimney, molded watertable, brick belt courses at upper floors, pedimented entrance with round fan, splayed brick arches at windows; marble stairs.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

One-third of the architecturally most important row in Annapolis, part of the row developed by John Ridout for the use of his children; important as types and critical to streetscape.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

Open Lane() Woodland() Scattered Buildings()
 Moderately Built Up() Densely-Built Up(✓)
 Residential() Commercial()
 Agricultural() Industrial()
 Roadside Strip Development()
 Other:

RECORDED BY:

Russell Wright

ORGANIZATION:

Historic Annapolis, Inc

DATE RECORDED:

Aug. 1983



114 Duke of Gl AA 461
Annapolis, Anne Arundel County
Russell Wright July, 1982
Maryland Historical Trust,
Annapolis, Maryland
SW Elevation/camera facing NE

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC
Ridout Tenement House Outbuilding
 AND/OR COMMON

2 LOCATION

STREET & NUMBER
114 Duke of Gloucester Street
 CITY, TOWN
Annapolis VICINITY OF
 CONGRESSIONAL DISTRICT
4th
 STATE
Maryland COUNTY
Anne Arundel

3 CLASSIFICATION

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input type="checkbox"/> PUBLIC	<input type="checkbox"/> OCCUPIED	<input type="checkbox"/> AGRICULTURE <input type="checkbox"/> MUSEUM
<input checked="" type="checkbox"/> BUILDING(S)	<input checked="" type="checkbox"/> PRIVATE	<input checked="" type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL <input type="checkbox"/> PARK
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> PRIVATE RESIDENCE
<input type="checkbox"/> SITE	PUBLIC ACQUISITION	ACCESSIBLE	<input type="checkbox"/> ENTERTAINMENT <input type="checkbox"/> RELIGIOUS
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input checked="" type="checkbox"/> YES: RESTRICTED	<input type="checkbox"/> GOVERNMENT <input type="checkbox"/> SCIENTIFIC
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> INDUSTRIAL <input type="checkbox"/> TRANSPORTATION
		<input type="checkbox"/> NO	<input type="checkbox"/> MILITARY <input checked="" type="checkbox"/> OTHER: vacant

4 OWNER OF PROPERTY

NAME
Dr. Richard F. Tyler Telephone #:
 STREET & NUMBER
114 Duke of Gloucester
 CITY, TOWN
Annapolis VICINITY OF
 STATE, zip code
Maryland

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE, REGISTRY OF DEEDS, ETC
Anne Arundel County Court House Liber #:
 Folio #:
 STREET & NUMBER
South Street and Church Circle
 CITY, TOWN
Annapolis STATE
Maryland 21401

6 REPRESENTATION IN EXISTING SURVEYS

TITLE
 DATE
 DEPOSITORY FOR SURVEY RECORDS
 CITY, TOWN
 STATE
 FEDERAL STATE COUNTY LOCAL

7 DESCRIPTION

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input checked="" type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED DATE _____
<input checked="" type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This small frame outbuilding is located in the garden of 114 Duke of Gloucester Street, the northwesternmost of the three brick townhouses known as the Ridout Tenement Houses. The overall form and the framing system suggest the building was originally constructed to serve as a meat house. The absence of smoke blackening on the interior indicates that it was never used to smoke meat but served as a storehouse and possibly for sugar curing.

The building rests on a high brick foundation. It is square in form, with a pyramidal roof. The door is centered on the southeast wall, but has been altered in position. The original door was framed in above the sill, but the sill has been cut through, the foundation altered, and the door dropped to ground level. A simple lattice-work grill now fills the upper portion of the original door opening. Window openings have also been cut in to the left of the door and across the southwest wall. These are fitted with six-light sash mounted as casement windows. One sash has crude initials carved in the glass, dated in the 1880's. The sash

CONTINUE ON SEPARATE SHEET IF NECESSARY

CONTINUATION SHEET

7.1 DESCRIPTION

is mounted sideways, indicating that it has been reused from a previous location. The exterior of the building is covered with random-width horizontal boards set flush with a lapped joint. They are not beaded, and are secured with machine nails. The plain cornerboards and siding appear to be original. The roof is covered with wood shingles and was probably surmounted by a simple carved finial. The eaves are framed with light jack rafters scabbed on to the top plate, and are left exposed.

The interior of the building is quite plain. The framing is fully exposed and has never been sheathed or plastered. There is no evidence of the building ever having a wood floor, although it is possible one has been removed. The walls are framed with machine sawn timber in the "close-stud" framing pattern typical of meat houses. The corner posts are let into heavy sills with a mortise-and-tenon joint and are reinforced with two down-braces at each corner. The top plates are laid flat and are also secured with a pegged mortise-and-tenon joint. The studs are set on 15 inch centers and are let into the sills and top plates with mortise-and-tenon joints. Where the

CONTINUATION SHEET

7.2 DESCRIPTION

down-braces interrupt the studs, the studs are mitred to fit and are nailed with machine-made nails. The ceiling joists are notched over the wall plates and do not support a secondary false plate. Instead, the roof rafters rest directly on the top plates, and the joists are mitred to fit in against the underside of the roof. There are eight primary rafters in the roof: one rising from each corner of the building and one from the center of each wall. These eight rafters are butted against a heavy octagonal block at the peak of the roof. Smaller jack rafters run from the plates up to the four corner rafters. The octagonal piece at the peak of the roof probably also served as the base for a carved pyramidal finial that projected up through the roof.

PERIOD		AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW				
<input type="checkbox"/> Prehistoric	<input type="checkbox"/> Archeology-Prehistoric	<input type="checkbox"/> Community Planning	<input type="checkbox"/> Landscape Architecture	<input type="checkbox"/> Religion		
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> Archeology-Historic	<input type="checkbox"/> Conservation	<input type="checkbox"/> Law	<input type="checkbox"/> Science		
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> Agriculture	<input type="checkbox"/> Economics	<input type="checkbox"/> Literature	<input type="checkbox"/> Sculpture		
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> Architecture	<input type="checkbox"/> Education	<input type="checkbox"/> Military	<input type="checkbox"/> Social/Humanitarian		
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> Art	<input type="checkbox"/> Engineering	<input type="checkbox"/> Music	<input type="checkbox"/> Theater		
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> Commerce	<input type="checkbox"/> Exploration/Settlement	<input type="checkbox"/> Philosophy	<input type="checkbox"/> Transportation		
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> Communications	<input type="checkbox"/> Industry	<input type="checkbox"/> Politics/Government	<input type="checkbox"/> Other (Specify)		
		<input type="checkbox"/> Invention				

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The small frame outbuilding at 114 Duke of Gloucester is a rare survival in downtown Annapolis. Few outbuildings have survived in the Historic District, and this example, constructed circa 1830-1850, is believed to be one of the earliest examples still standing. Although the southeast wall has suffered considerable damage from water and termites, the building remains largely intact and is scheduled for repair and rehabilitation.

Particular details of interest include the eave construction, in which the rafters rest directly on the top plate rather than a false plate, and the large octagonal block which serves as the structural keystone at the peak of the roof.

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

AA-461A

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE COUNTY

STATE COUNTY

11 FORM PREPARED BY

NAME / TITLE

Orlando Ridout V, Historic Sites Surveyor

ORGANIZATION

Maryland Historical Trust

DATE

11/12/80

STREET & NUMBER

21 State Circle

TELEPHONE

CITY OR TOWN

Annapolis

STATE

Maryland

Field Notebook Md-III; Recorded October 16, 1980.

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

End Here

Scan One Time Only
And
Copy for Multiple Numbers

AA-461

AND

AA-461A