

701 BALTIMORE AVE.

Among the collection of late 19th century and early 20th century houses which constitute the 600 and 700 blocks of Baltimore Ave. one can see several interesting front porches. One of them is on this two story frame and clapboard building.

Prior to air-conditioning and the "patio" the porch was a very important living area in Maryland homes for as much as six months of the year. On entering a home the porch was quite often the first covered area of a house which one encountered and it was common to find specific types of porch furniture. The furnishings of a porch might include not only chairs and benches, but plant stands and a bench-swing, all of which were much used during warmer weather. That this living area was oriented to the street and facilitated at least eye contact with passers by is an important factor in understanding life in a 19th century town.

The porch was also that area of the house where the Victorian preference for ornateness in design saw full bloom. The eaves of the porch were often bracketed to match those of the house and the columns were decorated with chamfers and scrollwork. A significant number of porches had ceilings which were painted sky-blue. Towson has its share of such porches and on # 701 Baltimore Ave. the importance of the porch is almost exaggerated due to the rather oversized scrollwork on the columns. Whether this effect is intentional or more indicative of having bought pre-cut materials is uncertain but there is little doubt that with such a porch this house is a great contribution to this Victorian streetscape.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

Church of the Immaculate Conception CCD Center

ANO/OR COMMON

2 LOCATION

STREET & NUMBER

701 Baltimore Avenue

CITY, TOWN

Towson

CONGRESSIONAL DISTRICT

___ VICINITY OF

STATE

Md.

COUNTY

3 CLASSIFICATION

CATEGORY

- DISTRICT
- BUILDING(S)
- STRUCTURE
- SITE
- OBJECT

OWNERSHIP

- PUBLIC
- PRIVATE
- BOTH

PUBLIC ACQUISITION

- IN PROCESS
- BEING CONSIDERED

STATUS

- OCCUPIED
- UNOCCUPIED
- WORK IN PROGRESS
- ACCESSIBLE
- YES: RESTRICTED
- YES: UNRESTRICTED
- NO

PRESENT USE

- AGRICULTURE
- MUSEUM
- COMMERCIAL
- PARK
- EDUCATIONAL
- PRIVATE RESIDENCE
- ENTERTAINMENT
- RELIGIOUS
- GOVERNMENT
- SCIENTIFIC
- INDUSTRIAL
- TRANSPORTATION
- MILITARY
- OTHER:

4 OWNER OF PROPERTY

NAME

Rev. Lawrence J. Shehan

Telephone #:

STREET & NUMBER

CITY, TOWN

___ VICINITY OF

STATE, zip code

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,
REGISTRY OF DEEDS, ETC.

Baltimore County Courthouse

Liber #: 4298

Folio #: 204

STREET & NUMBER

CITY, TOWN

STATE

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

___ FEDERAL ___ STATE ___ COUNTY ___ LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input type="checkbox"/> ORIGINAL SITE
<input checked="" type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input checked="" type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		DATE Spring, 1978

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

Located at 701 Baltimore Avenue is a two-story frame house with a gable-end roof . It consists of a main block, withn a corbelled chiminey located just south of center, and three telescoping projections to the east. The main block is three bays wide and one bay deep with the projection being two bays, one bay and one bay wide to the east.

The main or west facade is characterized by a porch running the full length of the first floor facade. The porch roof is supported by four square columns with chamfered edges and featuring a railing partially enclosed with shingles. The roof of both the structure and the porch are covered with asphalt shingles. The facade features a regular fenestration of three 4/4 sash windows an the second floor and two 4/4 sash windows on the first floor. Also noted are over-sized brackets at the roof between the porch and column. An entrance-way is surrounded by a doorframe with transom above.

The south facade features a visible stone foundation pierced by a single opening. Visible ia the gable-end of the main block Characterized by an arched, sash window centrally located in the gable-end. Also notamble is the largest block of a series of telescoping extensions to the east. This western-most extension consists of two storys and appears two bays wide with an entrance in the western bay consisting of a doorway with transom. The first story is covered by a porch ~~separated~~ supported by square columns with the porch floor being supported by square brick piers. Also visible is a chimney at the peak of the roof ridge pole eastern-most bay of the extension. Also visible on this facade is the

CONTINUE ON SEPARATE SHEET IF NECESSARY

the entrance to the basement, located in the foundation of the western-most bay of the eastern-most extension. This extension features a slightly lower roofline than that of the more westerly extension. Also noted was a smaller, one story addition resembling an enclosed porch or stoop with hip roof and a single, centrally located 2 lite casement window.

The east facade features the gable-end of the eastern-most extension with a centrally located 4/4 sash window. This facade displays a full view of the southern-most bay of the main block and points up the basic L-shape of the structure. Also featured on this facade is what appears to be a one-story addition or enclosed porch with hip roof and centrally located entranceway.

The north facade is characterized by irregular fenestration and window size with 4/4, 3/3 and 1/1 sash. Also visible on this facade are the graduated rooflines of the telescoping extension. The gable-end of the main block visible on this facade, features centrally located 4/4 sash windows in the first and second story. The western-most extension features two 4/4 lite sash windows located on the second story and one in the eastern-most bay of the first story. The eastern-most portion of the telescoping extension is characterized by a slightly lower roofline and a single 6 lite casement window located in the western-most end of the first story. Also visible on this facade is what appears to be an enclosed stoop or porch. This one-story addition is one bay wide and features one centrally located 2 lite casement window.

INTERIOR

Upon entering the structure located at 709 Baltimore Avenue, it can be noted that the transom placed above the door contains a pane of frosted glass. The main or western entrance opens into a side hall containing a stairway featuring an open-string staircase with turned ballisters and scrolled step-ends. Directly to the left of the entrance-way is located a doorway in the northern wall of the hall, leading to the parlor. This northern room features large, floor to ceiling, 4/4 sash windows on the western wall and on the southern wall a centrally located fireplace projecting approximately fifteen inches into the parlor. Also visible is a metal lock box with porcelain door knobs on the door in the eastern wall leading into a dining room. The dining room features an enclosed flue chimney on the western wall. To the east of the dining room are existing a modern kitchen and what appears to be an enclosed perch finished with tongue and groove pine paneling.

The second story is characterized by a short hall at the head of the stairs with one room to the north and a bath room and hall to the south as well as two other modern rooms. Visible in the attic are vertically sawn rafters joined at the ridge pole. Also noted were random width purlins with ribbed shingles. Cut nails are also observable in the attic.

Beneath the structure is a full basement. Accessible only from an exterior entrance located in the foundation of the south facade. The basement features uncoursed stone walls and overhead were visible circular sawn joists.

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

Among the collection of late 19th century and early 20th century houses which constitute the 600 and 700 blocks of Baltimore Ave. one can see several interesting front porches. One of them is on this two story frame and clapboard building.

Prior to air-conditioning and the "patio" the porch was a very important living area in Maryland homes for as much as six months of the year. On entering a home the porch was quite often the first covered area of a house which one encountered and it was common to find specific types of porch furniture. The furnishings of a porch might include not only chairs and benches, but plant stands and a bench-swing, all of which were much used during warmer weather. That this living area was oriented to the street and facilitated at least eye contact with passers by is an important factor in understanding life in a 19th century town.

The porch was also that area of the house where the Victorian preference for ornateness in design saw full bloom. The eaves of the porch were often bracketed to match those of the house and the columns were decorated with chamfers and scrollwork. A significant number of porches had ceilings which were painted sky-blue. Towson has its share of such porches and on # 701 Baltimore Ave. the importance of the porch is almost exaggerated due to the rather oversized scrollwork on the columns. Whether this effect is intentional or more indicative of having bought pre-cut materials is uncertain but there is little doubt that with such a porch this house is a great contribution to this Victorian streetscape.

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

U. S. GEOLOGICAL SURVEY

VERBAL BOUNDARY DESCRIPTION

See Attachment

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE COUNTY

STATE COUNTY

11 FORM PREPARED BY

NAME / TITLE

WAYNE L. NIELD, II
HISTORIC TOWSON, INC.

ORGANIZATION

DATE

STREET & NUMBER

TELEPHONE

CITY OR TOWN

STATE

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

TITLE SEARCH for # 701 BALTIMORE AVE.

Liber 4298, Folio 204 May 11, 1964
 Grantor: Pearl F. Wheattley, widow
 Grantee: Rev. Lawrence J. Shehan

"Beginning...corner formed by intersection of northeast side of Joppa Rd. with southeast side of Baltimore Ave. as laid down on Plat of "Ware's Additions to Towsontowne"...Plat Book JWS #1/47...East 117'5"... East 90'...West 117'5"...90' to place of beginning known as # 701 Baltimore Ave."

Liber 1074, Folio 429 September 16, 1939
 Grantor: Bettie C. Foster, widow
 Grantee: John W. S. Wheattley & wife

Liber 506, Folio 157 August 30, 1918
 Grantor: George C. Tracey & wife
 Grantee: Milton H. Foster & wife

Mortgage: Liber 514/101 June 12, 1917 George C. Tracey & wife to Milton H. Foster, the land being 90' front on Baltimore Ave. by 117'5" of Joppa Rd.

All these two lots...situate on North side of Joppa...Beginning... East 150'...East 150'to south side of Ware Ave...West 32.5'...West 60'... West 117.5'...90'..."

Liber 449, Folio 497 September 28, 1915
 Grantor: J. Frank Parks & wife
 Grantee: George C. Tracey

Liber 287, Folio 394 July 3, 1905
 Grantor: David G. McIntosh, Atty.
 Grantee: George C. Tracey

Liber 248, Folio 13 October 9, 1900
 Grantor: David G. McIntosh & wife
 Grantee: Samuel E. Lloyd

Liber 246, Folio 489 August 23, 1900
 Grantor: Peter E. Torre, Atty.
 Grantee: David G. McIntosh

June 18, 1900 Public sale Mortgage from Benjamin F. Bayne & wife to Jacob Torre June 5, 1895 Mrotgage Records 176/261


Liber 144, Folio 214 January 23, 1885

Grantor: William A. Lee & wife


Grantee: William P. Cole

...and part of lot # 6 and # 8 on Plat of "Ware's Addition to Towson-towns" recorded in Liber 96, Folio 186 January 5, 1895 William P. Cole to Benjamin F. Bayne

Baltimore Ave
701



COPYRIGHT-MAP DIVISION-1967
MD DEPT OF ASSESS & TAX



TOWSON
SCALE 1"=200'
DEPT. OF ASSESSMENT & TAXATION
TAX MAP SYMBOL

BA-1399

MAP N
70A



BA- 1399

701 BALTIMORE AVE
S. W. CORNER

W. NIELD
SUM-78



BA- 1399

701 BALTIMORE AVE.

W. FACADE DETAIL

W. NIELD

9/78



BA-1399

701 BALTIMORE AVE.
N.E.

W. NIELD
9/78