6800426414

CE 42

CE-42 – Ruins – Mill at Rowlandsville on Octoraro Creek

Ruins – stone + poured concrete –
over an acre of factory network of piling,
Retaining walls, house + building ruins.
Old iron turbine in [redacted] the main
mill race.
Along the banks of the Octoraro Creek

owner – J W. Dempsey

(possible park site)

color 2477, 7625-29

CE - 42

Rowlandsville Mill
Rowlandsville
South Elevation
DAG/1967
NEG - MD. Hist. Trust

8



CE-42

Rowlandville Mill MAB – 4/70

CE-42

Rowlandville Mill mos 4/20

CE- 42

Rowlandville Mill MOB - 4/70



CE-42

Rowlandville Mill MMB - 4/70

CE-42

Rowlandville Mill MIB - 4/70