


Inventory Number: CE-527
Tyson House
Cecil County, MD
C. Mazurek
June 1998
Section 7.1

Addendum

The Tyson House is located to the east of the intersection of Gallaher Road and Big Elk Chapel Road. It is just beyond the park entrance gate and straight down the dirt access road.

This structure has been unoccupied for many years, and has deteriorated beyond livability. The loss of the roof has further compounded the problem of deterioration. It is a simple plan that may have been divided into two units, is two and one-half stories tall, and is four bays wide. According to the last historic sites survey in 1979 the roof, now gone, was gabled with a central chimney. The entire structure is constructed of uncut fieldstone, with no courses, that appears to have had a stucco finish applied to it at one time. All of the window sashes and doors have deteriorated or have been vandalized. The interior wood framing has fallen into the basement, but it is still possible to see that the walls were covered with a plaster coating. The entire west facade is missing. For the most part the Tyson House is just the shell of the original structure.



MD
PENN
CECIL CO
CHESTER CO
DIXON
AND
MASON
LINE
FLINT HILL CH
Cem
Christina
East
MA

374
BM
Sharpes
Cem.

384
Fair Hill
Fair Hill Race Track

NEWARK WEST
DIR 98 MAP # 18

Big Elk
Chapel

CE 52
TYSON
HOUSE

Appleton

Kenmore
Sch

Andora

CE 57

238



CE-527

TYSON HOUSE, FAIR HILL N.R.M.A.

CECIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES

WEST ELEVATION

NO. 2501 70105 8401 N.N.N.N-05 2



CE-527

TYSON HOUSE, FAIR HILL N.R.M.A.

CECIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES

S.E. ELEVATION

NOV 1997 10:51 AM



CE-527

TYSON HOUSE, FAIR HILL N.R.M.A.

CÉCIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES

N.E. ELEVATION

27 186 0661 N N N N 96 2



CE-527

TYSON HOUSE, FAIR HILL N.R.M.A.

CECIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES

FACING NORTH

NO. 222-1 100 0561 N N N N N

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC
TYSON HOUSE RUINS
AND/OR COMMON

2 LOCATION

STREET & NUMBER
East bank of the Big Elk Creek below Brewsters Bridge
CITY, TOWN
Elk Mills
STATE
Maryland
VICINITY OF
CONGRESSIONAL DISTRICT
4
COUNTY
Cecil

3 CLASSIFICATION

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input type="checkbox"/> PUBLIC	<input type="checkbox"/> OCCUPIED	<input type="checkbox"/> AGRICULTURE <input type="checkbox"/> MUSEUM
<input type="checkbox"/> BUILDING(S)	<input checked="" type="checkbox"/> PRIVATE	<input checked="" type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL <input type="checkbox"/> PARK
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> PRIVATE RESIDENCE
<input checked="" type="checkbox"/> SITE	PUBLIC ACQUISITION	ACCESSIBLE	<input type="checkbox"/> ENTERTAINMENT <input type="checkbox"/> RELIGIOUS
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input checked="" type="checkbox"/> YES: RESTRICTED	<input type="checkbox"/> GOVERNMENT <input type="checkbox"/> SCIENTIFIC
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> INDUSTRIAL <input type="checkbox"/> TRANSPORTATION
		<input type="checkbox"/> NO	<input type="checkbox"/> MILITARY <input type="checkbox"/> OTHER:

4 OWNER OF PROPERTY

NAME
State of Maryland, Dept. Of Natural Resources Telephone #:
STREET & NUMBER
Tawes State Office Building
CITY, TOWN
Annapolis
VICINITY OF
STATE, zip code
Maryland 21401

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE.
REGISTRY OF DEEDS, ETC. Clerk of the Circuit Court
STREET & NUMBER
Cecil County Courthouse
CITY, TOWN
Elkton
STATE
Maryland
Liber #: WAS 347
Folio #: 441

6 REPRESENTATION IN EXISTING SURVEYS

TITLE
DATE
DEPOSITORY FOR SURVEY RECORDS
CITY, TOWN
STATE
 FEDERAL STATE COUNTY LOCAL

7 DESCRIPTION

CONDITION

- EXCELLENT
- GOOD
- FAIR
- DETERIORATED
- RUINS
- UNEXPOSED

CHECK ONE

- UNALTERED
- ALTERED

CHECK ONE

- ORIGINAL SITE
- MOVED DATE _____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Tyson House Ruins are the remains of two stone structures. Only parts of one remain standing: it is built of fieldstone and has two walls, the south gable and facade. The building was two stories and four bays long by two deep. The house had a gable roof and a central chimney. The facade has two entrances suggesting that the house was a duplex. Both of these houses were standing in 1959.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input checked="" type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The ruins date from the early to mid-1800's and possibly served as mill workers homes during this period due to the fact that flour mills were in operation within 1/4 mile of the houses.

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE COUNTY

STATE COUNTY

11 FORM PREPARED BY

NAME / TITLE

George W. Lutz III, Field Historian

ORGANIZATION

DATE

Cecil Historical Trust, Inc.

STREET & NUMBER

TELEPHONE

R.D. 2

CITY OR TOWN

STATE

Rising Sun

Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

Tyson House Ruins

AND/OR COMMON

2 LOCATION

STREET & NUMBER East bank of the Big Elk Creek Below
Brewsters Bridge

CITY, TOWN

Elk Mills

___ VICINITY OF

CONGRESSIONAL DISTRICT

STATE

Maryland

COUNTY

Cecil

3 CLASSIFICATION

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input type="checkbox"/> PUBLIC	<input type="checkbox"/> OCCUPIED	<input type="checkbox"/> AGRICULTURE <input type="checkbox"/> MUSEUM
<input type="checkbox"/> BUILDING(S)	<input checked="" type="checkbox"/> PRIVATE	<input checked="" type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL <input type="checkbox"/> PARK
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> PRIVATE RESIDENCE
<input checked="" type="checkbox"/> SITE	PUBLIC ACQUISITION	ACCESSIBLE	<input type="checkbox"/> ENTERTAINMENT <input type="checkbox"/> RELIGIOUS
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input checked="" type="checkbox"/> YES: RESTRICTED	<input type="checkbox"/> GOVERNMENT <input type="checkbox"/> SCIENTIFIC
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> INDUSTRIAL <input type="checkbox"/> TRANSPORTATION
		<input type="checkbox"/> NO	<input type="checkbox"/> MILITARY <input type="checkbox"/> OTHER

4 OWNER OF PROPERTY

NAME Department of Natural Resources

Telephone #:

STREET & NUMBER

R

CITY, TOWN

___ VICINITY OF

STATE, zip code

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE, REGISTRY OF DEEDS, ETC. Clerk of the Circuit Court

Liber #: WAS 347

Folio #: 441

STREET & NUMBER

Cecil County Courthouse

CITY, TOWN

Elkton

STATE

Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

___ FEDERAL ___ STATE ___ COUNTY ___ LOCAL

DEPOSITORY FOR SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input checked="" type="checkbox"/> RUINS	<input checked="" type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Tyson House Ruins are the remains of two stone structures. Only one remains standing; it is built of fieldstone and has two walls the south gable and facade. The building was two stories in height and four bays long by two deep. The house had a gable roof and a central chimney. The facade has two entrances suggesting that the house was a duplex. Both of these houses were standing in 1959.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

CE-527

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input checked="" type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The ruins date from the early to mid-1800's and possibly served as mill workers homes during this period due to the fact that flour mills were in operation within $\frac{1}{4}$ mile of the houses.

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE COUNTY

STATE COUNTY

11 FORM PREPARED BY

NAME / TITLE

George W. Lutz, III Field Historian

ORGANIZATION

Cecil Historical Trust, Inc

DATE

January 1977

STREET & NUMBER

R.D. 2

TELEPHONE

CITY OR TOWN

Rising Sun

STATE

Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

The Tyson House ruins are the remains of a two and three-quarters story structure that appears to have been an impressive architectural dwelling for this region. The entire west wall and westernmost bay of the north and south walls have collapsed. However, one can distinguish from the remaining architectural trim, such as the dentil cornice, and by the size and style of this structure that it was a prominent building for its time. It was constructed of stone and had a gable roof. The interior had a central hall plan with a stairway in the central hall. The structure appears to have been built in the early nineteenth century in a Rural Federal style.

The Tyson House Ruins are located on the east side of Big Elk Road. They are approximately .3 mile east of Big Elk Chapel and .5 mile west of Scott's Mill. The structure was located on a slight prominence in the landscape. Its site and the sharp vertical lines of its two and three-quarters story facades projected a prominent visual impact.

The Tyson House Ruins consist of the east gable end of the house and the four-bays of the north and south facade. The west gable end and the westernmost bay of the north and south facade have entirely collapsed. The structure was constructed of field-stone covered in stucco. It is two and three-quarters story tall and originally was a five-bay by two-bay structure. The main facade faced north and had a central entrance. The outer bays of the first story and five-bays of the second story contain six-over-six sash windows. The three-quarter story had three windows

symmetrically arranged in the center bay in the outer bays of the structure. The gable roof contained a boxed and *dentil* cornice. ^{The roof} It was most recently covered in sheet metal. The east gable end has two windows on the first story and two small windows in the gable. There was an interior-end chimney on this wall. It is not possible from the ruins to determine the fenestration on the west wall. The south facade was fenestrated in a manner similar to the north facade but also contains two foundation level three-pane windows.

The interior of the house had a central hall plan with rooms on each side of the hall. The stairway to the second floor rose along the west hall of the central hall. The interior framing that remains can be easily viewed in the ruins. The structure had a common rafter roof.

DRAFT

MEMO

TO: ROSS KIMMEL, State Historian
FROM: Joe Getty, Architectural Surveyor
DATE: April 8, 1984
SUBJECT: Buildings at Fair Hill NRMA

There was some confusion over the sites on my list located within the Fair Hill NRMA. I met with Tom Merryweather and Bill ~~McMaster~~ and I believe we resolved the problems on my list. The problematic sites are:

CE-362 McMaster Farm. The survey form contains an incorrect map location. The house and barn were located on the site where the equestrian center is currently being constructed. The buildings were demolished in 1982.

CE-771 McCleary House. This map location is wrong and Tom Merryweather believes that the photograph is of a house that is actually in Pennsylvania. There is only one brick structure north of Route 273 in the Fair Hill NRMA.

Cockerham Property. A two-story, three-bay by two-bay house with an L-shaped plan located at the site inaccurately marked as McMaster Farm. See survey form.

J. M. Peterson Farm. A two-story, three-bay by two-bay house with an L-shaped plan located at the site inaccurately marked as McCleary House. See survey form.

Gann Property. A two-story, five-bay by two-bay stone house with a collapsed west wall that is not located on previous surveys. See survey form.

DNR-50 New Covered Bridge. Tom Merryweather states that this is not nor never was a covered bridge. The inaccurately labeled structure is actually a gatehouse.

cc: *McMasta Farm file*
McLewey House file

PENNSYLVANIA
MARYLAND

5 MASON

AND

4 DIXON

CHESTER CO
CECIL CO

3 LINE

DNR- McCLEARY HOUSE
CE-771

BUNTING HOUSE
CE

DNR-33 SCHOOL HOUSE
CE-758

DNR-14/16 BARN, FEED MILL

DNR-28 MCMASTER HOUSE
CE-362

DNR-13 HAY LOFT
CE-300-C

DNR-47 BARN
CE-364-A

DNR-04 FINLEY BARN
CE-301-A

DNR-12 SMOKE HOUSE
CE-300-12

DNR-45 HOUSE
CE-364

DNR-03 CARE TAKER'S
HOUSE

DNR-10 BEERS HOUSE
CE-300-

DNR-50
NEW COVERED BRIDGE

DNR-02 FINLEY HSE
CE-301

DNR-11 BEERS BARN
CE-300-A

DNR-03, 93, TRACK STRUCTURES
CE-552

DNR-01 COVERED
BRIDGE CE-238

DNR-103 CLUB
CE-75

DNR-77 HOUSE CE-54

DNR-90-102 TRACK
STRUCTURES CE-552

DNR-51 HOUSE

DNR-53 STABLES

DNR-56 STONE HOUSE CE-363

DNR-64 STONE STABLES CE-366

SCOTT MILL DAM

NEWARK
WEST
QUAD.

CE-527

TYSON HOUSE
RUINS CE-527

GAYLEN HOUSE
RUINS CE-517

COVERED BRIDGE
SITE CE-516

HOUSE RUINS

SCOTT MILL RUI
CE

5663 III NW
(BAY VIEW)

LITTLE
ELK

Andora

Big Elk
Chapel

Grannies

ANT HILL 1.5 MI.

Providence

Kenmore
Sch

BM 352

Cowe



CE-527





CE-527