

Inventory Number: CE-717
Bunting House
Cecil County, MD
C. Mazurek
June 1998
Section 7.1

Addendum

The Bunting House is located to the west of Appleton Road, and just south of the Mason-Dixon Line in the Fair Hill N.R.M.A. It has been unoccupied for a number of years and is concealed by underbrush and vegetation.

Since the last historic sites surveys were completed in 1979 and 1984 no changes have occurred on this property. The house, silo, stone barn, and wood outbuildings are still intact; however the lack of maintenance has caused the buildings to deteriorate further.

PA
VILLE
PENNSYLVANIA
AND
DIXON
CHESTER CO
CECIL CO
LINE
PENN
MA

**CECIL
BUNTING
HOUSE**



BM
374
Sharpes
Cem

Fair Hill
Fair Hill Race Track


**NEWARK WEST
DNR 98 MAP #3**

Big Elk
Chapel

Appleton

Kenmore
Schl

Andora





CE-717

BUNTING HOUSE; FAIR HILL N.R. - M.A.

CECIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES

HOUSE RUINS

<No. 329> 46 05 0001 N N N N-01 2



CE-717

BUNTING HOUSE; FAIR Hill N.R. M.A.

CECIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES

HOUSE RUINS

10-N-N-01 2
1065 8561 N N N-01 2



3.a

CE-717

BUNTING HOUSE; FAIR HILL N.R., MA.

CECIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES

NO. 17 25 000 0561 N N N N N-09 X



CE-717

BUNTING HOUSE; FAIR HILL N.R. M.A.

CECIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES

2005 OCT 01 N N N N-08 2





NO. 251 304 100 0561 N N N N 83 7

CE-717

BUNTING HOUSE; FAIR HILL N.R. M.A.

CECIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES

SILO AND BARN RUINS



CE-717

HOUSE RUINS; FAIR HILL N.R. MA.

CECIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES

<NO.

E>

74-185

2061

N

N

N

N

N

N

N

N

2

MARYLAND HISTORICAL TRUST

CE-717
0807174204

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC **Bunting House**

AND/OR COMMON

2 LOCATION

STREET & NUMBER **west of Appleton Road just south of the Mason Dixon Line**

CITY, TOWN **Elkton**

CONGRESSIONAL DISTRICT **1**

VICINITY OF

STATE **Maryland**

COUNTY **Cecil**

3 CLASSIFICATION

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input checked="" type="checkbox"/> PUBLIC	<input type="checkbox"/> OCCUPIED	<input checked="" type="checkbox"/> AGRICULTURE <input type="checkbox"/> MUSEUM
<input checked="" type="checkbox"/> BUILDING(S)	<input type="checkbox"/> PRIVATE	<input checked="" type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL <input type="checkbox"/> PARK
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> PRIVATE RESIDENCE
<input type="checkbox"/> SITE	PUBLIC ACQUISITION	ACCESSIBLE	<input type="checkbox"/> ENTERTAINMENT <input type="checkbox"/> RELIGIOUS
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input checked="" type="checkbox"/> YES: RESTRICTED	<input checked="" type="checkbox"/> GOVERNMENT <input type="checkbox"/> SCIENTIFIC
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> INDUSTRIAL <input type="checkbox"/> TRANSPORTATION
		<input type="checkbox"/> NO	<input type="checkbox"/> MILITARY <input type="checkbox"/> OTHER:

4 OWNER OF PROPERTY

NAME **Department of Natural Resources**

Telephone #:

STREET & NUMBER **Taves Office Building**

CITY, TOWN **Annapolis**

VICINITY OF

STATE, zip code

Maryland 21401

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE, REGISTRY OF DEEDS, ETC. **Clerk of the Circuit Court**

Liber #: **WAS 347**

Folio #: **415**

STREET & NUMBER **Cecil County Courthouse**

CITY, TOWN **Elkton**

STATE **Maryland**

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

FEDERAL STATE COUNTY LOCAL

DEPOSITORY FOR SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

CONDITION		CHECK ONE		CHECK ONE	
<input type="checkbox"/> EXCELLENT	<input checked="" type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE	<input type="checkbox"/> MOVED	DATE _____
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input checked="" type="checkbox"/> ALTERED			
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED				

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Bunting House is a simple farmhouse built in two sections in the "colonial" style, The house is approximately 5 bays long by two bays deep and faces the south. The entire house is two stories in height and is built on two levels because the house is built into a hillside and because the two major sections were not built at the same time. The earlier part of this structure is the eastern end or eastern two bays of the house. It is built of hewn logs laid in the saddle notch style which were chinked with mud. This section as does the stone section, has a gable roof covered with asphalt shingles. Some of the early rafters still support the roof, but they appear to be mixed in with some later wood. The roof has a plain box cornice. In the east gable wall is a small brick stove chimney. There appears to have been a large fireplace in the west gable wall but it has been covered over. The exterior walls have tile shingles and the interior has a covering of lath and plaster. The facade has a central entrance and a single story Victorian porch probably built after 1900. In the upper story are two gable roof dormers. The house has 6/6 sash throughout. The interior looks like it was altered when the stone section was built. Toward the back of the log section is an open well stair with a landing at the same level as the second story of the stone section. There is no hardware left with the exception of some handmade nails.

The stone section is roughly of the same dimensions as the log side of the house. It is built of fieldstone and has been covered with stucco which has worn off in some places. In the west gable wall is a brick end chimney. The first floor room has some circa 1830 woodwork particularly some cupboards made of beaded lumber. There is also a nice door with ten panels which are flush with the stile. On the eastern wall of the first floor is an entrance to the cellar. The house has a stone foundation with log floor joists.

On the rear of both sides of the house are frame shed additions. Behind the house are several frame outbuildings that date from the late 19th century. Directly to the west of the house is an enormous stone bank barn made of fieldstone. The roof has deteriorated, but it was gable construction. The barn was about three stories in height and six bays long by three deep. Some of the stone used in the construction is serpentine

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input checked="" type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input checked="" type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input checked="" type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES	BUILDER/ARCHITECT
----------------	-------------------

STATEMENT OF SIGNIFICANCE

The Bunting House is important because of its log construction within the New Munster grant. This area was settled around 1711-20. Although it has not yet been determined the house could date partially from the mid to early part of the 18th century. The logs for the most part are in good condition and are worthy of preservation. The farm must have been very productive due to the size of the stone bank barn. It is the largest of its kind in the area. This house could have been lived in by a member of the Finley family an early important family. The Elk Creeks Preservation group is doing research on this building at the present time.

CE-717

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Lake, Griffith, and Stevenson An Illustrated Atlas of Cecil County Maryland Phila. 1877
Martenet, Simon J. Martenet's Map of Cecil County, Maryland.
Phila. R. L. Barnes

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE	COUNTY
STATE	COUNTY

11 FORM PREPARED BY

NAME / TITLE	DATE
George Lutz Field Historian	Jan 1977
ORGANIZATION	TELEPHONE
Cecil Historical Trust	658-6850
STREET & NUMBER	STATE
RD 2	Maryland
CITY OR TOWN	
Rising Sun	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

MARYLAND HISTORICAL TRUST

CE 717

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC BUNTING HOUSE
AND/OR COMMON

2 LOCATION

STREET & NUMBER West of Appleton Road just south of the Mason Dixon Line
CITY, TOWN Elkton CONGRESSIONAL DISTRICT 1
STATE Maryland COUNTY Cecil

3 CLASSIFICATION

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input checked="" type="checkbox"/> PUBLIC	<input type="checkbox"/> OCCUPIED	<input checked="" type="checkbox"/> AGRICULTURE <input type="checkbox"/> MUSEUM
<input checked="" type="checkbox"/> BUILDING(S)	<input type="checkbox"/> PRIVATE	<input checked="" type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL <input type="checkbox"/> PARK
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> PRIVATE RESIDENCE
<input type="checkbox"/> SITE	PUBLIC ACQUISITION	ACCESSIBLE	<input type="checkbox"/> ENTERTAINMENT <input type="checkbox"/> RELIGIOUS
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input checked="" type="checkbox"/> YES: RESTRICTED	<input checked="" type="checkbox"/> GOVERNMENT <input type="checkbox"/> SCIENTIFIC
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> INDUSTRIAL <input type="checkbox"/> TRANSPORTATION
		<input type="checkbox"/> NO	<input type="checkbox"/> MILITARY <input type="checkbox"/> OTHER:

4 OWNER OF PROPERTY

NAME State of Maryland, Dept. of Natural Resources Telephone #:
STREET & NUMBER Tawes Office Building
CITY, TOWN Annapolis STATE, zip code Maryland 21401

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE, REGISTRY OF DEEDS, ETC. Clerk of the Circuit Court Liber #: was 347 Folio #: 415
STREET & NUMBER Cecil County Courthouse
CITY, TOWN Elkton STATE Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE
DATE
DEPOSITORY FOR SURVEY RECORDS
CITY, TOWN STATE

7 DESCRIPTION

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input checked="" type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input checked="" type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Bunting House is a simple farmhouse built in two sections. The house is 5 bays long and two bays deep, facing the south. The house is two stories built into a hillside. The earlier part, the eastern two bays of the house, are built of hewn logs laid in the saddle notch style, chinked with mud. The entire house has a single gable roof with asphalt shingles. Some of the early rafters still support the roof, but they appear to be mixed in with some later circular-sawn wood. The roof has a plain box cornice. In the east gable wall is a small brick stove chimney. There appears to have been a large fireplace in the west gable wall but it has been covered over. The exterior walls are shingled and the interior has a covering of lath and plaster. The facade has a central entrance and on story porch probably built after 1900. In the upper story are two gable roof dormers. The house has 6/6 sash throughout. The interior appears to have been altered when the stone section was built. Toward the back of the log section is an open well stair with a landing at the same level as the second story of the stone section. There is no hardware left with the exception of some handmade nails.

The stone section is roughly of the same dimensions as the log portion of the house. It is built of fieldstone and has been covered with stucco which has worn off in some places. A brick end chimney is in the west gable wall. The first floor room has some 1830's woodwork*, particularly cupboards made of beaded lumber. There is also a nice door with ten panels which are flush with the stile. On the eastern wall of the first floor is an entrance to the cellar. The house has a stone foundation with log floor joists.

On the rear of both sides of the house are frame shed additions. Behind the house are several frame outbuildings that date from the late 19th century. Directly to the west of the house is an enormous stone bank barn made of fieldstone. The roof has deteriorated, but it was gable construction. Some of the stone used in the construction is serpentine, some quartz.

* 1979 examination turned up no significant woodwork. The door mentioned is gone.

8 SIGNIFICANCE

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW				
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION	
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE	
<input type="checkbox"/> 1500-1599	<input checked="" type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE	
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN	
<input checked="" type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER	
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input checked="" type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION	
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)	
		<input type="checkbox"/> INVENTION			

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The Bunting House is important because of its log construction within the New Munster grant. This area was settled around 1711-20. Although it has not yet been determined, the house could date partially from the mid to early part of the 18th century. The logs for the most part are in good condition and are worthy of preservation. The farm must have been very productive due to the size of the stone bank barn. It is the largest of its kind in the area. This house could have been lived in by a member of the Finley family, an early important family.

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Lake, Griffith, and Stevenson An Illustrated Atlas of Cecil County Maryland, Phila. 1877

Martenet, Simon J. Martenet's Map of Cecil County, Maryland, Phila. R.L. Barnes

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE	COUNTY
STATE	COUNTY

11 FORM PREPARED BY

NAME / TITLE

George Lutz, Field Historian/ John D. Hnedak

ORGANIZATION

Cecil Historical Trust/MHT

DATE

Jan 1977/1979

STREET & NUMBER

Rd 2

TELEPHONE

658-6850

CITY OR TOWN

Rising Sun

STATE

Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

The Bunting House is a two section structure consisting of a two-story stone section and a one and one-half story log section. The main facade faces south and ~~is~~ the stone section is three-bays with a central entrance. Six-over-six sash windows are in the outer bays of the first story and, on the second story, two windows are located immediately above those on the first story. The stone structure is constructed of field and quarried stone from the area. The stone ^{r work} ~~structure~~ was covered in stucco and whitewashed. It has a gable roof covered in asphalt shingles. The log structure has a high stone foundation that was originally covered in wood siding. It is now covered in ^{asbestos} ~~asbestos~~ exterior siding. The south facade has a central entrance with six-over-six windows on either side of the entrance. Above the windows are gabled dormers. Both sections have rear frame additions.

The Bunting House is located on the west side of Appleton Road, approximately 1.4 mile north of Maryland Route 273. The house is built on a sloping site approximately .2 mile west of Appleton Road. The site is presently overgrown with weeds and small trees.

The earliest section of the house appears to be the east section constructed of logs. It is a one and one-half story log structure on a ~~sub~~^{field} stone basement. The manner in which the foundation of the stone section connects to the western portion of the house and in the way the logs are tied into the log section indicate that the log section was probably the earlier of the two. This section has a common rafter roof and the roof has been extended in catslide manner to cover a frame addition on the north facade. The logs were originally covered with stucco and white-washed. Later a weatherboard exterior was placed around the house and in the twentieth century this was covered with an asbestos siding. The log section is three-bays wide with an entrance located off-center. Six-over-six sash windows were located in the other two bays. A full-length, one-story Victorian style porch with a shed roof extended the length of the log section only. The porch has turned posts, exposed rafter ends, and a corrugated metal roof. At the easternmost portion of the porch was a stairway into the basement of the stone section. The half-story has two gabled dormer windows that rise from the front wall of the house. At the east gable end of the structure is a brick flue. However, there is evidence that a large fireplace existed at this wall at one time. The north facade of this structure has a

sharply sloping roof due to the catslide and a central entrance flanked by two windows.

The stone structure is a two-story, three-bay by one-bay addition. It is constructed of fieldstone and was originally covered with stucco. The main facade has a central entrance flanked by a single six-over-six window on each side. The second story has six-over-six windows immediately above the windows of the first story. The structure has a gable roof with a boxed cornice. The west gable end is unfenestrated except for two four pane windows in the gable. There is an interior-end chimney at this gable end. The north facade has a one-story frame addition with a shed roof. The second story of the stone section has two six-over-six sash windows. The frame section has a central entrance with a six-over-six window on each side.

PENNSYLVANIA MARYLAND 5 MASON AND 4 DIXON CHESTER CO 3 CECIL CO LINE

DNR-771 McCLEARY HOUSE CE-771

BUNTING HOUSE CE

DNR-33 SCHOOL HOUSE CE-758

DNR-1007 BARN, FEED MILL

DNR-28 MCMASTER HOUSE CE-362

DNR-13 HAY LOFT CE-300-C

DNR-47 BARN B74

DNR-04 FINLEY BARN CE-301-A

DNR-12 SMOKE HOUSE CE-300-12

DNR-45 HOUSE CE-364

DNR-03 CAR TAKERS HOUSE

DNR-10 BEERS HOUSE CE-300-

DNR-50 NEW COVERED BRIDGE

DNR-02 FINLEY ASE CE-301

DNR-11 BEERS BARN CE-300-A

DNR-03, 93, TRACK STRUCTURES CE-552

DNR-01 COVERED BRIDGE CE-238

DNR-103 CLUB CE-75

DNR-77 HOUSE CE-544

DNR-90-92 TRACK STRUCTURES CE-552

DNR 51 HOUSE

DNR 53 STABLES

DNR 56 STONE HOUSE CE-363

DNR 64 STONE STABLES CE-366

SCOTT MILL DAM

TYSON HOUSE RUINS CE-527

GAYLEN HOUSE RUINS CE-517

HOUSE RUINS CE

COVERED BRIDGE SITE CE-516

SCOTT MILL RUIN CE

NEWARK WEST QUAD.

LIL-32

5863 III NW (BAY VIEW) SANT HILL 1.5 MI.

LITTLE ELK

Providence

Kenmore Sch

Andora

Big Elk Chapel

TYSON HOUSE

GAYLEN HOUSE

HOUSE RUINS

SCOTT MILL RUIN

Cowe



Bunting House 1976

CE-717

ELKTON, MARYLAND

4



Bunting House 1976

CE-717

ELKTON, MARYLAND