

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Survey No. CE-771

1. Name of Property (indicate preferred name)

historic Cockerham Property

other McCleary House

2. Location

street & number Within Fair Hill N.R.M.A.; south of Mason-Dixon Line.

not for publication

city, town Fair Hill

vicinity

county Cecil

3. Owner of Property (give names and mailing addresses of all owners)

name Maryland Department of Natural Resources

street & number 580 Taylor Avenue, Tawes State Office Building

telephone (410) 260-8186

city, town Annapolis

state and zip code Maryland, 21401

4. Location of Legal Description

courthouse, registry of deeds, etc.

tax map and parcel

city, town

liber and folio

5. Primary Location of Additional Data

- Individually Listed in the National Register/Maryland Register
- Contributing Resource in National Register District
- Contributing Resource in Local Historic District
- Determined Eligible for the National Register/Maryland Register
- Recorded by HABS/HAER
- HSR or Research report at MHT
- Other:

6. Classification

Inventory Number: CE-771
Cockerham Property
Cecil County, MD
C. Mazurek
June 1998
Section 7.1

Addendum

The Cockerham Property is located within the Fair Hill N.R.M.A. in Cecil County, Maryland. It is sited just south of the Mason-Dixon Line and just west of the Big Elk Creek off of a dirt access road within the N.R.M.A. boundaries.

The main house is a two and one-half story tall, late Nineteenth century, Victorian, frame farmhouse with an overall "L"-shaped design. The foundation is constructed of uncut fieldstone with no courses directly visible. Exterior wall cladding is of asbestos shingles, which are without a doubt a later replacement for wood shingles. On the exterior wall space under the front gables are the original wood shingles in a traditional Victorian chisel pattern. The front-gabled roof has a covering of replacement composition shingles. All the windows have been either broken out, or removed, so it is impossible to tell the sash glazing patterns, although they were most likely typical 2/2 sash patterns.

According to the survey done by Joe Getty in 1984 much of the interior fabric has been removed. With the house vacant it has suffered major deterioration, however the roof is still mostly intact and keeping out water. Vegetation has overgrown the house site and is also leading to further deterioration.

Also on the Cockerham Property is a round two to three story silo that is in deteriorated condition.

8. Significance

Survey No. CE-771

Period	Areas of Significance	Check and justify below		
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> health/medicine	<input type="checkbox"/> performing arts
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> archeology	<input type="checkbox"/> education	<input type="checkbox"/> industry	<input type="checkbox"/> philosophy
<input checked="" type="checkbox"/> 1800-1899	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> engineering	<input type="checkbox"/> invention	<input type="checkbox"/> politics/government
<input type="checkbox"/> 1900-1999	<input type="checkbox"/> art	<input type="checkbox"/> entertainment/ recreation	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
	<input type="checkbox"/> commerce	<input type="checkbox"/> ethnic heritage	<input type="checkbox"/> law	<input type="checkbox"/> science
	<input type="checkbox"/> communications	<input checked="" type="checkbox"/> exploration/ settlement	<input type="checkbox"/> literature	<input type="checkbox"/> social history
	<input type="checkbox"/> community planning		<input type="checkbox"/> maritime history	<input type="checkbox"/> transportation
	<input type="checkbox"/> conservation		<input type="checkbox"/> military	<input type="checkbox"/> other:

Specific dates

Builder/Architect

Evaluation for:

National Register Maryland Register not evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, and a narrative discussion of the history of the resource and its context. (For compliance reports, discuss evaluation on a DOE Form - see manual).

*See attached

Inventory Number: (E - 771)
Cockerham Property
Cecil County, MD
C. Mazurek
June 1998
Section 8.1

Addendum

The Cockerham Property is significant as an example of the rural Victorian farming complexes that once dominated the Fair Hill area. Although there is not much of the house structure left, except for a shell, it still retains some of it's Victorian elements to remain as a record of the past.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Survey No. CE-771

Name
Continuation Sheet
Number 8 Page 2

HISTORIC CONTEXT:

MARYLAND COMPREHENSIVE PRESERVATION PLAN DATA

Geographic Organization: Eastern Shore

Chronological/Developmental Period(s): Industrial/Urban Dominance

Prehistoric/Historic Period Theme(s): Architecture, Landscape Architecture, Community Planning.

Resource Type:

Category: Building

Historic Environment: Rural

Historic Function(s) and Use(s): Farming

Known Design Source: None

9. Major Bibliographical References

Survey No. CE-771

10. Geographical Data

Acreage of surveyed property _____

Quadrangle name _____

Quadrangle scale _____

Verbal boundary description and justification

11. Form Prepared By

name/title C. Mazurek, Historic Sites Surveyor

Date 6/22/98

city or town Annapolis

state and zip code Maryland 21401

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust
DHCD/DHCP
100 Community Place
Crownsville, MD 21032-2 023
410-514-7646

SYLVANIA
BYLAND

5 MASON

AND

4 DIXON

CHESTER CO
CECIL CO

LINE

PENN
MA

**COCKERHAM
PROPERTY.**



CREEK

Flint Hill
Ch
Cem

Christina

East

BM 374
Shares
Cem

300


300

300

300

325

Fair Hill



369

Kenmore
Sch

**NEWARK WEST
DNR 98 MAP #10**

Andora

Big Elk
Chapel

292

Appleton

300

300

300

300

238

CE 171



CE-771

COOKERHAM PROPERTY, FAIR HILL N.R.M.A. 6.a

CECIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES

SILLO

1/3

NO. 771 02 105 8563 N N N-03 2





CE-77†

6

COCKERHAM PROPERTY, FAIR HILL N.R.M.A.
CECIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES

FARMHOUSE

79 187 0561 N N N N-81 2

3/3

Inventory Number: CE-771
McCleary House
Cecil County, MD
C. Mazurek
June 1998
Section 8.1

Addendum

According to Joe Getty, who was an Architectural Surveyor for the Department of Natural Resources in 1984, this house is not located in Maryland.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC McCLEARY BRICK HOUSE

AND/OR COMMON

2 LOCATION

STREET & NUMBER

Just south of Mason Dixon line, 1 mile east of Lewisville, PA

CITY, TOWN

Lewisville (Pennsylvania) VICINITY OF

CONGRESSIONAL DISTRICT

1

STATE

Maryland

COUNTY

Cecil

3 CLASSIFICATION

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input checked="" type="checkbox"/> PUBLIC	<input type="checkbox"/> OCCUPIED	<input checked="" type="checkbox"/> AGRICULTURE <input type="checkbox"/> MUSEUM
<input type="checkbox"/> BUILDING(S)	<input type="checkbox"/> PRIVATE	<input checked="" type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL <input type="checkbox"/> PARK
<input checked="" type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> PRIVATE RESIDENCE
<input type="checkbox"/> SITE	PUBLIC ACQUISITION	ACCESSIBLE	<input type="checkbox"/> ENTERTAINMENT <input type="checkbox"/> RELIGIOUS
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input checked="" type="checkbox"/> YES: RESTRICTED	<input type="checkbox"/> GOVERNMENT <input type="checkbox"/> SCIENTIFIC
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> INDUSTRIAL <input type="checkbox"/> TRANSPORTATION
		<input type="checkbox"/> NO	<input type="checkbox"/> MILITARY <input type="checkbox"/> OTHER

4 OWNER OF PROPERTY

NAME

State of Maryland, Dept. of Natural Resources Telephone #:

STREET & NUMBER

Tawes State Office Building

CITY, TOWN

Annapolis

VICINITY OF

STATE, zip code

Maryland 21404

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,
REGISTRY OF DEEDS, ETC.

Clerk of the Circuit Court

STREET & NUMBER

Cecil County Courthouse

CITY, TOWN

Elkton

STATE

Maryland

Liber #: WAS 347

Folio #: 415

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

FEDERAL STATE COUNTY LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

CE-771

7 DESCRIPTION

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input checked="" type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The McCleary Farmhouse is a two-storey building built of brick laid in common bond. The house has a gable roof with slate shingles. The rafter ends are hidden by a box cornice and bed moulding. The house had inside end chimneys but they have fallen down. Between the first and second storeys, there is a belt course on the north and south walls. The house has a stone foundation and full cellar. The joists for the first storey floor are exposed and show cut nails and circular saw blade marks. The south wall which was probably the facade has a central entrance. The house is three bays long by two deep. The rear wall has a side bay entrance which appears to have had single storey porches. The interior has been removed, but the house did have some chairrail. Some of the first storey windows have paneled shutters.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The McCleary Farmhouse is an early 19th century structure which is in a semi-ruinous condition. Although unoccupied, it is structurally sound and could be preserved.

(In 1977, the state of the house was more than semi-ruinous; today it could be considered an archaeological site) JDH - 1979

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE COUNTY

STATE COUNTY

11 FORM PREPARED BY

NAME/TITLE

George W. Lutz III, Field Historian

ORGANIZATION

Cecil County Committee

DATE

STREET & NUMBER

RD 2

TELEPHONE

CITY OR TOWN

Rising Sun

STATE

Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

MARYLAND HISTORICAL TRUST

CE-771
MAGI # 0807715404

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

McCleary Brick House

AND/OR COMMON

2 LOCATION

STREET & NUMBER

Just south of Mason Dixon Line, 1 mile east of Lewisville, Pennsylvania

CITY, TOWN

CONGRESSIONAL DISTRICT

Lewisville (Pennsylvania)

VICINITY OF

1
COUNTY

STATE

Maryland

Cecil

3 CLASSIFICATION

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input checked="" type="checkbox"/> PUBLIC	<input type="checkbox"/> OCCUPIED	<input checked="" type="checkbox"/> AGRICULTURE
<input type="checkbox"/> BUILDING(S)	<input type="checkbox"/> PRIVATE	<input checked="" type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> MUSEUM
<input checked="" type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> COMMERCIAL
<input type="checkbox"/> SITE	PUBLIC ACQUISITION	ACCESSIBLE	<input type="checkbox"/> EDUCATIONAL
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input checked="" type="checkbox"/> YES: RESTRICTED	<input type="checkbox"/> ENTERTAINMENT
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> GOVERNMENT
		<input type="checkbox"/> NO	<input type="checkbox"/> INDUSTRIAL
			<input type="checkbox"/> MILITARY
			<input type="checkbox"/> PARK
			<input type="checkbox"/> PRIVATE RESIDENCE
			<input type="checkbox"/> RELIGIOUS
			<input type="checkbox"/> SCIENTIFIC
			<input type="checkbox"/> TRANSPORTATION
			<input type="checkbox"/> OTHER:

4 OWNER OF PROPERTY

NAME

Department of Natural Resources

Telephone #:

STREET & NUMBER

Taves State Office Building

CITY, TOWN

Annapolis,

___ VICINITY OF

Maryland

STATE, zip code
21404

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,

REGISTRY OF DEEDS, ETC.

Clerk of the Circuit Court

Liber #: WAS 347

Folio #: 415

STREET & NUMBER

Cecil County Courthouse

CITY, TOWN

Elkton

STATE
Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

___ FEDERAL ___ STATE ___ COUNTY ___ LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

CONDITION

- EXCELLENT
- GOOD
- FAIR
- DETERIORATED
- RUINS
- UNEXPOSED

CHECK ONE

- UNALTERED
- ALTERED

CHECK ONE

- ORIGINAL SITE
- MOVED DATE _____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The McCleary Farmhouse is a two-storey building built of brick laid in common bond with a flemish bond header row. The house has a gable roof with slate shingles. The rafter ends are hidden by a box cornice and bed moulding. The house had inside end chimneys but they have fallen down. Between the first and second storeys there is a belt course on the north and south walls. The house has a stone foundation and full cellar. The joists for the first storey floor are exposed and show cut nails and circular saw blade marks. The south wall which was probably the facade has a central bay entrance. The house is three bays long by two deep. The rear wall has a side bay entrance which opens onto a rear stair hall with single flight stairs. Both front and rear walls appear to have had single storey porches. The interior has been removed, but the house did have some chairrail. Some of the first storey windows have paneled shutters.

8 SIGNIFICANCE

CE-771

PERIOD

AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW

- | | | | | |
|---|---|---|---|--|
| <input type="checkbox"/> PREHISTORIC | <input type="checkbox"/> ARCHEOLOGY-PREHISTORIC | <input type="checkbox"/> COMMUNITY PLANNING | <input type="checkbox"/> LANDSCAPE ARCHITECTURE | <input type="checkbox"/> RELIGION |
| <input type="checkbox"/> 1400-1499 | <input type="checkbox"/> ARCHEOLOGY-HISTORIC | <input type="checkbox"/> CONSERVATION | <input type="checkbox"/> LAW | <input type="checkbox"/> SCIENCE |
| <input type="checkbox"/> 1500-1599 | <input type="checkbox"/> AGRICULTURE | <input type="checkbox"/> ECONOMICS | <input type="checkbox"/> LITERATURE | <input type="checkbox"/> SCULPTURE |
| <input type="checkbox"/> 1600-1699 | <input type="checkbox"/> ARCHITECTURE | <input type="checkbox"/> EDUCATION | <input type="checkbox"/> MILITARY | <input type="checkbox"/> SOCIAL/HUMANITARIAN |
| <input type="checkbox"/> 1700-1799 | <input type="checkbox"/> ART | <input type="checkbox"/> ENGINEERING | <input type="checkbox"/> MUSIC | <input type="checkbox"/> THEATER |
| <input checked="" type="checkbox"/> 1800-1899 | <input type="checkbox"/> COMMERCE | <input type="checkbox"/> EXPLORATION/SETTLEMENT | <input type="checkbox"/> PHILOSOPHY | <input type="checkbox"/> TRANSPORTATION |
| <input type="checkbox"/> 1900- | <input type="checkbox"/> COMMUNICATIONS | <input type="checkbox"/> INDUSTRY | <input type="checkbox"/> POLITICS/GOVERNMENT | <input type="checkbox"/> OTHER (SPECIFY) |
| | | <input type="checkbox"/> INVENTION | | |

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The McCleary Farmhouse is an early 19th century structure which is in a semi-ruinous condition. Although unoccupied it is structurally sound and could be preserved.

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE COUNTY

STATE COUNTY

11 FORM PREPARED BY

NAME / TITLE

George W. Lutz III, Field Historian

ORGANIZATION

Cecil County Committee

DATE

July 1, 1977

STREET & NUMBER

RD 2

TELEPHONE

658-6850

CITY OR TOWN

Rising Sun

STATE

Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

DRAFT

CE-771

MEMO

TO: ROSS KIMMEL, State Historian
FROM: Joe Getty, Architectural Surveyor
DATE: April 8, 1984
SUBJECT: Buildings at Fair Hill NRMA

There was some confusion over the sites on my list located within the Fair Hill NRMA. I met with Tom Merryweather and Bill and I believe we resolved the problems on my list. The problematic sites are:

CE-562 McMaster Farm. The survey form contains an incorrect map location. The house and barn were located on the site where the equestrian center is currently being constructed. The buildings were demolished in 1982.

✓ CE-771 McCleary House. This map location is wrong and Tom Merryweather believes that the photograph is of a house that is actually in Pennsylvania. There is only one brick structure north of Route 275 in the Fair Hill NRMA.

Cockerham Property. A two-story, three-bay by two-bay house with an L-shaped plan located at the site inaccurately marked as McMaster Farm. See survey form.

L. M. Peterson Farm. A two-story, three-bay by two-bay house with an L-shaped plan located at the site inaccurately marked as McCleary House. See survey form.

Gann Property. A two-story, five-bay by two-bay stone house with a collapsed west wall that is not located on previous surveys. See survey form.

Memo to Ross Kimmel
Buildings at Fair Hill NRMA

CE-771 2

DNR-50 New Covered Bridge. Tom Merryweather states that this is not nor never was a covered bridge. The inaccurately labeled structure is actually a gatehouse.

cc: McHasta Fam. file
✓ McHenry House file

Lewisville
PENNSYLVANIA MARYLAND
5 MASON AND 4 DIXON
CHESTER CO 3 LINE
CECIL CO

DNR-771 MCCLARY HOUSE
CE-771

BUNTING HOUSE
CE-771

DNR-758 SCHOOL HOUSE
CE-758

DNR-1417 BARN, FEED MILL
CE-758

DNR-28 MCMASTER HOUSE
CE-362

DNR-13 HAY LOFT
CE-300-E

DNR-47 BARN
CE-364-A

DNR-01 FINLEY BARN
CE-301-A

DNR-12 SMOKE HOUSE
CE-300-15

DNR-45 HOUSE
CE-364

DNR-03 CARE TAKERS HOUSE
CE-301

DNR-10 BEERS HOUSE
CE-300

DNR-50 NEW COVERED BRIDGE

DNR-02 FINLEY HSE
CE-301

DNR-11 BEERS BARN
CE-300-A

DNR-03, 93 TRACK STRUCTURES
CE-552

DNR-01 COVERED BRIDGE
CE-238

DNR-103 CLUB
CE-75

DNR-77 HOUSE
CE-544

DNR-90-102 TRACK STRUCTURES
CE-552

DNR-51 HOUSE

DNR-53 STABLES

DNR-56 STONE HOUSE
CE-363

DNR-64 STONE STABLES
CE-366

NEWARK WEST QUAD.

ILL-32

SANT HILL 1.5 MI.
5663 III NW (BAY VIEW)

LITTLE ELK

Providence

Kenmore Sch

Andora

Big Elk Chapel

TYSON HOUSE
CE-527

GAYLEN HOUSE
CE-517

COVERED BRIDGE
SITE CE-516

SCOTT MILL DAM

HOUSE RUINS

SCOTT MILL RUINS
CE-516

Cowe