

CARR - 108

WOODSIDE

1845

932 Stone Chapel Road  
Westminster vicinity

Private

Woodside is a large brick house built by David Englar in 1845. The original house was recorded as being H-shaped, but alterations to the house in the 1880s enlarged it to its present appearance. The outbuildings on this property are also significant with a frame tenant house that predates the brick house and a log smokehouse.



DEPARTMENT OF PLANNING AND DEVELOPMENT  
225. N. Center Street  
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT  
FIELD SHEET--HISTORIC RESOURCES SURVEY

SURVEY NUMBER: CARR-108

NEGATIVE FILE NUMBER:

UTM REFERENCES:  
Zone/Easting/Northing

U.S.G.S. QUAD. MAP: New Windsor

PRESENT FORMAL NAME: Woodside

ORIGINAL FORMAL NAME:

PRESENT USE: Farmhouse

ORIGINAL USE: Farmhouse

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:  
Excellent ( ) Good (X)  
Fair ( ) Poor ( )

THEME:

STYLE:

DATE BUILT: 1845

COUNTY: CARROLL

TOWN: Westminster vic

LOCATION: 932 Stone Chapel Road

COMMON NAME: Woodside

FUNCTIONAL TYPE: Farmhouse

OWNER: Elizabeth T. Finley  
ADDRESS: 932 Stone Chapel Rd  
Westminster Md 21157

ACCESSIBILITY TO PUBLIC:  
Yes ( ) No (X) Restricted ( )

LEVEL OF SIGNIFICANCE:  
Local ( ) State ( ) National ( )

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone (X) Brick ( ) Concrete ( ) Concrete Block ( )
- Wall Structure
  - Wood: Log ( ) Post and Beam ( ) Balloon ( )
  - Wood Bearing Masonry: Brick (X) Stone ( ) Concrete ( ) Concrete Block ( )
  - Iron ( ) D. Steel ( ) E. Other
- Wall Covering: Weatherboard ( ) German Siding ( ) Board and Batten ( )  
Wood Shingle ( ) Shiplap ( ) Novelty ( ) Stucco (X) Sheet Metal ( )  
Aluminum ( ) Asphalt Shingle ( ) Brick Veneer ( ) Stone Veneer ( )  
Bonding Pattern: Other:
- Roof Structure
  - Truss: Wood (X) Iron ( ) Steel ( ) Concrete ( )
  - Other:
- Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle ( ) Sheet Metal (X)  
Built Up ( ) Rolled ( ) Tile ( ) Other:
- Engineering Structure:
- Other:

Appendages: Porches (X) Towers ( ) Cupolas ( ) Dormers ( ) Chimneys ( ) Sheds ( )  
Ells (X) Wings ( ) Other:

Roof Style: Gable (X) Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )  
Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( )  
With False Front ( ) Other:

Number of Stories: 2

Number of Bays: 5 x 2

Approximate Dimensions: \_\_\_\_\_

Entrance Location: center

THREAT TO STRUCTURE:  
No Threat ( ) Zoning ( ) Roads ( )  
Development ( ) Deterioration ( )  
Alteration ( ) Other:

LOCAL ATTITUDES:  
Positive ( ) Negative ( )  
Mixed ( ) Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

CARR-108

brick covered in stucco  
clipped gables  
central hyphen or main facade + gable pediment  
porch with balcony railing



RELATED STRUCTURES: (Describe)

brick summer kitchen

STATEMENT OF SIGNIFICANCE:

prominent Carroll County building from its refined architecture

REFERENCES:

1862 Martenet's Map:

1877 LG & S Atlas:

768/417

n. 45 p. 558

SURROUNDING ENVIRONMENT:

Open Lane ( ) Woodland (X) Scattered Buildings ( )  
Moderately Built Up ( ) Densely-Built Up ( )  
Residential ( ) Commercial ( )  
Agricultural ( ) Industrial ( )  
Roadside Strip Development ( )  
Other:

RECORDED BY:

J. S. Gentry

ORGANIZATION:

Carroll County Planning Dept

DATE RECORDED:

8/83

1. STATE *MD.*  
 COUNTY *CARROLL*  
 TOWN \_\_\_\_\_ VICINITY *Westminster*  
 STREET NO. *E side U.S. 140 approx.*  
*1/2 mi. N. of Westminster*  
 ORIGINAL OWNER \_\_\_\_\_  
 ORIGINAL USE \_\_\_\_\_  
 PRESENT OWNER *THOMPSON*  
 PRESENT USE *dwelling*  
 WALL CONSTRUCTION *brick*  
 NO. OF STORIES *2 - 2 1/2*

HISTORIC AMERICAN BUILDINGS SURVEY  
INVENTORY

2. NAME *THOMPSON FARM*  
 DATE OR PERIOD *mid-19th.*  
 STYLE *Victorian*  
 ARCHITECT \_\_\_\_\_  
 BUILDER \_\_\_\_\_

3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION

OPEN TO PUBLIC

*This rather large and sprawling home appears from the road to be a fairly good (but not outstanding) surviving example of mid and late nineteenth century architecture. The dwelling is situated on the E. side of U.S. 140 and faces W.*

5. PHYSICAL CONDITION OF STRUCTURE

Endangered

Interior

Exterior

*good*



6. LOCATION MAP (Plan Optional)

7. PHOTOGRAPH

8. PUBLISHED SOURCES (Author, Title, Pages)  
INTERVIEWS, RECORDS, PHOTOS, ETC.

9. NAME, ADDRESS AND TITLE OF RECORDER

*J.R. Wouke*

*M+T*

*12/70*

DATE OF RECORD

SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE



U.S.G.S. MAP  
NEW WINDSOR, MD.  
1:24000 SCALE



1. CARR- 108            WOODSIDE
2. Carroll County, Maryland
3. Joe Getty
4. November 1983
5. Md. Historical Trust, Annapolis, Md.
6. East elevation (camera facing west)
7. 1/1