

CARR - 675

LOG HOUSE (SITE)

late 18th or early 19th century

Littlestown Pike  
Westminster vicinity

private

The Log House Site is located on the west side of Littlestown Pike at the intersection with Old Bachman's Valley Road. There is currently a late nineteenth century barn on the property that serves as a Jaycee Reclamation Center. The log house was a two-room structure that was torn down in 1975. The building had a double-tiered front porch that indicates it may have been an early tavern because many taverns had such porches and double entrances such as this log house had. The barn has interesting sawn ornamentation in its ventilator frames.



DEPARTMENT OF PLANNING AND DEVELOPMENT  
225. N. Center Street  
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

n 38 p 516 ? Block 12 113

SURVEY NUMBER: CARR-675

NEGATIVE FILE NUMBER:

UTM REFERENCES:  
Zone/Easting/Northing

U.S.G.S. QUAD. MAP: Westminster

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE:

ORIGINAL USE:

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:  
Excellent ( ) Good ( )  
Fair ( ) Poor ( )

THEME:

STYLE:

DATE BUILT:

COUNTY: CARROLL

TOWN: Westminster vicinity

LOCATION: west side of Littlestown Pike (MD 97) at  
intersection with Old Bachman's Valley Rd

COMMON NAME: LOG HOUSE SITE

FUNCTIONAL TYPE:

OWNER: County Commissioners of Carroll Co.

ADDRESS: 225 N. Center St.  
Westminster, MD 21157

ACCESSIBILITY TO PUBLIC:  
Yes ( ) No ( ) Restricted ( )

LEVEL OF SIGNIFICANCE:  
Local ( ) State ( ) National ( )

GENERAL DESCRIPTION: DEMOLISHED LOG HOUSE - JAYCEE RECLAMATION BARN

Structural System

- Foundation: Stone ( ) Brick ( ) Concrete ( ) Concrete Block ( )
- Wall Structure
  - Wood: Log ( ) Post and Beam ( ) Balloon ( )
  - Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )
  - Iron ( ) D. Steel ( ) E. Other
- Wall Covering: Weatherboard ( ) German Siding ( ) Board and Batten ( )  
Wood Shingle ( ) Shiplap ( ) Novelty ( ) Stucco ( ) Sheet Metal ( )  
Aluminum ( ) Asphalt Shingle ( ) Brick Veneer ( ) Stone Veneer ( )  
Bonding Pattern: Other:
- Roof Structure
  - Truss: Wood ( ) Iron ( ) Steel ( ) Concrete ( )
  - Other:
- Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle ( ) Sheet Metal ( )  
Built Up ( ) Rolled ( ) Tile ( ) Other:
- Engineering Structure:
- Other:

Appendages: Porches ( ) Towers ( ) Cupolas ( ) Dormers ( ) Chimneys ( ) Sheds ( )  
Ells ( ) Wings ( ) Other:

Roof Style: Gable ( ) Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )  
Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( )  
With False Front ( ) Other:

Number of Stories: \_\_\_\_\_

Number of Bays: \_\_\_\_\_ Entrance Location: \_\_\_\_\_

Approximate Dimensions: \_\_\_\_\_

THREAT TO STRUCTURE:  
No Threat ( ) Zoning ( ) Roads ( )  
Development ( ) Deterioration ( )  
Alteration ( ) Other:

LOCAL ATTITUDES:  
Positive ( ) Negative ( )  
Mixed ( ) Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

log house had characteristics of an early town - double tiered porch - double entrance

RELATED STRUCTURES: (Describe)

late nineteenth century bank barn - interesting saw ornamentation on ventilator frame

STATEMENT OF SIGNIFICANCE:

REFERENCES:

1862 Martenet's Map: Henry Baile

1877 LG & S Atlas: Henry Baile

SURROUNDING ENVIRONMENT:

- Open Lane ( ) Woodland ( ) Scattered Buildings ( )
- Moderately Built Up ( ) Densely-Built Up ( )
- Residential ( ) Commercial ( )
- Agricultural ( ) Industrial ( )
- Roadside Strip Development ( )
- Other:

RECORDED BY:

Joe Getty

ORGANIZATION:

DATE RECORDED:

U.S.G.S. MAP  
WESTMINSTER, MD.  
1:24000 SCALE

CARR-675



4386

4385

4384

35'

4383

32

31

4382

4381

TANEYTOWN 11 MI.  
FRIZZELLBURG 3.9 MI.

WESTMINSTER

High Sch

Cem  
Cemetery

Random House  
Park

Crabapple  
Branch

Crabapple  
Station

Reservoir

Crabapple  
Branch

Tanne



1. Log House (site) CARR-675
2. Carroll Co., Md.
3. Joe Getty
4. April 1975
5. Md. Hist. Trust, Annapolis, Md.
6. East & north elevations (camera facing southwest)
7. 1/4

WESTMINSTER JAYCEES  
RECLAMATION CENTER



1. CARR-675 LOG HOUSE SITE
2. Carroll County, Maryland
3. Joe Getty
4. August 1983
5. Md. Historical Trust, Annapolis, Md.
6. Bank barn, north and east elevations,  
camera facing southwest.
7. 2/2



CARR. 675

LOG HOUSE (site)

Littlestown Pike

Westminster vicinity

~~8183~~ March 1975

east elevation

Photo By Joe Getty



CARR-675

- 1 Log House site - barn
- 2 Carroll Co., Md.
- 3 Joe Getty
- 4 8/83
- 5 Md. Hist. Trust  
Annapolis Md.
- 6 window detail
- 7 4/4



CARR. 675

1. LOG HOUSE site BARN
2. Carroll County, Md.
3. Joe Getty
4. Aug. 1983
5. Md. Hist. Trust  
Annapolis Md
6. gable detail
7. 3/4