

CARR - 707

318 WEST MAIN STREET

mid-19th century

Westminster

private

318 West Main Street is representative of mid-to-late nineteenth century farmhouse construction in this region. It is an L-shaped plan structure built into a slope that moves gently away from the front of the house. Other typical characteristics are its two-story height, three-bay by two-bay massing, stone foundation and gable roof. The full-length, one-story front porch has Victorian-style ornamentation in its triangular brackets and stick-style bannister.



DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

5/5

SURVEY NUMBER: CARR-707
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP: New Windsor
PRESENT FORMAL NAME:

COUNTY: CARROLL
TOWN: Westminster
LOCATION: 318 West Main Street (MD 32)
TAX MAP 38 Block 23 P.327
COMMON NAME:
FUNCTIONAL TYPE: residence
OWNER: Joseph N. Shelton PATRICIA ANN TREVORROW
ADDRESS: 318 West Main St 806 YOUNG CT.
Westminster MD 21157
ACCESSIBILITY TO PUBLIC: Yes ( ) No (X) Restricted ( )
LEVEL OF SIGNIFICANCE: Local ( ) State ( ) National ( )

ORIGINAL FORMAL NAME:
PRESENT USE: residence
ORIGINAL USE: residence
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE:
Excellent ( ) Good (X)
Fair ( ) Poor ( )
THEME:
STYLE:
DATE BUILT: mid 19th century

GENERAL DESCRIPTION:
Structural System
1. Foundation: Stone (X) Brick ( ) Concrete ( ) Concrete Block ( )
2. Wall Structure
A. Wood: Log ( ) Post and Beam (X) Balloon ( )
B. Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )
C. Iron ( ) D. Steel ( ) E. Other
3. Wall Covering: Weatherboard ( ) German Siding ( ) Board and Batten ( )
Wood Shingle ( ) Shiplap ( ) Novelty ( ) Stucco ( ) Sheet Metal ( )
Aluminum (X) Asphalt Shingle ( ) Brick Veneer ( ) Stone Veneer ( )
Bonding Pattern: Other:
4. Roof Structure
A. Truss: Wood (X) Iron ( ) Steel ( ) Concrete ( )
B. Other:
5. Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle ( ) Sheet Metal (X)
Built Up ( ) Rolled ( ) Tile ( ) Other:
6. Engineering Structure:
7. Other:
Appendages: Porches (X) Towers ( ) Cupolas ( ) Dormers ( ) Chimneys ( ) Sheds ( )
Ells (X) Wings ( ) Other:
Roof Style: Gable (X) Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )
Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( )
With False Front ( ) Other:
Number of Stories: 2
Number of Bays: 3x2
Approximate Dimensions:
Entrance Location: center

THREAT TO STRUCTURE:
No Threat ( ) Zoning ( ) Roads ( )
Development ( ) Deterioration ( )
Alteration ( ) Other:

LOCAL ATTITUDES:
Positive ( ) Negative ( )
Mixed ( ) Other:

## ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

regional farmhouse type

L-shaped plan

Victorian style ornamentation on porch - triangular brackets

## RELATED STRUCTURES: (Describe)

washhouse - frame 1 story

chicken coop - frame, shed roof

small stable

## STATEMENT OF SIGNIFICANCE:

representative of mid-to-late nineteenth century domestic architecture

## REFERENCES:

1862 Martenet's Map:

1877 LG & S Atlas: D. D. Borsack

## SURROUNDING ENVIRONMENT:

Open Lane ( ) Woodland ( ) Scattered Buildings ( )

Moderately Built Up (X) Densely-Built Up ( )

Residential ( ) Commercial ( )

Agricultural ( ) Industrial ( )

Roadside Strip Development ( )

Other:

## RECORDED BY:

Joe Getty

## ORGANIZATION:

## DATE RECORDED:

8/83

U.S.G.S. MAP  
 NEW WINDSOR, MD.  
 1:24000 SCALE





CARR-707

318 WEST MAIN ST

Westminster

8/83

South elevation

Photo By Joe Getty



CARR-707

1. 318 WEST MAIN ST
2. Westminster Carroll Co. Md
3. J. Getty
4. 8/83
5. Md. Hist. Trust Annapolis Md.
6. southwest elevation
7. 111

Photo By Joe Getty