

CARR - 786

1010 OLD WESTMINSTER PIKE

mid-19th century

Westminster vicinity

private

1010 Old Westminster Pike is a mid-nineteenth century regional style farmhouse that provides an example of ornamental window frames. During the Victorian period, decoration on window frames became popular. The first story windows in this house provide decoration through their arch upper piece. Other characteristics, such as the L-shaped plan with double-tiered porch, symmetrical facade with a full-length porch, and gabled dormer are representative of this period in Carroll County.



DEPARTMENT OF PLANNING AND DEVELOPMENT  
225. N. Center Street  
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

SURVEY NUMBER: CARR-786

NEGATIVE FILE NUMBER:

UTM REFERENCES:  
Zone/Easting/Northing

U.S.G.S. QUAD. MAP: Westminster

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: residence

ORIGINAL USE: residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:  
Excellent ( ) Good ()  
Fair ( ) Poor ( )

THEME:

STYLE:

DATE BUILT: mid-19th c.

COUNTY: CARROLL

TOWN: WESTMINSTER UIC

LOCATION: 1010 Old Westminster Pike  
*box - Ranser bk 2 Uicli*

TAX MAP 46 Block 22 P-764

COMMON NAME:

FUNCTIONAL TYPE: residence

OWNER: Philip Kemper

ADDRESS: 2715 Lodge Forest Dr.  
Baltimore

ACCESSIBILITY TO PUBLIC:  
Yes ( ) No () Restricted ( )

LEVEL OF SIGNIFICANCE:  
Local ( ) State ( ) National ( )

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone () Brick ( ) Concrete ( ) Concrete Block ( )
- Wall Structure
  - Wood: Log ( ) Post and Beam () Balloon ( )
  - Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )
  - Iron ( ) D. Steel ( ) E. Other
- Wall Covering: Weatherboard ( ) German Siding ( ) Board and Batten ( )  
Wood Shingle ( ) Shiplap ( ) Novelty ( ) Stucco ( ) Sheet Metal ( )  
Aluminum () Asphalt Shingle ( ) Brick Veneer ( ) Stone Veneer ( )  
Bonding Pattern: Other:
- Roof Structure
  - Truss: Wood () Iron ( ) Steel ( ) Concrete ( )
  - Other:
- Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle () Sheet Metal ( )  
Built Up ( ) Rolled ( ) Tile ( ) Other:
- Engineering Structure:
- Other:

Appendages: Porches () Towers ( ) Cupolas ( ) Dormers ( ) Chimneys ( ) Sheds ( )  
Ells () Wings ( ) Other:

Roof Style: Gable () Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )  
Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( )  
With False Front ( ) Other:

Number of Stories: 2 1/2

Number of Bays: 5 x 2

Approximate Dimensions: \_\_\_\_\_ Entrance Location: center

THREAT TO STRUCTURE:  
No Threat ( ) Zoning ( ) Roads ( )  
Development ( ) Deterioration ( )  
Alteration ( ) Other:

LOCAL ATTITUDES:  
Positive ( ) Negative ( )  
Mixed ( ) Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

representative regional style  
gabled dormer  
arch wood window frames

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

example of mid-19th century house w/

REFERENCES:

1862 Martenet's Map:  
1877 LG & S Atlas: G. Grabenhorst

SURROUNDING ENVIRONMENT:

Open Lane ( ) Woodland ( ) Scattered Buildings ( )  
Moderately Built Up (X) Densely-Built Up ( )  
Residential ( ) Commercial ( )  
Agricultural ( ) Industrial ( )  
Roadside Strip Development ( )  
Other:


RECORDED BY:

J. Getty

ORGANIZATION:


DATE RECORDED:

8/83



U.S.G.S. MAP  
WESTMINSTER, MD.  
1:24000 SCALE

CARR-786





1. CARR-786 1010 Old Westminster Pike
2. Carroll County, Maryland
3. Joe Getty
4. August 1983
5. Md. Historical Trust, Annapolis, Md.
6. South & east elevations; camera facing northwest
7. 1/1