



DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

SURVEY NUMBER: CARR-1066

NEGATIVE FILE NUMBER:

UTM REFERENCES:
Zone/Easting/Northing

U.S.G.S. QUAD. MAP: Lineboro

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: Apartments

ORIGINAL USE: Barn

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:
Excellent ( ) Good (X)
Fair ( ) Poor ( )

THEME:

STYLE: Vernacular

DATE BUILT: mid-19th c.

COUNTY: CARROLL

TOWN: Lineboro

LOCATION: 4200 Main Street (11086)

COMMON NAME: Frame Bank Barn

FUNCTIONAL TYPE: Barn

OWNER: Earl Kopp
ADDRESS: 4200 Main St
Lineboro Rd 21088

ACCESSIBILITY TO PUBLIC:
Yes ( ) No (X) Restricted ( )

LEVEL OF SIGNIFICANCE:
Local ( ) State ( ) National ( )

GENERAL DESCRIPTION:

Structural System

- 1. Foundation: Stone (X) Brick ( ) Concrete ( ) Concrete Block ( )
2. Wall Structure
A. Wood: Log ( ) Post and Beam (X) Balloon ( )
B. Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )
C. Iron ( ) D. Steel ( ) E. Other
3. Wall Covering: Weatherboard ( ) German Siding ( ) Board and Batten ( )
Wood Shingle ( ) Shiplap ( ) Novelty ( ) Stucco ( ) Sheet Metal ( )
Aluminum (X) Asphalt Shingle ( ) Brick Veneer ( ) Stone Veneer ( )
Bonding Pattern: Other:
4. Roof Structure
A. Truss: Wood (X) Iron ( ) Steel ( ) Concrete ( )
B. Other:
5. Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle (X) Sheet Metal ( )
Built Up ( ) Rolled ( ) Tile ( ) Other:
6. Engineering Structure:
7. Other:

Appendages: Porches ( ) Towers ( ) Cupolas (X) Dormers ( ) Chimneys ( ) Sheds ( )
Ells ( ) Wings ( ) Other:

Roof Style: Gable (X) Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )
Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( )
With False Front ( ) Other:

Number of Stories: 1

Number of Bays: 6x3

Approximate Dimensions:

Entrance Location: sides of structure

THREAT TO STRUCTURE:

No Threat (X) Zoning ( ) Roads ( )
Development ( ) Deterioration ( )
Alteration ( ) Other:

LOCAL ATTITUDES:

Positive (X) Negative ( )
Mixed ( ) Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

rehabbed in 1970s as house

REFERENCES:

- 1862 Martenet's Map:
- 1877 LG & S Atlas:

SURROUNDING ENVIRONMENT:

- Open Lane ( ) Woodland ( ) Scattered Buildings ( )
- Moderately Built Up (X) Densely-Built Up ( )
- Residential ( ) Commercial ( )
- Agricultural ( ) Industrial ( )
- Roadside Strip Development ( )
- Other:

RECORDED BY:


Joe Betty

ORGANIZATION:

C. C. Dept. of Planning

DATE RECORDED:

2/85



LINEBORO, MD. - PA.  
QUADRANGLE  
7.5 minute series



1. CARR-1066
2. Carroll County, Maryland
3. Joe Getty
4. February 1985
5. Md. Historical Trust, Annapolis, Md.
6. east elevation