



DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

SURVEY NUMBER: CARR-1124
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP: Manchester
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: Residence
ORIGINAL USE: Residence
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE:
Excellent ( ) Good ( )
Fair (X) Poor ( )
THEME:
STYLE:
DATE BUILT: late 19th c.

COUNTY: CARROLL
TOWN: MELROSE
LOCATION: 4242 HANOVER PIKE (MD30)
COMMON NAME:
FUNCTIONAL TYPE: Residence
OWNER:
ADDRESS:
ACCESSIBILITY TO PUBLIC:
Yes ( ) No (X) Restricted ( )
LEVEL OF SIGNIFICANCE:
Local ( ) State ( ) National ( )

GENERAL DESCRIPTION:
Structural System
1. Foundation: Stone (X) Brick ( ) Concrete ( ) Concrete Block ( )
2. Wall Structure
A. Wood: Log ( ) Post and Beam ( ) Balloon (X)
B. Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )
C. Iron ( ) D. Steel ( ) E. Other
3. Wall Covering: Weatherboard ( ) German Siding ( ) Board and Batten ( )
Wood Shingle ( ) Shiplap ( ) Novelty ( ) Stucco ( ) Sheet Metal ( )
Aluminum ( ) Asphalt Shingle ( ) Brick Veneer ( ) Stone Veneer ( )
Bonding Pattern: Other: Asbestos Siding
4. Roof Structure
A. Truss: Wood (X) Iron ( ) Steel ( ) Concrete ( )
B. Other:
5. Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle ( ) Sheet Metal (X)
Built Up ( ) Rolled ( ) Tile ( ) Other:
6. Engineering Structure:
7. Other:
Appendages: Porches (X) Towers ( ) Cupolas ( ) Dormers ( ) Chimneys ( ) Sheds ( )
Ells (X) Wings ( ) Other:
Roof Style: Gable (X) Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )
Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( )
With False Front ( ) Other:
Number of Stories: 2
Number of Bays: 3x2
Approximate Dimensions:
Entrance Location: side

THREAT TO STRUCTURE:
No Threat ( ) Zoning ( ) Roads ( )
Development ( ) Deterioration ( )
Alteration (X) Other:

LOCAL ATTITUDES:
Positive ( ) Negative ( )
Mixed ( ) Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

period dentil cornice  
replacement windows and doors have altered hist. character

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

REFERENCES:

1862 Martenet's Map:  
1877 LG & S Atlas:

SURROUNDING ENVIRONMENT:

Open Lane ( ) Woodland ( ) Scattered Buildings ( )  
Moderately Built Up ( / ) Densely-Built Up ( )  
Residential ( ) Commercial ( )  
Agricultural ( ) Industrial ( )  
Roadside Strip Development ( )  
Other:

RECORDED BY:


Joe Getty

ORGANIZATION:

C.L. Dept. of Planning

DATE RECORDED:

7/85



690 000 FEET  
(M.D.)

HOKES 2.1 MI.  
GLENVILLE 4.3 MI.

4398

4397

42°30'

4396

LINEBORO 2.4 MI.

4395

(LINEBORO)  
5663 III NE

4394

4393

CARR-1124

MANCHESTER, MD-PA.

QUADRANGLE

7.5 minute series