



DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

SURVEY NUMBER: CARR-1126
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP: Manchester
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: Residence
ORIGINAL USE: Residence
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE:
Excellent () Good ()
Fair (X) Poor ()
THEME:
STYLE:
DATE BUILT: late 19th c.

COUNTY: CARROLL
TOWN: MELROSE
LOCATION: 4248 HANOVER PIKE (MD 30)
COMMON NAME:
FUNCTIONAL TYPE: Residence
OWNER: Estie A Stanel
ADDRESS: 4248 Hanover Pike
Manchester Md 21102 374-2308
ACCESSIBILITY TO PUBLIC:
Yes () No (X) Restricted ()
LEVEL OF SIGNIFICANCE:
Local () State () National ()

GENERAL DESCRIPTION:
Structural System
1. Foundation: Stone (X) Brick () Concrete () Concrete Block ()
2. Wall Structure
A. Wood: Log () Post and Beam () Balloon (X)
B. Wood Bearing Masonry: Brick () Stone () Concrete () Concrete Block ()
C. Iron () D. Steel () E. Other
3. Wall Covering: Weatherboard () German Siding () Board and Batten ()
Wood Shingle () Shiplap () Novelty () Stucco () Sheet Metal ()
Aluminum (X) Asphalt Shingle () Brick Veneer () Stone Veneer ()
Bonding Pattern: Other:
4. Roof Structure
A. Truss: Wood (X) Iron () Steel () Concrete ()
B. Other:
5. Roof Covering: Slate () Wood Shingle () Asphalt Shingle () Sheet Metal (X)
Built Up () Rolled () Tile () Other:
6. Engineering Structure:
7. Other:
Appendages: Porches (X) Towers () Cupolas () Dormers () Chimneys () Sheds ()
Ells (X) Wings () Other:
Roof Style: Gable (X) Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead ()
Saw Tooth () With Monitor () With Bellcast () With Parapet ()
With False Front () Other:
Number of Stories: 2
Number of Bays: 3x2
Approximate Dimensions:
Entrance Location: center

THREAT TO STRUCTURE:
No Threat (X) Zoning () Roads ()
Development () Deterioration ()
Alteration () Other:

LOCAL ATTITUDES:
Positive () Negative ()
Mixed (X) Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

had period cornice that was removed for 1982 aluminum siding job

RELATED STRUCTURES: (Describe)

frame washhouse

STATEMENT OF SIGNIFICANCE:

contributing

REFERENCES:

- 1862 Martenet's Map:
- 1877 LG & S Atlas:

SURROUNDING ENVIRONMENT:

- Open Lane () Woodland () Scattered Buildings ()
- Moderately Built Up (x) Densely-Built Up ()
- Residential () Commercial ()
- Agricultural () Industrial ()
- Roadside Strip Development ()
- Other:

RECORDED BY:


Joe Betty

ORGANIZATION:

C.C. Dept. of Planning

DATE RECORDED:

7/85



690 000 FEET
(MD.)
HOKES 2.1 MI.
GLENNVILLE 4.3 MI.
4398
4397
42'30"
4396
LINEBORO 2.4 MI.
4395
(LINEBORO)
5663 711 NE
4394
4393

CARR-1126

MANCHESTER, MD-PA.

QUADRANGLE

7.5 minute series



1. CARR-1126
2. Carroll County, Maryland
3. Joe Getty
4. July 1985
5. Maryland Historical Trust, Annapolis, Md.
6. East elevation (camera facing west)
7. 1/1