

CARR-1169

VILLAGE STORE

early 20th c.

Detour

private

This site is the tradition location for a store in Detour, but the original building was destroyed in a fire of 1894. The frame section of the existing structure was built as a replacement, but was significantly altered by a storefront remodeling and construction of a concrete block addition in the mid-20th century.



DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

SURVEY NUMBER: CARR-1169

NEGATIVE FILE NUMBER:

UTM REFERENCES:
Zone/Easting/Northing

U.S.G.S. QUAD. MAP: Woodsboro

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: Store

ORIGINAL USE: Store

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent () Good ()
Fair (X) Poor ()

THEME:

STYLE:

DATE BUILT: early 20th c.

COUNTY: CARROLL

TOWN: DETOUR

LOCATION: 7566 Middleburg Road (MD 77)

COMMON NAME: Village Store

FUNCTIONAL TYPE: Store

OWNER: Thomas M. Smith
ADDRESS: 7550 Middleburg Rd
Detour MD 21725

ACCESSIBILITY TO PUBLIC:
Yes () No () Restricted (X)

LEVEL OF SIGNIFICANCE:
Local () State () National ()

GENERAL DESCRIPTION:

Structural System

- 1. Foundation: Stone () Brick () Concrete () Concrete Block (X)
2. Wall Structure
A. Wood: Log () Post and Beam () Balloon ()
B. Wood Bearing Masonry: Brick () Stone () Concrete () Concrete Block (X)
C. Iron () D. Steel () E. Other
3. Wall Covering: Weatherboard () German Siding () Board and Batten ()
Wood Shingle () Shiplap () Novelty () Stucco () Sheet Metal ()
Aluminum () Asphalt Shingle () Brick Veneer () Stone Veneer ()
Bonding Pattern: Other:
4. Roof Structure
A. Truss: Wood (X) Iron () Steel () Concrete ()
B. Other:
5. Roof Covering: Slate () Wood Shingle () Asphalt Shingle () Sheet Metal (X)
Built Up () Rolled () Tile () Other:
6. Engineering Structure:
7. Other:

Appendages: Porches (X) Towers () Cupolas () Dormers () Chimneys () Sheds ()
Ells () Wings () Other:

Roof Style: Gable (X) Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead ()
Saw Tooth () With Monitor () With Bellcast () With Parapet ()
With False Front (X) Other:

Number of Stories: 1

Number of Bays: 4 x 1

Approximate Dimensions:

Entrance Location: center

THREAT TO STRUCTURE:

No Threat (X) Zoning () Roads ()
Development () Deterioration ()
Alteration () Other:

LOCAL ATTITUDES:

Positive () Negative ()
Mixed (X) Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

The original building on this site was destroyed by fire in 1894. A frame gable front store was built as a replacement (the westernmost portion of the existing structure) and a concrete block addition was added in the mid-20 century.

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

non-contributing building due to modern storefront and addition

REFERENCES:

1862 Martenet's Map:
1877 LG & S Atlas:

W.W. Schweigert - buildings at this location burned in 1894

SURROUNDING ENVIRONMENT:

Open Lane () Woodland () Scattered Buildings ()
Moderately Built Up () Densely-Built Up ()
Residential () Commercial ()
Agricultural () Industrial ()
Roadside Strip Development ()
Other:

RECORDED BY:

Joe Getty

ORGANIZATION:


Can. Co. Dept. of Planning

DATE RECORDED:

3/31/86

WOODSBORO QUADRANGLE
MARYLAND
7.5 MINUTE SERIES (TOPOGRAPHIC)

5563 11 NW
(TANEYTOWN)



CARR-1169



1. CARR-1169 VILLAGE STORE
2. Detour, Carroll County, Md.
3. Joe Getty
4. March 1986
5. Md. Hist. Trust, Annapolis, Md
6. South elevation
7. 1/1