

7. Description

Survey No. F-1-143

Condition		Check one	Check one	
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input checked="" type="checkbox"/> original site	
<input checked="" type="checkbox"/> good	<input type="checkbox"/> ruins	<input type="checkbox"/> altered	<input type="checkbox"/> moved	date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed			

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

This farm complex is located at the end of a dirt road leading from the east side of Pleasant View Road, south of Doubs. Due to the slope of the land from west to east, the buildings are almost completely obscured from view from Pleasant View Road. The complex appears to contain a house, barn, and other outbuildings; none of the buildings were observed in detail. The house is gable roofed, 2½ stories high, and has a main block and smaller wing. From a distance, it appears to be stuccoed; the material and method of construction are not known.

8. Significance

Survey No. F-1-143

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates

Builder/Architect

check: Applicable Criteria: A B C D
and/or

Applicable Exception: A B C D E F G

Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.

The B.J. Snouffer Farm, although observed only from a distance, appears to be architecturally significant as a mid-19th century or earlier farm complex. The house may be of special interest; it is composed of a 2½ story main block and lower wing.

The property is shown on the 1873 Lake atlas of Frederick County as that of B.J. Snouffer. The Snouffers were large landowners in the Point of Rocks-Doubs area, and Scharf lists them among the earliest settlers in the area (Vol. I, p. 567).

4353
4352
17°30'
4351
POINT OF ROCKS 2.2 MI
4349
660 FEET
4345

F-1-143
B. J. SNOUFFER
FARM

Pleasant View

Doubs Sch

Tuscarora

Fish Hatchery

Tuscarora

Forest Grove Cb

BALTIMORE AND OHIO RIVER
CANAL
POTOMAC RIVER
Nolands Island
MARYLAND VIRGINIA
660 FEET

