N. R. FIELD SHEET

HA-33

1300334104

Form 10-300
(Dec. 1968)

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES INVENTORY – NOMINATION FORM

*(Type all entries – complete applicable sections)*

| STATE: | |
|---|---|
| COUNTY: | |
| FOR NPS USE ONLY | |
| ENTRY NUMBER | DATE |
| | |

SEE INSTRUCTIONS

## 1. NAME

COMMON: The Campbell Farm house

AND/OR HISTORIC:

## 2. LOCATION

STREET AND NUMBER: house enters south from Federal Hill Road (Md 165) about 0.3 mi west of Md 24.

CITY OR TOWN: Clermont Mills

STATE: Maryland | CODE: | COUNTY: Harford | CODE:

## 3. CLASSIFICATION

| CATEGORY (Check One) | | OWNERSHIP | | STATUS | ACCESSIBLE TO THE PUBLIC |
|---|---|---|---|---|---|
| District ☐ | Building ☑ | Public ☐ | Public Acquisition: | Occupied ☑ | Yes: |
| Site ☐ | Structure ☐ | Private ☑ | In Process ☐ | Unoccupied ☐ | Restricted ☑ |
| Object ☐ | | Both ☐ | Being Considered ☐ | Preservation work in progress ☐ | Unrestricted ☐ |
| | | | | | No: ☐ |

PRESENT USE (Check One or More as Appropriate)

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Agricultural | ☐ | Government | ☐ | Park | ☐ | Transportation | ☐ | Comments | ☐ |
| Commercial | ☐ | Industrial | ☐ | Private Residence | ☑ | Other (Specify) | ☐ | | |
| Educational | ☐ | Military | ☐ | Religious | ☐ | | | | |
| Entertainment | ☐ | Museum | ☐ | Scientific | ☐ | | | | |

## 4. OWNER OF PROPERTY

OWNERS NAME: Mr & Mrs Robert Emmett Campbell

STREET AND NUMBER: Federal Hill Road

CITY OR TOWN: Street | STATE: Maryland | CODE:

## 5. LOCATION OF LEGAL DESCRIPTION

COURTHOUSE, REGISTRY OF DEEDS, ETC: Clerk of the Circuit Court

STREET AND NUMBER: Harford County Courthouse 40 S. Main ST

CITY OR TOWN: Bel Air | STATE: Maryland | CODE:

APPROXIMATE ACREAGE OF NOMINATED PROPERTY:

## 6. REPRESENTATION IN EXISTING SURVEYS

TITLE OF SURVEY:

DATE OF SURVEY: Federal ☐ State ☐ County ☐ Local ☐

DEPOSITORY FOR SURVEY RECORDS:

STREET AND NUMBER:

CITY OR TOWN: | STATE: | CODE:

STATE: | COUNTY: | FOR NPS USE ONLY: ENTRY NUMBER | DATE

Color c 6860

HA-33 N. R. FIELD SHEET

## 7. DESCRIPTION

| | | | | | | |
|---|---|---|---|---|---|---|
| CONDITION | (Check One) Excellent ☐ | Good ☐ | Fair ☐ | Deteriorated ☑ | Ruins ☐ | Unexposed ☐ |
| INTEGRITY | (Check One) Altered ☐ | Unaltered ☑ | | (Check One) Moved ☐ | Original Site ☑ | |

DESCRIBE THE PRESENT AND ORIGINAL *(If known)* PHYSICAL APPEARANCE

SEE INSTRUCTIONS

N. R. FIELD SHEET

HA-33

## 8. SIGNIFICANCE

PERIOD *(Check One or More as Appropriate)*

| | | | |
|---|---|---|---|
| Pre-Columbian ☐ | 16th Century ☐ | 18th Century ☑ | 20th Century ☐ |
| 15th Century ☐ | 17th Century ☐ | 19th Century ☐ | |

SPECIFIC DATE(S) *(If Applicable and Known)*

AREAS OF SIGNIFICANCE *(Check One or More as Appropriate)*

| | | | |
|---|---|---|---|
| Aboriginal | Education ☐ | Political ☐ | Urban Planning ☐ |
| Prehistoric ☐ | Engineering ☐ | Religion/Philosophy ☐ | Other *(Specify)* ☐ |
| Historic ☐ | Industry ☐ | Science ☐ | |
| Agriculture ☐ | Invention ☐ | Sculpture ☐ | Architectural |
| Art ☐ | Landscape Architecture ☐ | Social/Humanitarian ☐ | |
| Commerce ☐ | Literature ☐ | Theater ☐ | |
| Communications ☐ | Military ☐ | Transportation ☐ | |
| Conservation ☐ | Music ☐ | | |

STATEMENT OF SIGNIFICANCE *(Include Personages, Dates, Events, Etc.)*

An independent small farmer has started out on her own here within the year, dairying and truck gardening. The house is in need of a great deal of work, but has not been substantially altered and may yield some good original locks, mantels and other ~~[illegible]~~ evidence of early 18th century materials and methods.

SEE INSTRUCTIONS

## 9. MAJOR BIBLIOGRAPHICAL REFERENCES

## 10. GEOGRAPHICAL DATA

LATITUDE AND LONGITUDE COORDINATES DEFINING A RECTANGLE LOCATING THE PROPERTY

| CORNER | LATITUDE | | | LONGITUDE | | |
|---|---|---|---|---|---|---|
| | Degrees | Minutes | Seconds | Degrees | Minutes | Seconds |
| NW | ° | ' | " | ° | ' | " |
| NE | ° | ' | " | ° | ' | " |
| SE | ° | ' | " | ° | ' | " |
| SW | ° | ' | " | ° | ' | " |

OR

LATITUDE AND LONGITUDE COORDINATES DEFINING THE CENTER POINT OF A PROPERTY OF LESS THAN ONE ACRE

| LATITUDE | | | LONGITUDE | | |
|---|---|---|---|---|---|
| Degrees | Minutes | Seconds | Degrees | Minutes | Seconds |
| ° | ' | " | ° | ' | " |

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

| STATE: | CODE | COUNTY | CODE |
|---|---|---|---|
| | | | |
| STATE: | CODE | COUNTY: | CODE |
| | | | |
| STATE: | CODE | COUNTY: | CODE |
| | | | |
| STATE: | CODE | COUNTY: | CODE |
| | | | |

## 11. FORM PREPARED BY

NAME AND TITLE:

ORGANIZATION | DATE

STREET AND NUMBER:

CITY OR TOWN: | STATE | CODE

## 12. STATE LIAISON OFFICER CERTIFICATION

As the designated State Liaison Officer for the National Historic Preservation Act of 1966 (Public Law 89-665), I hereby nominate this property for inclusion in the National Register and certify that it has been evaluated according to the criteria and procedures set forth by the National Park Service. The recommended level of significance of this nomination is:

National ☐ State ☐ Local ☐

Name _____

Title _____

Date _____

## NATIONAL REGISTER VERIFICATION

I hereby certify that this property is included in the National Register.

_____
*Chief, Office of Archeology and Historic Preservation*

Date _____

ATTEST:

_____
*Keeper of The National Register*

Date _____

SEE INSTRUCTIONS

(7)

This frame and stone house six bays long and one room deep, is under one long A roof. Chimneys are at either end and in the center of the house where the stone wall meets the frame section.

The house faces away from the road to the south across the Deer Creek valley. The ridge line runs east-west.

The stone section, the western half of the house, was once three bays long, but now the door between two windows has been blocked up with stone. Windows in this part of the house are 9 over 6 lights. Three windows are upstairs on the south side of the house, but two remain on the north side of the house, and here another door has been closed up with masonry. Two small gable windows face west from the attic.

The frame part of the house - the eastern half - is three bays long one.

This rugged old house has been continuously lived in but has recieved

(7)

marginal attention over many years, judging from the fact that shutters are gone, window frames eroded under thin paint, stucco is washed off the fieldstone structure, showing at least two colors of ~~[illegible]~~ paint in poor condition.