

**MARYLAND HISTORICAL TRUST
DETERMINATION OF ELIGIBILITY FORM**

Property Name: Herold House Inventory Number: HA-262
 Address: 4114 Flintville Road Historic district: yes no
 City: Darlington Zip Code: 21034 County: Harford
 USGS Quadrangle(s): Conowingo Dam
 Property Owner: HEROLD GEORGE M K TRUSTEE Tax Account ID Number: 1305018455
 Tax Map Parcel Number(s): 34 Tax Map Number: 13
 Project: Herold House Proposed Tower Agency: FCC
 Agency Prepared By: ATC Associates
 Preparer's Name: William Riggs Date Prepared: 5/19/2003
 Documentation is presented in: _____
 Preparer's Eligibility Recommendation: Eligibility recommended Eligibility not recommended
 Criteria: A B C D Considerations: A B C D E F G
Complete if the property is a contributing or non-contributing resource to a NR district/property:
 Name of the District/Property: _____
 Inventory Number: _____ Eligible: yes Listed: yes
 Site visit by MHT Staff yes no Name: _____ Date: _____

Description of Property and Justification: *(Please attach map and photo)*

Although identified on the Maryland SHPO Harford County map as HA-262, no other documentation of the property was found. The property was most recently observed on May 09, 2003. The house is a masonry hybrid two-story residential duplex, with basement. It presents itself with a continuous gable roof, running north-south, clad in slate and modern asphalt composition shingles. The oldest portion of the house appears to date from the mid-nineteenth century. The integrity of the house has been compromised by the addition of modern windows and doors, as well as by an incongruous mixture of building materials. For instance, the southern half of the building is constructed of native field stone, laid randomly. The front (east) elevation of the northern half of the building is faced in modern brick, laid generally in a running bond. Immediately as one turns the northeast corner of the house, however, the brick gives way to weathered cedar shingles. The northern end of the house extends into a two-story gabled ell, terminating in a modern open porch with shed roof that extends across the full extent of the rear of the house. The grade falls away to the rear of the house, allowing walk-out basement entries. A small, relatively modern two-level horse barn is located behind the house. Its lower level is constructed of concrete block, with a wood-framed upper level with a low-slope (roughly 3:12) gable roof with asphalt shingles. The upper level is covered with vertical weathered board siding. The property is not considered eligible for National Register designation under Criterion C because of its general lack of integrity. It is not known to be associated with any historic event, personage, or archaeological significance that would qualify it for registration under

MARYLAND HISTORICAL TRUST REVIEW

Eligibility recommended Eligibility not recommended
 Criteria: A B C D Considerations: A B C D E F G

MHT Comments:

<u>Tania Georgiou Tully</u> Reviewer, Office of Preservation Services	<u>Friday, June 20, 2003</u> Date
<u>Peter Kurtze</u> Reviewer, National Register Program	<u>Friday, June 20, 2003</u> Date

Criteria A, B, or D.

MARYLAND HISTORICAL TRUST REVIEW

Eligibility recommended _____ Eligibility not recommended X

Criteria: A B C D Considerations: A B C D E F G

MHT Comments:

Tania Georgiou Tully
Reviewer, Office of Preservation Services

Friday, June 20, 2003
Date

Peter Kurtze
Reviewer, National Register Program

Friday, June 20, 2003
Date

4114 Flintville Road Darlington, MD 21034

SITE VISIT MAY 9, 2003

PHOTO NOTES

Photo 1

- East front façade
- Building is 2 story plus basement.
- Left side of façade is stone cladding; right side is newer brick in running bond.
- Main gable roof running in north to south direction is slate shingles.
- Brick chimneys protrude main gable at north and south ends.
- Windows are predominantly single hung wood windows in wooden frames. Storm windows are single hung metal.
- Front patio is brick pavers, which appeared deteriorated.

Photo 2

- South and west back façade
- South façade is stone cladding.
- Large brick side chimney.
- Minor gable roof (east-west direction) and shed canopy over back porch are clad with asphalt shingles.
- Steel beam between stone pillar and bearing wall supports wood beams and portion of wood decking.
- Open frame wood steps with metal railings.
- Metal picket railings are around north deck at top of stairs.
- Wood picket railings surround southern portion of deck.
- North deck wall clad in wood shakes. Southern deck wall clad with vertical wood boards.
- Brick pavers under deck and at stair approach.

Photo 3

- North and west back façade
- Wood shakes covers north façade and 2nd floor rear. Wood shakes in need of refurbishing and staining.
- Foundation wall –CMU and stone veneer.

Photo 4


- View showing horse stable (barn) on west side of main building.

Photo 5


- Front view of horse stable.
- Gable roof clad with asphalt shingles.
- Façade is CMU at lower level; vertical wood boards at upper level.
- Wood fence surrounds stable.

Photo 6

- Rear view of horse stable.



HA-262



MN TN
11 1/2°

Map created with TOPO!® ©2002 National Geographic (www.nationalgeographic.com/topo)

SITE VICINITY MAP
 Conowingo Dam, MD PA Quadrangle
 (Dated 1992)
 SCALE: As Shown



Determination of Eligibility
 Herold Property
 4114 Flintville Road
 Darlington, Maryland 21034





HA-262

LEONARD H. ST. JAMES, 11111 1/2 RD,
MARTIN, MISSISSIPPI, 39238
05/13/03

PHOTOS BY CHARLIE WATKINS-COLE 05/04/03
NEAR W. HIGHWAY
22 THE "REAR" ELEVATION

2/13

at:513. R101-02A_003

Photo Gallery: 05/13/03



UNIVERSITY OF TENNESSEE, KNOXVILLE, TN
SAS: H. B. HART, JR., 1954
HA-262
PHOTOGRAPHED BY H. B. HART, JR. 05/13/83
FIELD NO. 1000
P. 1000 (2000) = 1000

HA-262

sta513: R101-03A-004

Photo Gallery, 05/13/83



143000 FOOT 4110 FLINTVILLE RD

HA-262

DARLINGTON HARBOR 33, MD 21034

PHOTO BY: J. L. S. T. - CAR 05/09/83

NEGG W MD 21034

VIEW OF BIRN FROM ELEVATION

5/9

300513, 9101-110-812

Photo Gallery, 05/13/83



HA-262

HEROLD HARB, 412 FLINDERS RD,
DARLING, NSW, HARTSWOOD CO, MOUNTAIN

PHOTO BY CHARLES WELLS-COLE. 25.09.95
NEGS W/MD 440

BARN, SOUTH 40° 23' ELEVATION 115
F/15

atc513. R:01-95A-806

Photo Gallery. 05/13/03



HERON HOUSE, 4147 WILMINGTON RD.

HA-262

DARLINGTON, HARBERT CO., MD 21042

PHOTOS BY CHARLES MENCK-COLE 09.09.03

WEST M. SHPD

272 (NORTH) ELEVATION OF HERON

at-513; R101-00A-009

Photo Gallery: 05/13/03

HA-262
Herold House
Flintville Road
Darlington, Maryland 21034

This structure is located on Flintville Road and faces east toward the Susquehanna River. The house consists of two main units, one of which is rubblestone, the other being frame construction.

This stone and frame house has been drastically renovated and is now being used for apartment dwellings. Its age is difficult to assess, although the frame unit appears to be turn of the century. Neither unit appears on either the Jennings and Herrick Map of 1858 or the Martenet Map of 1878.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

AND/OR COMMON

Herold House

2 LOCATION

STREET & NUMBER

Flintville Road

CITY, TOWN

Darlington

STATE

Maryland

___ VICINITY OF

CONGRESSIONAL DISTRICT

first

COUNTY

Harford

3 CLASSIFICATION

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input type="checkbox"/> PUBLIC	<input checked="" type="checkbox"/> OCCUPIED	<input type="checkbox"/> AGRICULTURE <input type="checkbox"/> MUSEUM
<input checked="" type="checkbox"/> BUILDING(S)	<input checked="" type="checkbox"/> PRIVATE	<input type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL <input type="checkbox"/> PARK
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> PRIVATE RESIDENCE
<input type="checkbox"/> SITE	PUBLIC ACQUISITION	ACCESSIBLE	<input type="checkbox"/> ENTERTAINMENT <input type="checkbox"/> RELIGIOUS
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input checked="" type="checkbox"/> YES: RESTRICTED	<input type="checkbox"/> GOVERNMENT <input type="checkbox"/> SCIENTIFIC
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> INDUSTRIAL <input type="checkbox"/> TRANSPORTATION
		<input type="checkbox"/> NO	<input type="checkbox"/> MILITARY <input type="checkbox"/> OTHER

4 OWNER OF PROPERTY

NAME

Francis X. and Marie K.V. Herold

Telephone #:

STREET & NUMBER

Flintville Road

CITY, TOWN

Darlington

___ VICINITY OF

STATE, zip code

MD 21034

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE, Harford County Courthouse
REGISTRY OF DEEDS, ETC.

Liber #: 622

Folio #: 106

STREET & NUMBER

40 South Main Street

CITY, TOWN

Bel Air

STATE

Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

___ FEDERAL ___ STATE ___ COUNTY ___ LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

41902

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This structure is located on Flintville Road and faces east toward the Susquehanna River. The house consists of two main units, one of which is rubblestone, the other being frame construction.

The stone unit makes up the southern half of this rural apartment building. This unit is two stories high and is three bays by two. It has a gable flank, slate covered roof with a new, corbeled brick chimney located at the south, inside gable end. Windows in this unit are six lights over six. The principle entrance is in the center bay of the east facade. There is a stone addition on the west. This consists of an additional bay, a huge stone chimney and a porch across the west facade.

The frame unit of this house is covered with cedar shake shingles on all but the eastern exposure. This side is faced with a brick facade. The unit is two bays by two. The door and window sashes are replaced. This unit is also two stories high and covered with slate shingles. A new brick chimney is located on the north inside gable end.

A large rubble stone and frame barn is located to the north of the house. The main part of this barn is constructed of vertical board.

The roof is slate. The foundations are rubble stone. In the section to the west, the rubble stone foundations make up the ground floor level. There are four small windows and a door on the south side of the rubble wall.

CONTINUE ON SEPARATE SHEET IF NECESSARY

11-26-92

8 SIGNIFICANCE

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES	BUILDER/ARCHITECT
----------------	-------------------

STATEMENT OF SIGNIFICANCE

This stone and frame house has been drastically renovated and is now being used for apartment dwellings. Its age is difficult to assess, although the frame unit appears to be turn of the century. Neither unit appears on either the Jennings and Herrick Map of 1858 or the Martenet Map of 1878.

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Preston, Walter W.; History of Harford County
Press of the Sun Book Office, Baltimore, 1901.

1814 Maryland Tax List

Wright, C. Milton; Our Harford Heritage, French
Bray Press, Baltimore, 1967.

Jennings and Herrick Map of 1858.

Harford County Directory, 1953.

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY 29.48 acres

VERBAL BOUNDARY DESCRIPTION

This property is bounded by Rt. 623 on the east and Castleton Road on the South.

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE COUNTY

STATE COUNTY

11 FORM PREPARED BY

NAME / TITLE

Susan M. Deeney, Field Historian

ORGANIZATION

Historic District Commission

STREET & NUMBER

45 South Main Street

CITY OR TOWN

Bel Air

DATE

2/78

TELEPHONE

838-6000, ext. 207

STATE

Maryland 21014

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

1302624504
N. R. FIELD SHEET

HA 262

MD. HISTORICAL TRUST
BOX 1704
ANNAPOLIS, MD. 21404

NATIONAL REGISTER OF HISTORIC PLACES
INVENTORY - NOMINATION FORM

(Type all entries - complete applicable sections)

DATE:	
COUNTY:	
FOR NPS USE ONLY	
ENTRY NUMBER	DATE

SEE INSTRUCTIONS

1. NAME

COMMON: Herold house

AND/OR HISTORIC:

2. LOCATION

STREET AND NUMBER: West Side of Md 623, Flintville Road, about 0.2 mi north of Castleton Road

CITY OR TOWN: Darlington RFD

STATE: Maryland CODE: COUNTY: Harford CODE:

3. CLASSIFICATION

CATEGORY (Check One)	OWNERSHIP	STATUS	ACCESSIBLE TO THE PUBLIC
District <input type="checkbox"/> <u>Building</u> <input type="checkbox"/>	Public <input type="checkbox"/>	<u>Occupied</u> <input type="checkbox"/>	Yes: <u>Restricted</u> <input type="checkbox"/>
Site <input type="checkbox"/> Structure <input type="checkbox"/>	<u>Private</u> <input type="checkbox"/>	Unoccupied <input type="checkbox"/>	Unrestricted <input type="checkbox"/>
Object <input type="checkbox"/>	Both <input type="checkbox"/>	Preservation work in progress <input type="checkbox"/>	No: <input type="checkbox"/>
PRESENT USE (Check One or More as Appropriate)			
Agricultural <input type="checkbox"/>	Government <input type="checkbox"/>	Park <input type="checkbox"/>	Transportation <input type="checkbox"/>
Commercial <input type="checkbox"/>	Industrial <input type="checkbox"/>	<u>Private Residence</u> <input type="checkbox"/>	Other (Specify) <input type="checkbox"/>
Educational <input type="checkbox"/>	Military <input type="checkbox"/>	Religious <input type="checkbox"/>	Comments <input type="checkbox"/>
Entertainment <input type="checkbox"/>	Museum <input type="checkbox"/>	Scientific <input type="checkbox"/>	

4. OWNER OF PROPERTY

OWNERS NAME: Francis X & Marie K. V. Herold

STREET AND NUMBER: Flintville Road

CITY OR TOWN: Darlington STATE: Maryland CODE:

5. LOCATION OF LEGAL DESCRIPTION

COURTHOUSE, REGISTRY OF DEEDS, ETC.: **CLERK OF THE CIRCUIT COURT**

STREET AND NUMBER: **HARFORD COUNTY COURTHOUSE 69 S. MAIN ST.**

CITY OR TOWN: **BEL AIR** STATE: **MARYLAND** CODE:

APPROXIMATE ACREAGE OF NOMINATED PROPERTY:

6. REPRESENTATION IN EXISTING SURVEYS

TITLE OF SURVEY:

DATE OF SURVEY: Federal State County Local

DEPOSITORY FOR SURVEY RECORDS:

STREET AND NUMBER:

CITY OR TOWN: STATE: CODE:

STATE:
COUNTY:
ENTRY NUMBER
DATE
FOR NPS USE ONLY

7. DESCRIPTION

CONDITION	(Check One)					
	Excellent <input type="checkbox"/>	Good <input checked="" type="checkbox"/>	Fair <input type="checkbox"/>	Deteriorated <input type="checkbox"/>	Ruins <input type="checkbox"/>	Unexposed <input type="checkbox"/>
INTEGRITY	(Check One)		(Check One)			
	<u>Much</u> Altered <input type="checkbox"/>	Unaltered <input type="checkbox"/>	Moved <input type="checkbox"/>	Original Site <input checked="" type="checkbox"/>		

DESCRIBE THE PRESENT AND ORIGINAL (If known) PHYSICAL APPEARANCE

Stone and frame house, the frame covered with imitation brick asphalt siding. The granite masonry end, (south) is ~~three~~ bays x two, the frame 2 bays x 1. Huge new chimney on the south end of the house ^{almost} rises straight, seeming huge at the top. Two chimneys at the gable ends small.

SEE INSTRUCTIONS

B. SIGNIFICANCE

PERIOD (Check One or More as Appropriate)

- Pre-Columbian 16th Century 18th Century 20th Century
 15th Century 17th Century 19th Century

SPECIFIC DATE(S) (If Applicable and Known)

AREAS OF SIGNIFICANCE (Check One or More as Appropriate)

- | | | | |
|---|---------------------------------------|---|--|
| Aboriginal | Education | Political | Urban Planning |
| Prehistoric <input type="checkbox"/> | Engineering <input type="checkbox"/> | Religion/Phi- | Other (Specify) <input type="checkbox"/> |
| Historic <input type="checkbox"/> | Industry <input type="checkbox"/> | losophy <input type="checkbox"/> | _____ |
| Agriculture <input type="checkbox"/> | Invention <input type="checkbox"/> | Science <input type="checkbox"/> | _____ |
| Art <input type="checkbox"/> | Landscape <input type="checkbox"/> | Sculpture <input type="checkbox"/> | _____ |
| Commerce <input type="checkbox"/> | Architecture <input type="checkbox"/> | Sociol/Humon- | _____ |
| Communications <input type="checkbox"/> | Literature <input type="checkbox"/> | itorian <input type="checkbox"/> | _____ |
| Conservation <input type="checkbox"/> | Military <input type="checkbox"/> | Theater <input type="checkbox"/> | _____ |
| | Music <input type="checkbox"/> | Transportation <input type="checkbox"/> | _____ |

STATEMENT OF SIGNIFICANCE (Include Personages, Dates, Events, Etc.)

This farmhouse is ~~not~~ vigorously altered by suburbanites who seek the rustic life.

SEE INSTRUCTIONS

9. MAJOR BIBLIOGRAPHICAL REFERENCES

(Not on Martenet's map of 1878)

10. GEOGRAPHICAL DATA

LATITUDE AND LONGITUDE COORDINATES DEFINING A RECTANGLE LOCATING THE PROPERTY			O R	LATITUDE AND LONGITUDE COORDINATES DEFINING THE CENTER POINT OF A PROPERTY OF LESS THAN ONE ACRE		
CORNER	LATITUDE	LONGITUDE		LATITUDE	LONGITUDE	
	Degrees Minutes Seconds	Degrees Minutes Seconds		Degrees Minutes Seconds	Degrees Minutes Seconds	
NW	° ' "	° ' "		° ' "	° ' "	
NE	° ' "	° ' "		° ' "	° ' "	
SE	° ' "	° ' "		° ' "	° ' "	
SW	° ' "	° ' "		° ' "	° ' "	

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE:	CODE	COUNTY	CODE

11. FORM PREPARED BY

NAME AND TITLE: **JEAN S. EWING**

ORGANIZATION: **MARYLAND HISTORICAL TRUST** DATE: _____

STREET AND NUMBER: **NO STATE CIRCLE**

CITY OR TOWN: **ANNAPOLIS** STATE: **MARYLAND** CODE: _____

12. STATE LIAISON OFFICER CERTIFICATION

NATIONAL REGISTER VERIFICATION

As the designated State Liaison Officer for the National Historic Preservation Act of 1966 (Public Law 89-665), I hereby nominate this property for inclusion in the National Register and certify that it has been evaluated according to the criteria and procedures set forth by the National Park Service. The recommended level of significance of this nomination is:

National State Local

Name _____

Title _____

Date _____

I hereby certify that this property is included in the National Register.

Chief, Office of Archeology and Historic Preservation

Date _____

ATTEST:

Keeper of The National Register


Date _____

SEE INSTRUCTIONS

Title Search
HA- 262

Francis X. Herold

	622	106	7/1/1963	Grantor: J. Glasgow Archer, Jr., Executor Grantee: Francis X. Herold and Marie Kojub Vaters Herold, his wife Acreage: 29.48 acres
GCB	299	266	9/10/1946	Grantor: Charles G. Brooks and Belle M. Brooks, his wife Grantee: Olivia A. Browning Acreage: Including buildings
GCB	273	487	9/5/1946	Grantor: Oriel Mattingly Grantee: Charles G. Brooks and Belle M., his wife Acreage: Including buildings
GCB	273	335	6/30/1942	Grantor: John L. G. Lee, Assignee Grantee: Joe C. Mast Acreage: 28 acres
GCB	273	487	8/7/1942	Grantor: Joe C. Mast and wife, et al Grantee: Charles G. and Belle M. Brooks, his wife
JAR	158	193	12/8/1917	Grantor: James L. Randow and Amanda A. Randow, his wife Grantee: James F. Creggor
GCB	273	335	6/30/1942	Grantor: John L.G. Lee, Assignee of mortgage Grantee: Joe C. Mast Acreage: Buildings
JAR	147	13	12/1/1914	Grantor: J. Martin McNabb and Charles H. McNabb, trustees Grantee: James L. Randow and Amanda A. Randow Acreage: Buildings
JAR	142	60	6/2/1913	Grantor: Maud M. Tobias Grantee: Charles M. Browning Acreage: 28 acres more or less
WSR	10	195	4/13/1885	Grantor: Last Will and Testament of Samuel G. Ramsey, deceased Grantee: Maud M. Tobias
ALJ	40	115	9/23/1879	Grantor: George L. VanBibber and Stevenson A. Williams, trustees Grantee: Christian Randow Acreage: 28 acres more or less



HA-262

Conowingo Dam Quadrangle
 7.5 Minute Series
 U. S. Geological Survey



Herold House HA-262
Darlington, MD 21034
Susan M. Deeney
February, 1978
East



Herold House HA-262
Darlington, MD 21034
Susan M. Deeney
February, 1978
South



Herold's Barn HA-262
Darlington, MD 21034
Susan M. Deeney
February, 1978
East



HA 262

JSE April 70

(stone & frame)