

HA-286  
Woodlawn  
3214 Harmony Church Road  
Darlington, Maryland 21034

This el-shaped brick house is located off Harmony Church Road near Nobles Mill Road. The house faces south.

The two story home is built onto stone foundations. A beveled frame addition is located at the north end of the el. The principle facade of this dwelling, on the south, is laid on Flemish bond brick. Other facades are of common bond. Chipping white paint is present on some areas of the brick walls.

The roof of this house has slate shingles. The gable flank roof is hipped on the east end where the el begins. Three chimneys are located on the west inside gable end, the center of the hip on the east, and on the north gable end of the el. Chimneys are corbeled brick.

Although land records are quite complete for this property, it can not, with any certainty, be stated at which time the house standing on this property was constructed.

Woodlawn's measurements do not match with measurements given for Joshua Husband's holdings in 1798, nor does it match anything listed under Mary or Rachel Husband. The 1814 Tax Assessment lists Joshua Husband as owning 75 acres of Bachelor's Good Luck and Henley's Enlargement, upon which is a "brick dwelling house and kitchen." It measures only 18' x 27", however, which corresponds to the kitchen part of this house only.

Although the exact age of this home can not be ascertained, the house is architecturally significant. It is a brick house in a sea of stone dwellings and its classic Federal details are virtually unchanged.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

**1 NAME**

HISTORIC Woodlawn

AND/OR COMMON

**2 LOCATION**

STREET & NUMBER

3214 Harmony Church Road

CITY, TOWN

Darlington

— VICINITY OF

CONGRESSIONAL DISTRICT

first

STATE

Maryland

COUNTY

Harford

**3 CLASSIFICATION**

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input type="checkbox"/> PUBLIC	<input checked="" type="checkbox"/> OCCUPIED	<input checked="" type="checkbox"/> AGRICULTURE
<input checked="" type="checkbox"/> BUILDING(S)	<input checked="" type="checkbox"/> PRIVATE	<input type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input checked="" type="checkbox"/> PARK
<input type="checkbox"/> SITE	<b>PUBLIC ACQUISITION</b>	<b>ACCESSIBLE</b>	<input type="checkbox"/> EDUCATIONAL
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input type="checkbox"/> YES: RESTRICTED	<input type="checkbox"/> ENTERTAINMENT
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> GOVERNMENT
		<input type="checkbox"/> NO	<input type="checkbox"/> INDUSTRIAL
			<input type="checkbox"/> MILITARY
			<input type="checkbox"/> MUSEUM
			<input type="checkbox"/> PRIVATE RESIDENCE
			<input type="checkbox"/> RELIGIOUS
			<input type="checkbox"/> SCIENTIFIC
			<input type="checkbox"/> TRANSPORTATION
			<input type="checkbox"/> OTHER

**4 OWNER OF PROPERTY**

NAME

Mr. and Mrs. Monroe Duke

Telephone #: 734-6155

STREET & NUMBER

3214 Harmony Church Road

CITY, TOWN

Darlington

— VICINITY OF

STATE, zip code

MD 21034

**5 LOCATION OF LEGAL DESCRIPTION**

COURTHOUSE, Harford County Courthouse  
REGISTRY OF DEEDS, ETC.

Liber #: 473

Folio #: 541

STREET & NUMBER

40 South Main Street

CITY, TOWN

Bel Air

STATE

Maryland

**6 REPRESENTATION IN EXISTING SURVEYS**

TITLE

DATE

— FEDERAL — STATE — COUNTY — LOCAL

DEPOSITORY FOR  
SURVEY RECORDS

CITY, TOWN

STATE

## 7 DESCRIPTION

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input checked="" type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input checked="" type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

---

### DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This el-shaped brick house is located off Harmony Church Road near Nobles Mill Road. The house faces south.

The two story home is built onto stone foundations. A beveled frame addition is located at the north end of the el. The principle facade of this dwelling, on the south, is laid on Flemish bond brick. Other facades are of common bond. Chipping white paint is present on some areas of the brick walls.

The roof of this house has slate shingles. The gable flank roof is hipped on the east end where the el begins. Three chimneys are located on the west inside gable end, the center of the hip on the east, and on the north gable end of the el. Chimneys are corbeled brick.

The principle facade is four bays long while the el is five bays. Each is two bays wide. Windows on the first elevation are six lights over nine. On the second elevation they are six lights over six. Louvered shutters are at most windows. The main entrance is located in the second bay of the south facade. The double hung doors are of diagonal, beaded board. A lattice work transom is overhead. This forms a through hall and the corresponding door on the north facade is a very wide six panel door. A one bay entrance porch on the south shields the main entrance, while another porch, running the length of the el's west facade shields the north entrance to the through hall.

Another entrance is located on the east facade. This door leads to the kitchen and it has a three light transom.

The frame unit is two bays by one and two stories high. It also has a slate roof. Windows are six lights over six. The outside entrance to this unit is on the east facade. A porch shields this entrance.

Inside, the brick unit of this house is divided into four rooms on the first elevation. West of the through hall is a large sitting room. There are chair rails and a fireplace on the west wall has a shouldered architrave and fluted end blocks. The hallway also has chair rails as does every other room on the first level of the brick unit. The stairway is located on the northwest. It has half-rails on the west wall. Balusters are plain. There are simple brackets on the open string stair. The newel post is small and rounded.

The rooms to the east of through hall share a chimney. Both rooms have a fireplace. It is thought that the mantles are not original. One mantle is quite plain (in the east room) while the northeast room has a fireplace with moulded end blocks, pilasters and some ovolo trim.

North of this is the kitchen which originally had a large cooking fireplace. This was closed up in the past twenty years.

There is a cellar under the brick unit. It is lighted and has a concrete floor. Fireplace supports are present.

CONTINUE ON SEPARATE SHEET IF NECESSARY

# 8 SIGNIFICANCE

5/1/81

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input checked="" type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

Although land records are quite complete for this property, it can not, with any certainty, be stated at which time the house standing on this property was constructed.

Similarly planned structures are found in the historic home of John Stump and Hannah Husband - Perry Point, directly across from Havre de Grace and the Point Concord Lighthouse, in Cecil County, and John Carter's stone house in Harford's Susquehanna State Park. (HA-194). Though construction materials are different, all three homes have a similar appearance, and Woodlawn and the Carter house have the same measurements (excluding Woodlawn's frame addition). This becomes even more intriguing when one discovers that all three houses share a relationship with the Stump family.

Perry Point, believed to have been built prior to 1776, was purchased by a John Stump in 1800, and he lived there with his wife, Hanna Husband. The Carter house in Susquehanna State Park bears a date stone of 1804 and was built by or for John Carter, a partner of John Stump, who also owned one-half interest in the property. Also to be mentioned in the fact that Hannah Husband's family owned Woodlawn from 1764 until approximately 1800.

Woodlawn's measurements do not match with measurements given for Joshua Husband's holdings in 1798, nor does it match anything listed under Mary or Rachel Husband. The 1814 Tax Assessment lists Joshua Husband as owning 75 acres of Bachelor's Good Luck and Henley's Enlargement, upon which is a "brick dwelling house and kitchen." It measures only 18' x 27", however, which corresponds to the kitchen part of this house only.

Although the exact age of this home can not be ascertained, the house is architecturally significant. It is a brick house in a sea of stone dwellings and its classic Federal details are virtually unchanged.

CONTINUE ON SEPARATE SHEET IF NECESSARY

NA-176

**9 MAJOR BIBLIOGRAPHICAL REFERENCES**

1783 Maryland Tax List  
 1798 Federal Tax List  
 1814 Maryland Tax List

Preston, Walter W; History of Harford County Press of the Sun Book Office, Baltimore, 1901.

Earle, Swepson; Maryland's Colonial Eastern Shore, Baltimore, MD, 1916.  
 Wright, C. Milton; Our Harford Heritage, French Bray Press, Baltimore, 1967/

CONTINUE ON SEPARATE SHEET IF NECESSARY

**10 GEOGRAPHICAL DATA**

ACREAGE OF NOMINATED PROPERTY approx. 12.2 acres

**VERBAL BOUNDARY DESCRIPTION**

This property is bounded by Deer Creek on the north; the property of John Douglas on the east; and Harmony Church Road on the South.

**LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES**

STATE	COUNTY
STATE	COUNTY

**11 FORM PREPARED BY**

NAME / TITLE	
Susan M. Deeney, Field Historian	DATE
ORGANIZATION	1/78
Historic District Commission	TELEPHONE
STREET & NUMBER	838-6000, ext.207
45 South Main Street	STATE
CITY OR TOWN	Maryland
Bel Air	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust  
The Shaw House, 21 State Circle  
Annapolis, Maryland 21401  
(301) 267-1438

Title Search  
HA-286

	473	541	12/13/1956	Grantor: Virginia Kemp Jackson Grantee: Monroe I. Duke and Olga Duke, his wife
GCB	290	320	8/24/1945	Grantor: Hugh J. Jewett, et al Grantee: Virginia Kemp Jackson
GCB	255	284	3/31/1939	Grantor: Anne Jewett Grantee: Hugh J. Jewett, 3rd, Natalie J. Marbury, Anne Ingraham Jewett
SVC	251	200	4/16/1938	Grantor: Anne I. Jewett, widow Grantee: Hugh Judge Jewett, 3 rd Natalie J. Marbury and Anne Ingraham Jewett Acreage: Including buildings
CSW	17	312	1/2/1926	Grantor: Last Will and Testament of Hugh J. Jewett, Jr. Grantee: To my wife Anne I. Jewett all of my property and estate.
ALJ	68	136	7/17/1890	Grantor: Joseph T.C. Hopkins, trustee Grantee: Hugh J. Jewett
ALJ	68	136	7/17/1890	Grantor: J. Thomas C. Hopkins Grantee: Hugh J. Jewett Acreage: 122 $\frac{1}{4}$ acres
ALJ	44	400	4/6/1882	Grantor: Rachel Wilson, trustee Grantee: William Hopkins Acreage: Including buildings
HD	18	158	2/5/1861	Grantor: Rachel Wilson Grantee: Cassandra Wilson
HD	V	442	1809	Boundary Request John Quarles, Isaac Maulsby, John Archer, Jr. and Reuben Stump surveyed the property of Joshua Husband
JLG	P	673	12/25/1801	Grantor: John Wilson, Charles Lee Grantee: Joshua Husband Acreage: "Bachelor's Good Luck"
JLG	N	508	6/24/1797	Grantor: Mary Husband, et al Grantee: Rachel Husband

JLG	N	515	6/24/1797	Acreage: "Bachelor's Good Luck"	
				Grantor: Rachel Husband, et al	
				Grantee: Mary Husband	
				Acreage: "Bachelor's Good Luck"	
B	No.Q	403	1768		Joseph Husband's deed to 352 acres of Bachelor's Good Luck
B	No.G	135	1764	Grantor: James Crawford	
				Grantee: Thomas Husband	
B	No.N	356			50 acres of Bachelor's Good Luck
D.O.	5	519	1703		Enoch Spinks' Patent

N. R. FIELD SHEET  
1302864504

HT 0286

MD. HISTORICAL TRUST  
BOX 1704  
ANNAPOLIS, MD. 21404

NATIONAL REGISTER OF HISTORIC PLACES  
INVENTORY - NOMINATION FORM

(Type all entries - complete applicable sections)

STATE:	
COUNTY:	
FOR NPS USE ONLY	
ENTRY NUMBER	DATE

**1. NAME**

COMMON: Duke - Jewett house

AND/OR HISTORIC:  

**2. LOCATION**

STREET AND NUMBER: Home entrance north of Harmony Church Road about

CITY OR TOWN: Darlington (Calverville) 0.1 mi east of Noble's Mill Rd.

STATE: Maryland CODE:   COUNTY: Harford CODE:  

**3. CLASSIFICATION**

CATEGORY (Check One)	OWNERSHIP	STATUS	ACCESSIBLE TO THE PUBLIC
District <input type="checkbox"/> Building <input checked="" type="checkbox"/>	Public <input type="checkbox"/>	Public Acquisition: <input type="checkbox"/> Occupied <input checked="" type="checkbox"/>	Yes: <input type="checkbox"/> Restricted <input checked="" type="checkbox"/>
Site <input type="checkbox"/> Structure <input checked="" type="checkbox"/>	Private <input checked="" type="checkbox"/>	In Process <input type="checkbox"/>	Unoccupied <input type="checkbox"/>
Object <input type="checkbox"/>	Both <input type="checkbox"/>	Being Considered <input type="checkbox"/>	Preservation work in progress <input type="checkbox"/>
No: <input type="checkbox"/>			

PRESENT USE (Check One or More as Appropriate)

Agricultural <input type="checkbox"/>	Government <input type="checkbox"/>	Park <input type="checkbox"/>	Transportation <input type="checkbox"/>	Comments <input type="checkbox"/>
Commercial <input type="checkbox"/>	Industrial <input type="checkbox"/>	Private Residence <input checked="" type="checkbox"/>	Other (Specify) <input type="checkbox"/>	
Educational <input type="checkbox"/>	Military <input type="checkbox"/>	Religious <input type="checkbox"/>		
Entertainment <input type="checkbox"/>	Museum <input type="checkbox"/>	Scientific <input type="checkbox"/>		

**4. OWNER OF PROPERTY**

OWNERS NAME: C. Monroe & Olga Duke

STREET AND NUMBER: Harmony Church Road

CITY OR TOWN: Darlington STATE: MD CODE:  

**5. LOCATION OF LEGAL DESCRIPTION**

COURTHOUSE, REGISTRY OF DEEDS, ETC.: CLERK OF THE CIRCUIT COURT

STREET AND NUMBER: HARFORD COUNTY COURTHOUSE 40 S. MAIN ST.

CITY OR TOWN: BEL AIR STATE: MARYLAND CODE:  

APPROXIMATE ACREAGE OF NOMINATED PROPERTY:  

**6. REPRESENTATION IN EXISTING SURVEYS**

TITLE OF SURVEY:  

DATE OF SURVEY:   Federal  State  County  Local

DEPOSITORY FOR SURVEY RECORDS:  

STREET AND NUMBER:  

CITY OR TOWN:   STATE:   CODE:  

SEE INSTRUCTIONS

STATE:    
COUNTY:    
ENTRY NUMBER:    
DATE:    
FOR NPS USE ONLY

## 7. DESCRIPTION

CONDITION	(Check One)					
	<input checked="" type="checkbox"/> Excellent	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Deteriorated	<input type="checkbox"/> Ruins	<input type="checkbox"/> Unexposed
INTEGRITY	(Check One)		(Check One)			
	<input type="checkbox"/> Altered	<input checked="" type="checkbox"/> Unaltered	<input type="checkbox"/> Moved	<input checked="" type="checkbox"/> Original Site		

DESCRIBE THE PRESENT AND ORIGINAL (if known) PHYSICAL APPEARANCE

Brick, L shaped, 2-story, this house faces east, 5 bays x 2, with a wing running back from the south end ~~to the~~ <sup>wall</sup> ~~to the~~ adding 2 bays by 2.

The A-roof was treated as a hip-roof at the corner. 3 chimneys are spaced at ~~each end of~~ ~~each end~~ walls and near the centre of the turn. The roof is slate.

If the house was built in 2 ages they were probably about the same time, since there is unity in scale, material and style.

There is a wooden addition to the north end, 2 stories.

There is a simple porch on the west wall, one story.

SEE INSTRUCTIONS

8. SIGNIFICANCE

PERIOD (Check One or More as Appropriate)

- Pre-Columbian  16th Century  18th Century  20th Century   
 15th Century  17th Century  19th Century

SPECIFIC DATE(S) (If Applicable and Known)

AREAS OF SIGNIFICANCE (Check One or More as Appropriate)

- |   |                                       |   |  |
|---|---------------------------------------|---|--|
| Aboriginal                              | Education                             | Political                               | Urban Planning                           |
| Prehistoric <input type="checkbox"/>    | Engineering <input type="checkbox"/>  | Religion/Phi-                           | Other (Specify) <input type="checkbox"/> |
| Historic <input type="checkbox"/>       | Industry <input type="checkbox"/>     | losophy <input type="checkbox"/>        | <u>Architectural</u>                     |
| Agriculture <input type="checkbox"/>    | Invention <input type="checkbox"/>    | Science <input type="checkbox"/>        | _____                                    |
| Art <input type="checkbox"/>            | Landscape <input type="checkbox"/>    | Sculpture <input type="checkbox"/>      | _____                                    |
| Commerce <input type="checkbox"/>       | Architecture <input type="checkbox"/> | Social/Humon-                           | _____                                    |
| Communications <input type="checkbox"/> | Literature <input type="checkbox"/>   | itorian <input type="checkbox"/>        | _____                                    |
| Conservation <input type="checkbox"/>   | Military <input type="checkbox"/>     | Theater <input type="checkbox"/>        | _____                                    |
|   | Music <input type="checkbox"/>        | Transportation <input type="checkbox"/> | _____                                    |

STATEMENT OF SIGNIFICANCE (Include Personages, Dates, Events, Etc.)

The second generation of Sewtts lived in his ~~developed~~ ~~break~~ house in the summer. Built about 1858-60 by George Sewtts (whose father owned HA 287, son HA 288), Baltimore industrialist.

Once the club house for the Elkridge Hunt Club, before they joined the Harford Hunt in the 1930s, this has been the residence of a Martin Aircraft executive since about 1942.

SEE INSTRUCTIONS

9. MAJOR BIBLIOGRAPHICAL REFERENCES

*(This section is currently blank, containing only a diagonal line.)*

10. GEOGRAPHICAL DATA

LATITUDE AND LONGITUDE COORDINATES DEFINING A RECTANGLE LOCATING THE PROPERTY			O R	LATITUDE AND LONGITUDE COORDINATES DEFINING THE CENTER POINT OF A PROPERTY OF LESS THAN ONE ACRE		
CORNER	LATITUDE	LONGITUDE		LATITUDE	LONGITUDE	
	Degrees Minutes Seconds	Degrees Minutes Seconds		Degrees Minutes Seconds	Degrees Minutes Seconds	
NW	° ' "	° ' "		° ' "	° ' "	
NE	° ' "	° ' "		° ' "	° ' "	
SE	° ' "	° ' "		° ' "	° ' "	
SW	° ' "	° ' "		° ' "	° ' "	

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE:	CODE	COUNTY	CODE

11. FORM PREPARED BY

NAME AND TITLE: **JEAN S. EWING**

ORGANIZATION: **MARYLAND HISTORICAL TRUST** DATE: \_\_\_\_\_

STREET AND NUMBER: **50 STATE CIRCLE**

CITY OR TOWN: **ANNAPOLIS** STATE: **MARYLAND** CODE: \_\_\_\_\_

12. STATE LIAISON OFFICER CERTIFICATION

As the designated State Liaison Officer for the National Historic Preservation Act of 1966 (Public Law 89-665), I hereby nominate this property for inclusion in the National Register and certify that it has been evaluated according to the criteria and procedures set forth by the National Park Service. The recommended level of significance of this nomination is:

National  State  Local

Name \_\_\_\_\_

Title \_\_\_\_\_

Date \_\_\_\_\_

NATIONAL REGISTER VERIFICATION

I hereby certify that this property is included in the National Register.

\_\_\_\_\_  
*Chief, Office of Archeology and Historic Preservation*

Date \_\_\_\_\_

ATTEST:

\_\_\_\_\_  
*Keeper of The National Register*

Date \_\_\_\_\_

SEE INSTRUCTIONS

INVENTORY NO. HA-286

ELECTION DISTRICT \_\_\_\_\_

DATE: \_\_\_\_\_

TAX MAP NO. \_\_\_\_\_

REMODELING: Drastic, moderate, minor

PARCEL NO. \_\_\_\_\_

NAME OF PROPERTY: Wood lawn

LOCATION OF PROPERTY: \_\_\_\_\_

DIRECTION DWELLING FACES: EAST

NAME OF OWNER: Mr and Mrs Monroe Duke

ADDRESS: 3214 Harmony Church Road

Darlington, MD - 2,034

STORIES: 1[ ] 2[X] 3[ ] 4[ ] 5[ ] 6[ ] BAYS:

WINGS, ADDITIONS:

FRONT - 4 BAYS x 2  
EL - 5 BAYS in FRONT

FRAME ADDITION  
stone  
Found. 2 bay x 1  
6/6

WALL CONSTRUCTION:

✓ HEADER STRETCHER - HEADER  
STRETCHER - HEAD - STRETCHER

- [ ] FRAME: Bevel, clapboard, weatherboard, wood shingles, board & batten (type?)
- [X] BRICK: Bond type- common, English, Flemish. Sketch variants. w/ FINKING WHITE PAINT
- [ ] STONE: Bond type- rubble, ashlar (random or regular), quoins-plain, rusticated
- [ ] LOG

WALL FEATURES: BELT COURSE, PILASTERS, OTHERS

FOUNDATIONS: HIGH, LOW, BRICK, STONE

WATER TABLE: NONE, PLAIN, BEVELED, MOULDED BRICK



WINDOWS, TRIM, SHUTTERS: <sup>lowered</sup> 1/1[ ] 2/2[ ] 6/6[ ] 9/6[ ] 9/9[ ] other[ ] 6/9 FIRST FLOOR  
pegged[ ] nailed[ ] wide[ ] narrow[ ]  
original[ ] replaced[ ] 4/6 2ND

ENTRANCE, DOORS: LOCATION: \_\_\_\_\_

HARDWARE: original[ ] replaced[ ]

FAN LIGHT, TRANSOM, SIDE LIGHTS, PLAIN

CORNICE, BARGE, EAVES:

original[ ] replaced[ ]

✓ ROOF: GABLE FRONT, GABLE FLANK, HIP, MANSARD, FLAT, DORMERS

MATERIAL: wood shingles, slate, tin, asphalt original[ ] replaced[ ]

PORCHES: SHAPE OF ROOF - shed[ ] hip[ ] gable[ ]

✓ CHIMNEYS: NUMBER \_\_\_\_\_ BRICK[X] STONE[ ] CORBELED[X] original[ ] replaced[ ]

LOCATION: END 2ND BAY inside END

ARCHES:

COMMENTS:

CELLAR UNDER BRICK UNIT  
concrete floor  
FP SUPPORTS

COLLAR LIGHTS

OTHER  
BUILDS

SMALL  
BRICK STRUCTURE

Common  
to  
HIC  
SIDES:  
7 Row  
STRETCHER  
to  
HIC  
headers

HA-286

Sept 1858

Hopkins to  
Sister Mathew  
Shelburne/Agan

6/9



OTHER MANTLE VERY PLAIN


OTHER MANTLE  
PILASTER-  
GROG  
MOULDED MANTEL  
BREAST


FIRE PLACE

WEAVER CLOSED OFF KITCHEN  
FP (had been cooked in).  
CHAIR RAILS  
THROUGHOUT

NORTH ↑

Wood lawn HA-286





HA-286  
Woodlawn  
3214 Harmony Church Road  
Harford County Dept. of Planning map  
from aerial photos taken March, 1980



0.5 MI. TO MD. 156

N

384

383

5'

382

381

Aberdeen, MD  
Quadrangle  
7.5 Minute Series  
U.S. Geological  
Survey



Woodlawn

HA-286

Darlington, MD

Susan M. Deeney

January 1978

South



Woodlawn

HA-286

Darlington, MD

Susan M. Deeney

January 1978

Northwest



Woodlawn

HA-286

Darlington, MD

Susan M. Deeney

January 1978

Southwest



Woodlawn HA-286  
Darlington, MD  
Susan M. Deeney  
January 1978  
South