

June

INDIVIDUAL PROPERTY/DISTRICT
MARYLAND HISTORICAL TRUST
INTERNAL NR-ELIGIBILITY REVIEW FORM

Property/District Name: Buckley Farm Survey Number: HO-638

Project: Village of Long Reach Agency: F/COE

Site visit by MHT Staff: no yes Name _____ Date _____

Eligibility recommended _____ Eligibility not recommended

Criteria: A B C D Considerations: A B C D E F G None

Justification for decision: (Use continuation sheet if necessary and attach map)
The Buckley Farm consists of a dwelling and a collection of six outbuildings. Dating from the late nineteenth and early to mid 20th centuries, the complex is located off of Snowden River Parkway and south of Tamar Drive in a developing section of Columbia. The frame dwelling rises 2½ stories, measures three bays wide and is capped by a hipped roof. A cross bled bay (square tower) projects from the center of the building. A colonial revival porch was added to the main facade. A dairy barn, chicken house, corn crib, garage and failed buildings represent the agricultural component. The vernacular complex is in various states of disrepair and deterioration. The complex is a common property type which exists throughout the piedmont. Other examples retain a higher level of integrity. I concurred that the property does not meet the criteria for evaluation.

Documentation on the property/district is presented in: MD Inventory, A Phase 1 Archeological Site Identification Survey of the Village of Long Reach, and later revisions

Prepared by: James Gibb, David Gleason

Lauren L Bowlin 11/4/94
Reviewer, Office of Preservation Services Date

NR program concurrence: yes no not applicable

R. Anderson 15 Nov 94
Reviewer, NR program Date

MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA - HISTORIC CONTEXT

I. Geographic Region:

- Eastern Shore (all Eastern Shore counties, and Cecil)
- Western Shore (Anne Arundel, Calvert, Charles, Prince George's and St. Mary's)
- Piedmont (Baltimore City, Baltimore, Carroll, Frederick, Harford, Howard, Montgomery)
- Western Maryland (Allegany, Garrett and Washington)

II. Chronological/Developmental Periods:

- Paleo-Indian 10000-7500 B.C.
- Early Archaic 7500-6000 B.C.
- Middle Archaic 6000-4000 B.C.
- Late Archaic 4000-2000 B.C.
- Early Woodland 2000-500 B.C.
- Middle Woodland 500 B.C. - A.D. 900
- Late Woodland/Archaic A.D. 900-1600
- Contact and Settlement A.D. 1570-1750
- Rural Agrarian Intensification A.D. 1680-1815
- Agricultural-Industrial Transition A.D. 1815-1870
- Industrial/Urban Dominance A.D. 1870-1930
- Modern Period A.D. 1930-Present
- Unknown Period (prehistoric historic)

III. Prehistoric Period Themes:

- Subsistence
- Settlement
- Political
- Demographic
- Religion
- Technology
- Environmental Adaption

IV. Historic Period Themes:

- Agriculture
- Architecture, Landscape Architecture, and Community Planning
- Economic (Commercial and Industrial)
- Government/Law
- Military
- Religion
- Social/Educational/Cultural
- Transportation

V. Resource Type:

Category: buildings

Historic Environment: rural

Historic Function(s) and Use(s): domestic/residential, agricultural/farm

Known Design Source: _____

Capsule Summary

HO638

Buckley Farm Complex - Principal Dwelling

Columbia Vicinity

Private

Circa 1900

The Buckley Farm Complex Principal Dwelling is a 3-bay, 2 1/2 story frame structure located in Howard County near Dorsey Run. The dwelling has a center hall double pile plan with full front porch and half basement. The exterior of the house has been altered by the addition of asbestos shingles, alterations to the porch, and storm windows and doors and suffers from a lack of maintenance. The interior has suffered from the addition of several closets and the blocking-off of the second floor landing.

Once the main house of a small dairy farm, the principal dwelling and outbuildings is slated for removal.

Maryland Comprehensive Historic Preservation Plan Data

Buckley Farm Complex H0638

Geographic Organization

Piedmont

Chronological/Development Period

Industrial/Urban Dominance - A.D. 1870 - 1930

Historic Period Theme

Agricultural

Resource Type

Category:	Buildings
Historic Environment:	Rural
Historic Function/Use:	Farm Complex
Known Design Source:	None

Maryland Historical Trust
State Historic Sites Inventory Form

MARYLAND INVENTORY OF
HISTORIC PROPERTIES

Survey No. H0638

Magi No.

DOE ___yes x__no

1. Name (indicate preferred name)

historic

and/or common Buckley Farm Complex - Principal Dwelling

2. Location

street & number Old Montgomery Road _____ not for publication

city, town Columbia x__ vicinity of _____ congressional district

state Maryland _____ county Howard

3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input checked="" type="checkbox"/> private residence
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input checked="" type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input checked="" type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military	<input checked="" type="checkbox"/> other: Construction staging area

4. Owner of Property (give names and mailing addresses of all owners)

name Howard Research and Development Corporation

street & number 10275 Little Patuxent Parkway telephone no.:(410)992-6033

city, town Columbia state and zip code MD 21044-345

5. Location of Legal Description

courthouse, registry of deeds, etc. Howard County Courthouse liber 477

street & number _____ folio 460

city, town Ellicott City state MD

6. Representation in Existing Historical Surveys

title none (See Architectural Assessment of the Buckley Farm Complex

date Howard County, MD-Prepared by David H. Gleason, October 14, 1994
_____ federal _____ state _____ county _____ local

postory for survey records

city, town _____ state _____

7. Description

Survey No. H0638

Condition		Check one	Check one	
<input type="checkbox"/> excellent	<input checked="" type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input checked="" type="checkbox"/> original site	
<input type="checkbox"/> good	<input checked="" type="checkbox"/> ruins	<input checked="" type="checkbox"/> altered	<input type="checkbox"/> moved	date of move _____
<input checked="" type="checkbox"/> fair	<input type="checkbox"/> unexposed			

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

CONTRIBUTING RESOURCE COUNT: 5

The principal dwelling is a 2½ story, single family, balloon frame building with a partial cellar. It consists of three principal bays with a projecting central bay, or square tower with dormer. The hipped roof has paired pediments on either end that appear to be part of the original structure. The entire roof is sheathed in galvanized metal. The upper half-story sports imbricated shake siding, while the remaining portions of all of the facades are covered in asbestos shingles. Plain board moldings highlight both the windows and the principal corners of the front (north) facade. Tongue-and-groove board has been used on all of the eaves and porch soffits.

A full-length Colonial Revival porch with tapered columns and unadorned capitals was added to the front facade. It is in poor condition with one column failing completely, another beginning to fail, and the tongue-and-groove soffit in an advanced state of decay. The rear lean-to porch is in much better condition, being wholly enclosed and serving, in part, as a laundry and utility room. Single story, projecting bays have been added to the west and east facades, retaining the bilateral symmetry of the overall exterior and interior designs. All of the windows have been conserved with metal frame storm windows. A brick chimney stack has been added to the north facade to service the oil burner in the partial cellar below. The original chimneys, however, survive and consist of symmetrically-placed interior stacks that vent at least two fireplaces on the first floor. They are devoid of decorative treatment. The overall condition of the exterior is fair, deterioration attributable to neglect over the past 25 to 30 years. Although the roof appears to be tight, the gutters have not been maintained and significant damage from stormwater is imminent. The windows also are in need of replacement.

Several partition walls have been installed, and several plaster walls have been replaced with dry wall; however, the interior first and second floors retain much of their original configuration. Two large public rooms flank the central hall with its plain paneled stair. Original half-round moldings survive throughout most of the first and second floors, at least in those public areas to which we had access. The fireplace in the east room of the first floor retains its plain mantle with machine-carved central figure of a wreath and crossed torches. Most of the surviving doors are plain paneled. The interior, in general, is in fair condition.

8. Significance

Survey No. H0638

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input checked="" type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/humanitarian
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> theater
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> transportation
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> other (specify)
		<input type="checkbox"/> invention		

Specific dates	Builder/Architect
check: Applicable Criteria: <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
and/or	
Applicable Exception: <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G	
Level of Significance: <input type="checkbox"/> national <input type="checkbox"/> state <input type="checkbox"/> local	

Prepare both a summary paragraph of significance and a general statement of history and support.

The Buckley farmstead consists of a principal dwelling that dates to the last quarter of the 19th century or the first quarter of the 20th century, and a collection of at least six outbuildings that date to the early to mid-20th century. The large barn, silo and milk parlor complex probably date to the second quarter of the 20th century. The large barn, silo and milk parlor complex probably date to the second quarter of the 20th century, judging from the extensive use of concrete block in the construction. Overall, the Buckley farmstead represents a late 19th through 20th century dairy farmstead. Such farmsteads were common throughout the region into the middle of the 20th century. Rapid urbanization within the Washington-Baltimore metropolitan area, however, has largely destroyed the architectural character of the region, and, particularly, the open-pasture atmosphere characteristic of dairying, and the farmsteads that served as landmarks in what was once open, rolling country.

From an archaeological perspective, recent construction-related activities have destroyed the integrity of the homelot. Architecturally, however, the principal dwelling--and the principal dwelling alone--is potentially historically significant insofar as it represents an unusual architectural style in the area and it is one of a rapidly diminishing architectural resource base.

9. Major Bibliographical References

Survey No. H0638

None

10. Geographical Data

Acreeage of nominated property 201,88

Quadrangle name Savage

Quadrangle scale 1:24000

UTM References do NOT complete UTM references

A	<input type="text"/>	<input type="text"/>	<input type="text"/>
	Zone	Easting	Northing

B	<input type="text"/>	<input type="text"/>	<input type="text"/>
	Zone	Easting	Northing

C	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

D	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

E	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

F	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

G	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

H	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

Verbal boundary description and justification

List all states and counties for properties overlapping state or county boundaries

state	Maryland	code	county	Howard	code
-------	----------	------	--------	--------	------

state		code	county		code
-------	--	------	--------	--	------

11. Form Prepared By

name/title David H. Gleason Associates, Inc.

organization		date	<u>October 14, 1994</u>
--------------	--	------	-------------------------

street & number	<u>David H. Gleason Associates, Inc.</u>	telephone	<u>(410) 728-1810</u>
-----------------	--	-----------	-----------------------

city or town	<u>Baltimore</u>	state	<u>Maryland 21201</u>
--------------	------------------	-------	-----------------------

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust
 Shaw House
 21 State Circle
 Annapolis, Maryland 21401
 (301) 269-2438

MARYLAND HISTORICAL TRUST
 DHCP/DHCP
 100 COASTAL PIKE
 CROWNSVILLE, MD 21032
 301-269-2438

**Maryland Historical Trust
State Historic Sites Inventory Form**

MARYLAND INVENTORY OF
HISTORIC PROPERTIES

Magi No.

DOE yes no

1. Name (indicate preferred name)

historic

and/or common Buckley House

2. Location

street & number _____ not for publication

city, town COLUMBIA

vicinity of _____ congressional district

state MARYLAND

county HOWARD

3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input checked="" type="checkbox"/> private residence
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input checked="" type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input checked="" type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military	<input checked="" type="checkbox"/> other: ^{construction} staging area

4. Owner of Property (give names and mailing addresses of all owners)

name Howard Research and Development Corporation

street & number 10275 Little Patuxent Parkway telephone no.: (410) 992-6033

city, town Columbia state and zip code MD 21044-3456

5. Location of Legal Description

courthouse, registry of deeds, etc. Howard County Courthouse liber 477

street & number _____ folio 460

city, town Ellicott City state MD

6. Representation in Existing Historical Surveys

title _____

date _____ federal state county local

postory for survey records _____

city, town _____ state _____

7. Description

Survey No. HO-638

Condition		Check one	Check one
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input checked="" type="checkbox"/> original site
<input type="checkbox"/> good	<input type="checkbox"/> ruins	<input checked="" type="checkbox"/> altered	<input type="checkbox"/> moved
<input checked="" type="checkbox"/> fair	<input type="checkbox"/> unexposed		date of move _____

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The principal dwelling is a 2½ story, single family, balloon frame building with a partial cellar. It consists of three principal bays with a projecting central bay, or square tower with dormer. The hipped roof has paired pediments on either end that appear to be part of the original structure. The entire roof is sheathed in galvanized metal. The upper half-story sports imbricated shake siding, while the remaining portions of all of the façades are covered in asbestos shingles. Plain board moldings highlight both the windows and the principal corners of the front (north) façade. Tongue-and-groove board has been used on all of the eaves and porch soffits.

A full-length Colonial-Revival porch with tapered columns and unadorned capitals was added to the front façade. It is in poor condition with one column failing completely, another beginning to fail, and the tongue-and-groove soffit in an advanced state of decay. The rear lean-to porch is in much better condition, being wholly enclosed and serving, in part, as a laundry and utility room. Single story, projecting bays have been added to the west and east façades, retaining the bilateral symmetry of the overall exterior and interior designs. Most of the windows have been replaced with metal frame storm windows. A brick chimney stack has been added to the east façade to service the oil burner in the partial cellar below. The original chimneys, however, survive and consist of symmetrically-placed interior stacks that vent at least two fireplaces on the first floor. They are devoid of decorative treatment. The overall condition of the exterior is fair, deterioration attributable to neglect over the past 25 to 30 years. Although the roof appears to be tight, the gutters have not been maintained and significant damage from stormwater is imminent. The windows also are in need of replacement.

Several partition walls have been installed, and several plaster walls have been replaced with dry wall; however, the interior first and second floors retain much of their original configuration. Two large public rooms flank the central hall with its plain, paneled stair. Original half-round moldings survive throughout most of the first and second floors, at least in those public areas to which we had access. The fireplace in the east room of the first floor retains its plain mantle with machine-carved central figure of a wreath and crossed torches. Most of the surviving doors are plain paneled. The interior, in general, is in very good condition.

8. Significance

Survey No. HO-638

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400–1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500–1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600–1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/ humanitarian
<input type="checkbox"/> 1700–1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> theater
<input checked="" type="checkbox"/> 1800–1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> transportation
<input checked="" type="checkbox"/> 1900–	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> other (specify)
		<input type="checkbox"/> invention		

Specific dates **Builder/Architect**

check: Applicable Criteria: A B C D
and/or
Applicable Exception: A B C D E F G

Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.

The Buckley farmstead consists of a principal dwelling that dates to the last quarter of the 19th century or the first quarter of the 20th century, and a collection of at least six outbuildings that date to the early to mid-20th century. The large barn, silo and milk parlor complex probably date to the second quarter of the 20th century, judging from the extensive use of concrete block in the construction. Overall, the Buckley farmstead represents a late 19th through 20th century dairy farmstead. Such farmsteads were common throughout the region into the middle of the 20th century. Rapid urbanization within the Washington–Baltimore metropolitan area, however, has largely destroyed the agricultural character of the region, and, particularly, the open–pasture atmosphere characteristic of dairying, and the farmsteads that served as landmarks in what was once open, rolling country.

From an archaeological perspective, recent construction–related activities have destroyed the integrity of the homelot. Architecturally, however, the principal dwelling—and the principal dwelling alone—is potentially historically significant insofar as it represents an unusual architectural style in the area and it is one of a rapidly diminishing architectural resource base.

9. Major Bibliographical References

Survey No. HO-638

10. Geographical Data

Acreeage of nominated property 41 acre

Quadrangle name Savage

Quadrangle scale 1:24000

UTM References do NOT complete UTM references

A	<input type="text"/>	<input type="text"/>	<input type="text"/>
	Zone	Easting	Northing

B	<input type="text"/>	<input type="text"/>	<input type="text"/>
	Zone	Easting	Northing

C	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

D	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

E	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

F	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

G	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

H	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

Verbal boundary description and justification

List all states and counties for properties overlapping state or county boundaries

state	code	county	code
-------	------	--------	------

state	code	county	code
-------	------	--------	------

11. Form Prepared By

name/title James G. Gibb

organization Archaeological Consultant date 11 NOVEMBER 1993

street & number P.O. Box 378 telephone (410) 257-9377

city or town North Beach state MD 20714


The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust
Shaw House
21 State Circle
Annapolis, Maryland 21401
(301) 269-2438

MARYLAND HISTORICAL TRUST
DHCP/DHCD
100 COMMUNITY PLACE
CROWNSVILLE, MD 21052-2023
614-7100

Map 1: Project Area and Location Map



Map 2: Tax Record Map, L. 37, Howard County

HO-638

9

OPEN SPACE

LOT 1

SNOWDEN

OPEN SPACE

LOT 3

LOTS G-1 THRU G-87

LOT 7

OPEN SPACE


LOT 8

HO. RES. & DEV. COMP.
477/480
44.50A.
P. 254

MAP 36-
RD


HOWARD RESEARCH
DEV. COMP.
P. 254

36



HO-638

Map 4: USGS Map, 1974






Figure 3. Topographic map and project area location.

BUCKLEY FARM COMPLEX PHOTOGRAPHS

1. West Facade
2. Detail of original German siding and corner boards, North Facade
3. Detail of Front Porch, looking North
4. South Facade
5. Detail of eave, South Facade
6. North Facade
7. East and North Facades
8. Detail of window trim and shutter, East Facade
9. Detail of newel, Stair Hall, Ground Floor
10. Detail of main stair, Ground Floor
11. Detail of dropped newel at Landing, Ground Floor ceiling
12. Fireplace, Parlor A, Ground Floor
13. Detail of fireplace, Parlor A, Ground Floor
14. Fireplace, Parlor B, Ground Floor
15. Detail of arch at bay, Parlor A, Ground Floor
16. Landing with modern plasterboard wall, Second Floor
17. Landing newels, main stair, Second Floor
18. Newel, back stair, Second Floor
19. Typical interior door
20. Dairy Barn, South Facade
21. Garage, South Facade
22. Garage, North Facade



LOGS

EXPOSED TO THE SUN

CONCRETE WORK - 1.5000

REINFORCING: 1.5000 H. GUFASO

DATE: 02/18/82

WORKING ON THE WEST FACADE

CONCRETE WORK

REINFORCING

THURSDAY, FEBRUARY 18, 1982

1.5000



H-2 624

DETAIL OF ORIGINAL GERMAN SIDING AND CORNER BOARDS, NORTH FACADE

SECTION THROUGH CORNER BOARD AND SIDING

1. CORNER BOARD

2. SIDING

3. INSULATION

4. SHEATHING

5. STUDS

6. BRACKETS

7. GROUND

8. FINISH

9. FINISH

10. FINISH

2. Detail of original German siding and corner boards, North Facade



H0638

BOCKLEY FARM COMPLEX

COLUMBIA HIGHWAY, HOWARD COUNTY,
MARYLAND

PHOTOGRAPHER: DAVID H. GLEASON

DATE: OCT 1974

NEGATIVE LOCATION:

DAVID H. GLEASON ASSOC.,
520 N. EUTAW ST
BALTIMORE, MD

PRINCIPLE DWELLING, DETAIL
OF FRONT PORCH, LOOKING
NORTH

3/22



1063

BUCKLEY FARM COMPLEX

COLUMBIA COUNTY, GEORGIA

UNINCORPORATED, SOUTH OF ATLANTA

1000 ACRES

NEARBY TOWN

1000 ACRES

1000 ACRES

1000 ACRES

2000 ACRES, SOUTH FACADE

1063



SECTION EAST EAVE
 SHOWING DETAIL OF ROOF AND EAVE
 DETAIL OF EAST EAVE
 DATE OCT. 1951
 DRAWING NUMBER: DRAWING NO. 1000-1000-1000
 SCALE: 1/4" = 1'-0"
 PROJECT: DETAIL OF EAST EAVE
 ROOM: 1000-1000-1000
 1000

5. Detail of eave, South Facade



BUCKLEY FARM CENTER
COLUMBIA SPRING, HOWARD CO. MD

PHOTOGRAPHER: DAVID H. GLEASON

DATE: OCT. 1994

NEGATIVE LOCATION:

DAVID H. GLEASON ASSOC.

520 N. EUTAW ST.

BELTSVILLE MD

PRINCIPLE SUBJECTS: NORTH FACADE

6/22



#0638

BROOKLYN FARM COMPLEX

COLUMBIA VICINITY, HOWARD CO., MD

PHOTOGRAPHER: DAVID E. CLISSON

DATE: OCT 1994

NEGATIVE LOCATION:

DAVID E. CLISSON ARCH.

520 N. HUNTER ST.

BALTIMORE MD

DIRECTION: INTERIOR, EAST AND NORTH
FACADES

7/22

7. East and North Facades



1953

WICKLEY ROAD, CHURCH

CONCRETE CURB, HOWARD ROAD,
MARIETTA

INTERIORS: JAMES H. GLEASON

DATE: OCT 1953

WORKING DRAWINGS

JAMES H. GLEASON, ARCHT.

100 W. 10th St.,
Marietta, Ga.

EDUCATION

DETAIL OF
WINDOW TRIM AND SHUTTER,
EAST FACADE

5/13



4/10/77

1/2" scale drawing of newel

COLUMBIA UNIVERSITY HOME & CO,
NEW YORK

PROJECT NAME = DAVIS BUILDING
DATE = 10/1/77

BY: [unclear]

1/2" scale drawing of newel
5/20/77
M. J. [unclear]

DATE: 10/1/77, SET: 1/2"
1/2" scale drawing of newel
1/2"

9/1/77



10/17

BRISTOL PUBLIC LIBRARY

COUNTY LIBRARY, BRISTOL CO.,
MASSACHUSETTS

THOMAS STANTON, 1875-1876

DATE: 2011

LIBRARY LOCATION:

BRISTOL PUBLIC LIBRARY

100 STATE ST.

BRISTOL, MASS.

THIS COPY PURCHASED BY THE LIBRARY

ON 10/17/11

10/17

10. Detail of main stair, Ground Floor



11.6.55

WORKING DRAWING
CONCRETE WORKING DRAWING, HOUSE NO. 1, MANGALAM
MANGALAM, DISTRICT, KARVAT, MANGALAM
LAND, 200 SQ. FT.

WORKING DRAWING
LAND, 200 SQ. FT.
CONCRETE WORKING DRAWING,
MANGALAM, DISTRICT, KARVAT,
MANGALAM, DISTRICT, KARVAT,

CONCRETE WORKING DRAWING
AT 11.6.55, DISTRICT, KARVAT,
MANGALAM, DISTRICT, KARVAT,

11.6.55

11. Detail of dropped newel at Landing, Ground Floor ceiling



HOGS

BECKLEY PARK, BIRMINGHAM

CONCRETE BLOCKS, HERALD CO,
BIRMINGHAM

THE BECKLEY PARK, BIRMINGHAM

1914-1915

REPAIRS TO CONCRETE

BY THE ENGINEER, ARTHUR

W. H. BIRCHALL, JR.

BIRMINGHAM, ALA.

POSSIBLE TRACES OF THE

TABLE A, GROUND FLOOR

12 12 12



10/1/22
10/1/22
10/1/22
VICINITY, HOWARD
CO, MARYLAND

METAL PARTS:
DAILY 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101. 102. 103. 104. 105. 106. 107. 108. 109. 110. 111. 112. 113. 114. 115. 116. 117. 118. 119. 120. 121. 122. 123. 124. 125. 126. 127. 128. 129. 130. 131. 132. 133. 134. 135. 136. 137. 138. 139. 140. 141. 142. 143. 144. 145. 146. 147. 148. 149. 150. 151. 152. 153. 154. 155. 156. 157. 158. 159. 160. 161. 162. 163. 164. 165. 166. 167. 168. 169. 170. 171. 172. 173. 174. 175. 176. 177. 178. 179. 180. 181. 182. 183. 184. 185. 186. 187. 188. 189. 190. 191. 192. 193. 194. 195. 196. 197. 198. 199. 200. 201. 202. 203. 204. 205. 206. 207. 208. 209. 210. 211. 212. 213. 214. 215. 216. 217. 218. 219. 220. 221. 222. 223. 224. 225. 226. 227. 228. 229. 230. 231. 232. 233. 234. 235. 236. 237. 238. 239. 240. 241. 242. 243. 244. 245. 246. 247. 248. 249. 250. 251. 252. 253. 254. 255. 256. 257. 258. 259. 260. 261. 262. 263. 264. 265. 266. 267. 268. 269. 270. 271. 272. 273. 274. 275. 276. 277. 278. 279. 280. 281. 282. 283. 284. 285. 286. 287. 288. 289. 290. 291. 292. 293. 294. 295. 296. 297. 298. 299. 300. 301. 302. 303. 304. 305. 306. 307. 308. 309. 310. 311. 312. 313. 314. 315. 316. 317. 318. 319. 320. 321. 322. 323. 324. 325. 326. 327. 328. 329. 330. 331. 332. 333. 334. 335. 336. 337. 338. 339. 340. 341. 342. 343. 344. 345. 346. 347. 348. 349. 350. 351. 352. 353. 354. 355. 356. 357. 358. 359. 360. 361. 362. 363. 364. 365. 366. 367. 368. 369. 370. 371. 372. 373. 374. 375. 376. 377. 378. 379. 380. 381. 382. 383. 384. 385. 386. 387. 388. 389. 390. 391. 392. 393. 394. 395. 396. 397. 398. 399. 400. 401. 402. 403. 404. 405. 406. 407. 408. 409. 410. 411. 412. 413. 414. 415. 416. 417. 418. 419. 420. 421. 422. 423. 424. 425. 426. 427. 428. 429. 430. 431. 432. 433. 434. 435. 436. 437. 438. 439. 440. 441. 442. 443. 444. 445. 446. 447. 448. 449. 450. 451. 452. 453. 454. 455. 456. 457. 458. 459. 460. 461. 462. 463. 464. 465. 466. 467. 468. 469. 470. 471. 472. 473. 474. 475. 476. 477. 478. 479. 480. 481. 482. 483. 484. 485. 486. 487. 488. 489. 490. 491. 492. 493. 494. 495. 496. 497. 498. 499. 500. 501. 502. 503. 504. 505. 506. 507. 508. 509. 510. 511. 512. 513. 514. 515. 516. 517. 518. 519. 520. 521. 522. 523. 524. 525. 526. 527. 528. 529. 530. 531. 532. 533. 534. 535. 536. 537. 538. 539. 540. 541. 542. 543. 544. 545. 546. 547. 548. 549. 550. 551. 552. 553. 554. 555. 556. 557. 558. 559. 560. 561. 562. 563. 564. 565. 566. 567. 568. 569. 570. 571. 572. 573. 574. 575. 576. 577. 578. 579. 580. 581. 582. 583. 584. 585. 586. 587. 588. 589. 590. 591. 592. 593. 594. 595. 596. 597. 598. 599. 600. 601. 602. 603. 604. 605. 606. 607. 608. 609. 610. 611. 612. 613. 614. 615. 616. 617. 618. 619. 620. 621. 622. 623. 624. 625. 626. 627. 628. 629. 630. 631. 632. 633. 634. 635. 636. 637. 638. 639. 640. 641. 642. 643. 644. 645. 646. 647. 648. 649. 650. 651. 652. 653. 654. 655. 656. 657. 658. 659. 660. 661. 662. 663. 664. 665. 666. 667. 668. 669. 670. 671. 672. 673. 674. 675. 676. 677. 678. 679. 680. 681. 682. 683. 684. 685. 686. 687. 688. 689. 690. 691. 692. 693. 694. 695. 696. 697. 698. 699. 700. 701. 702. 703. 704. 705. 706. 707. 708. 709. 710. 711. 712. 713. 714. 715. 716. 717. 718. 719. 720. 721. 722. 723. 724. 725. 726. 727. 728. 729. 730. 731. 732. 733. 734. 735. 736. 737. 738. 739. 740. 741. 742. 743. 744. 745. 746. 747. 748. 749. 750. 751. 752. 753. 754. 755. 756. 757. 758. 759. 760. 761. 762. 763. 764. 765. 766. 767. 768. 769. 770. 771. 772. 773. 774. 775. 776. 777. 778. 779. 780. 781. 782. 783. 784. 785. 786. 787. 788. 789. 790. 791. 792. 793. 794. 795. 796. 797. 798. 799. 800. 801. 802. 803. 804. 805. 806. 807. 808. 809. 810. 811. 812. 813. 814. 815. 816. 817. 818. 819. 820. 821. 822. 823. 824. 825. 826. 827. 828. 829. 830. 831. 832. 833. 834. 835. 836. 837. 838. 839. 840. 841. 842. 843. 844. 845. 846. 847. 848. 849. 850. 851. 852. 853. 854. 855. 856. 857. 858. 859. 860. 861. 862. 863. 864. 865. 866. 867. 868. 869. 870. 871. 872. 873. 874. 875. 876. 877. 878. 879. 880. 881. 882. 883. 884. 885. 886. 887. 888. 889. 890. 891. 892. 893. 894. 895. 896. 897. 898. 899. 900. 901. 902. 903. 904. 905. 906. 907. 908. 909. 910. 911. 912. 913. 914. 915. 916. 917. 918. 919. 920. 921. 922. 923. 924. 925. 926. 927. 928. 929. 930. 931. 932. 933. 934. 935. 936. 937. 938. 939. 940. 941. 942. 943. 944. 945. 946. 947. 948. 949. 950. 951. 952. 953. 954. 955. 956. 957. 958. 959. 960. 961. 962. 963. 964. 965. 966. 967. 968. 969. 970. 971. 972. 973. 974. 975. 976. 977. 978. 979. 980. 981. 982. 983. 984. 985. 986. 987. 988. 989. 990. 991. 992. 993. 994. 995. 996. 997. 998. 999. 1000.

10/1/22
10/1/22
10/1/22

10/1/22

13. Detail of fireplace, Parlor A, Ground Floor



HOGS

ROCKLEY EAST COMPLEX

COLUMBIA COUNTY, HERBERT CRATT, MARY ANN

THEYRELANDERS, SOUTH W. QUINCY

DAN, OCT 1970

DEPT OF CORRECTIONS, DANVILLE, VA. A. C. 1970
2000 ST. PATRICK ST
FACILITY # 100

DEPARTMENT OF CORRECTIONS, DANVILLE, VA. 1970
QUINCY FLOOR

141



1/10/62

BRICKS - PARLOR, CHIMNEY

CRUMFORD, HIGGINS, NEWARK, NJ,
UNIVERSITY

PHOTOGRAPHS - WALL, FLOOR, etc.

DATE: OCT 1961

NEGATIVE LOCATION

LARGE H. CHIMNEY - ARCH
2nd & 3rd FLOOR
PART - etc, etc

PHOTOGRAPHS, DETAIL OF
ARCH AT BAY, PARLOR A,
GROUND FLOOR

15/12



HC 2577

BUCKLEY PARK 30 1991

CONCRETE DISTRICT, HERMAN CO.,
DALLAS TEXAS

PHOTOGRAPHER: DAVID H. SHAW

DATE: OCT 1991

NEGATIVE LOCATION:

TAVIS H. GLENN ASSOC.,

5000 N. HERMAN ST.,


IRVING TEXAS 75038

REFERENCE DISTRICT, LANDING WITH

MODERN PLASTERBOARD WALL

SECOND FLOOR

16/2



40 635

BOOKING PAGE CONTAINS

COLUMBIA UNIVERSITY RECORDS OF

UNIVERSITY

PHOTOGRAPHS TAKEN IN 1930s

DATED OCT 1931

APPROXIMATE LOCATION

LANDING NEWEL STAIRS

SECOND FLOOR

PHOTOGRAPH

UNIVERSITY RECORDS, LANDINGS

SECOND FLOOR

SECOND FLOOR

1722



110 612

PROJECT: FARM BUILDING

GENERAL LIGHTING FIXTURES CO.,
WILMINGTON

INSTALLATION, 1941 - H. S. ...

1941 - 1942

REPAIRS - 1943

DAVID M. GLEASON ASST


100 N. ...

... , NC

TON ...

... STAIR, ...

...



14 57

RECORDS FROM OFFICE

COLUMBIA UNIVERSITY, ACADEMICAL DEPT.,
BIBLIOTHEQUE

INTERVIEWS FROM H. GIBSON

DATE: OCT. 1954

PHYSICAL LOCATION:

UNIV. H. GIBSON OFFICE

522 S. EIGHTH ST

ANN ARBOR, MI

PHOTOGRAPHING - TYPICAL

INTERIOR DOOR (FAR LEFT)

GROUND FLOOR

19/32







40659

BLUESKY LABOR COMPANY

COLUMBIA UNIVERSITY, NEWARK CC, NJ

PHOTOGRAPHER: DAVID W. GIBSON

DATE: OCT 1994

RELATIVE LOCATION: 2ND FLOOR
300 W. 11TH ST
NEWARK NJ

GARAGE, NORTH FACADE

22/22

22. Garage, North Facade



HO-638

Buckley House
Columbia, Md.

Jibb G. Gibb

11 Nov. 93