

7. DESCRIPTION

CONDITION	(Check One)				
	<input checked="" type="checkbox"/> Excellent	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Deteriorated	<input type="checkbox"/> Ruins
	(Check One)		(Check One)		
	<input type="checkbox"/> Altered	<input checked="" type="checkbox"/> Unaltered	<input type="checkbox"/> Moved	<input checked="" type="checkbox"/> Original Site	

DESCRIBE THE PRESENT AND ORIGINAL (if known) PHYSICAL APPEARANCE

This is a typical, two-story, L-shaped farmhouse. The main block is a three-bay section that faces south. There is a central doorway, and a one-story, shed-roof porch covers the door and both flanking windows. There is a stove chimney flue in the west end, and the windows are all 2/2. A two-bay ell extends to the NW rear of the house.

SEE INSTRUCTIONS

M:15-13

9. MAJOR BIBLIOGRAPHICAL REFERENCES

10. GEOGRAPHICAL DATA

LATITUDE AND LONGITUDE COORDINATES DEFINING A RECTANGLE LOCATING THE PROPERTY			O R	LATITUDE AND LONGITUDE COORDINATES DEFINING THE CENTER POINT OF A PROPERTY OF LESS THAN TEN ACRES		
CORNER	LATITUDE	LONGITUDE		LATITUDE	LONGITUDE	
	Degrees Minutes Seconds	Degrees Minutes Seconds		Degrees Minutes Seconds	Degrees Minutes Seconds	
NW	° ' "	° ' "		° ' "	° ' "	
NE	° ' "	° ' "		° ' "	° ' "	
SE	° ' "	° ' "		° ' "	° ' "	
SW	° ' "	° ' "		° ' "	° ' "	

APPROXIMATE ACREAGE OF NOMINATED PROPERTY:

Acreage Justification:

11. FORM PREPARED BY

NAME AND TITLE: Michael F. Dwyer, Senior Park Historian

ORGANIZATION: M-NCPPC

DATE: 1/8/74

STREET AND NUMBER: 8787 Georgia Ave.

CITY OR TOWN: Silver Spring

STATE: Maryland

12. State Liaison Officer Review: (Office Use Only)

Significance of this property is:

National State Local

Signature _____

SEE INSTRUCTIONS



M#15-13

NAME HAROLD W. MULLINIX FARM - OLD TENANT HOUSE

LOCATION E OF LONG CORNER Rd DAMASCUS, Md

FACADE W

PHOTO TAKEN 1/8/74 M. DWYER



M# 15-13

NAME HAROLD W. MULLINIX SR. FARM - OLD TENANT HOUSE

LOCATION E OF LONG CORNER Rd. DAMASCUS, Md

FACADE W

PHOTO TAKEN 1/8/74 M. DWYER



M#15-13

NAME HAROLD W. MULLINIX SR FARM (BUILT 1899)

LOCATION E OF LONG CORNER RD DAMASCUS, MD

FACADE S

PHOTO TAKEN 1/8/74 M. DWYER