

M:16-13

7. DESCRIPTION

CONDITION	(Check One)					
	<input type="checkbox"/> Excellent	<input type="checkbox"/> Good	<input checked="" type="checkbox"/> Fair	<input type="checkbox"/> Deteriorated	<input type="checkbox"/> Ruins	<input type="checkbox"/> Unexposed
	(Check One)			(Check One)		
	<input checked="" type="checkbox"/> Altered	<input type="checkbox"/> Unaltered	<input type="checkbox"/> Moved	<input checked="" type="checkbox"/> Original Site		

DESCRIBE THE PRESENT AND ORIGINAL (if known) PHYSICAL APPEARANCE

The house is a 2 1/2 story frame house with external stone chimneys. The main (south) facade has three bays with entrance through the east bay. The cornice is boxed and returned into the gable ends. The chimneys are positioned off-center, the one on the east end being north of the ridge and the one on the west end being south of the ridge. On the interior, a lateral partition wall divides the house into front and rear rooms, each with a fireplace but on opposite end walls. The interior walls are nailed to the cellar girt and a summer beam.

The staircase rises against the east end wall in a straight run. On the 2nd floor there is a room opening at the top of the stairs and two rooms to the west of the hall. One room has a thimble for a stovepipe into the chimney.

The attic is ceiled at the collar beams. The rafters are not joined, but a number of non-supporting, cut-off members suggests extensive changes in the roof.

The house sits on a stone foundation. An exposed sill is a flattened log, as are some of the first floor joists. A girt runs laterally across the house and is supported by the foundation walls and three posts.

The house has brick infilling between the framing members. Angle braces are exposed where the plaster has fallen off on the first floor. None of the framing is mortised or pegged, however; all joining is by notching/into members

SEE INSTRUCTIONS

B. SIGNIFICANCE

PERIOD (Check One or More as Appropriate)

<input type="checkbox"/> Pre-Columbian	<input type="checkbox"/> 16th Century	<input type="checkbox"/> 18th Century	<input type="checkbox"/> 20th Century
<input type="checkbox"/> 15th Century	<input type="checkbox"/> 17th Century	<input checked="" type="checkbox"/> 19th Century	

SPECIFIC DATE(S) (If Applicable and Known)

AREAS OF SIGNIFICANCE (Check One or More as Appropriate)

<input type="checkbox"/> Aboriginal	<input type="checkbox"/> Education	<input type="checkbox"/> Political	<input type="checkbox"/> Urban Planning
<input type="checkbox"/> Prehistoric	<input type="checkbox"/> Engineering	<input type="checkbox"/> Religion/Philosophy	<input type="checkbox"/> Other (Specify)
<input type="checkbox"/> Historic	<input type="checkbox"/> Industry	<input type="checkbox"/> Science	_____
<input type="checkbox"/> Agriculture	<input type="checkbox"/> Invention	<input type="checkbox"/> Sculpture	_____
<input type="checkbox"/> Architecture	<input type="checkbox"/> Landscape Architecture	<input type="checkbox"/> Social/Humanitarian	_____
<input type="checkbox"/> Art	<input type="checkbox"/> Literature	<input type="checkbox"/> Theater	_____
<input type="checkbox"/> Commerce	<input type="checkbox"/> Military	<input type="checkbox"/> Transportation	_____
<input type="checkbox"/> Communications	<input type="checkbox"/> Music		_____
<input type="checkbox"/> Conservation			_____

STATEMENT OF SIGNIFICANCE

SEE INSTRUCTIONS

each other and nailing them together. There is an L wing to the rear, sitting on a separate foundation. Behind the house is a bankbarn.

9. MAJOR BIBLIOGRAPHICAL REFERENCES

10. GEOGRAPHICAL DATA

LATITUDE AND LONGITUDE COORDINATES DEFINING A RECTANGLE LOCATING THE PROPERTY			O R	LATITUDE AND LONGITUDE COORDINATES DEFINING THE CENTER POINT OF A PROPERTY OF LESS THAN TEN ACRES		
CORNER	LATITUDE	LONGITUDE		LATITUDE	LONGITUDE	
	Degrees Minutes Seconds	Degrees Minutes Seconds		Degrees Minutes Seconds	Degrees Minutes Seconds	
NW	° ' "	° ' "		° ' "	° ' "	
NE	° ' "	° ' "		° ' "	° ' "	
SE	° ' "	° ' "		° ' "	° ' "	
SW	° ' "	° ' "		° ' "	° ' "	

APPROXIMATE ACREAGE OF NOMINATED PROPERTY:

Acreage Justification:

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE:	COUNTY:

11. FORM PREPARED BY

NAME AND TITLE: Christopher Owens, Park Historian

ORGANIZATION: M-NCPPC

DATE: 31 May 1973

STREET AND NUMBER: 8787 Georgia Avenue

CITY OR TOWN: Silver Spring

STATE: Maryland

12. State Liaison Officer Review: (Office Use Only)

Significance of this property is:

National State Local

Signature _____

SEE INSTRUCTIONS



NAME ISAAC YOUNG HSE.

M: 16-13

LOCATION Rt. 107 & WAESCHE Rd., POOLESVILLE, Md

FACADE S. (FRONT)

PHOTO TAKEN 5/31/73 M. DWYER

30



M. 16-13

NAME ISAAC YOUNG HSE.

LOCATION Rt 107 & WAESCHER Rd., POOLESVILLE, Md.

FACADE W.

PHOTO TAKEN 5/31/73 M. DWYER

27



NAME ISAAC YOUNG HSE.

M: 16-13

LOCATION Rt. 0074 WAESCHE Rd. POOLESVILLE, Md.

FACADE N.E. - CHIMNEY

PHOTO TAKEN 5/31/73 M. DWYER





NAME ISAAC YOUNG FARM - BARN

M: 16-13

LOCATION RT. 1074 WAESCHE RD POOLESVILLE AREA

FACADE S.E.

PHOTO TAKEN 5/31/73 M. DWYER