S

GAITHERSBURG HISTORIC SITES SURVEY FIELD SHEET

ADDRESS 106 S. FREDERICK AVE. MHT # M-21-126 SURVEY # 006
County: Montgomery LOT -, BLOCK -
Gaithersburg LIBER 6, FOLIO 7

OWNER: Ballet 106 PRESENT USE: dance studio
ADDRESS: same ORIGINAL USE: residence
CITY: same BUILDER: unknown

STYLE: Late Victorian DATE BUILT: c.1900 PHYS. COND: good

GENERAL DESCRIPTION

STRUCTURAL SYSTEM:
- FOUNDATION: brick
- WALL STRUCTURE: Balloon
- WALL COVERING: stucco

ROOF CONSTRUCTION:
- ROOF STRUCTURE: Wood Truss
- ROOF COVERING: pressed tin, fish-scale pattern
- ROOF STYLE: modified hip
- EAVES: boxed cornice, plain frieze with return
- CHIMNEYS: 1, offset rear interior

APPENDAGES:
- ADDITIONS: rear
- ELLS: -
- PORCHES: front, wrap-around
  - SUPPORTS: doric columns
- OUTBUILDINGS: -

STORIES: 2 1/2 BAYS: 3 x 2 APPROX DIMENSION: 23 x 27

WINDOWS:
- TYPE: d.h.s., casement
- LIGHTS: 1/1, single/double casement, 6 lights
- BAY WINDOWS: 1 storey,right
- SIDE BY SIDES: front
- GABLE TYPES: single 1/1 d.h.s.

ENTRANCES:
- LOCATION: 2nd bay
- DESCRIPTION: 2 light transom

THREAT: roads/development SURROUNDINGS: commerical/buffer

M:21-126

DESCRIPTION: Gables-single 1/1 d.h.s. windows with plain surrounds. Decorative staggered butt shingles. Front-2nd storey two double 1/1 d.h.s. windows, plain surrounds. 1st storey, single 1/1 d.h.s. window, front door with two-light transom, five horizontal panels. 3rd bay has double 1/1 d.h.s. window. Porch supported by Doric columns, standing seam tin roof, original tongue/groove on floor now covered with plywood. Right-one-storey bay window with 1/1 d.h.s. windows in each bay, standing seam tin roof. Door in N.E. side of bay with one-light transom and glass in upper half. Double d.h.s 1/1/ windows in first bay, second storey; Back-1/1 d.h.s. windows in all three bays, middle one shorter. Addition has tin roof. Original part has German siding with single-light casement window on north side. Second part of addition is flush board with a single and double casement window, 6 lights in each, plain surrounds.
Left-single 1/1 d.h.s. window in each bay. Strange addition between bays: high gable shingle roof to top of second storey, wood exterior paneling.

Recorded by:
Lee Bowers
October 26, 1982
Historic Inventory Task Force