

Easement

FOR NPS USE ONLY	
RECEIVED	M - 30 - 12
DATE ENTERED	

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS
TYPE ALL ENTRIES -- COMPLETE APPLICABLE SECTIONS

1 NAME

HISTORIC

AND/OR COMMON

Corby Estate

2 LOCATION

STREET & NUMBER

10701 Rockville Pike (at Strathmore Ave.)

CITY, TOWN

Rockville

NOT FOR PUBLICATION

CONGRESSIONAL DISTRICT

Fourth

STATE

Maryland

VICINITY OF

CODE
024

COUNTY

Montgomery

CODE

031

3 CLASSIFICATION

CATEGORY

- DISTRICT
- BUILDING(S)
- STRUCTURE
- SITE
- OBJECT

OWNERSHIP

- PUBLIC
- PRIVATE
- BOTH
- PUBLIC ACQUISITION**
- IN PROCESS
- BEING CONSIDERED

STATUS

- OCCUPIED
- UNOCCUPIED
- WORK IN PROGRESS
- ACCESSIBLE**
- YES: RESTRICTED
- YES: UNRESTRICTED
- NO

PRESENT USE

- AGRICULTURE
- MUSEUM
- COMMERCIAL
- PARK
- EDUCATIONAL
- PRIVATE RESIDENCE
- ENTERTAINMENT
- RELIGIOUS
- GOVERNMENT
- SCIENTIFIC
- INDUSTRIAL
- TRANSPORTATION
- MILITARY
- OTHER

4 OWNER OF PROPERTY

NAME

American Speech and Hearing Association

STREET & NUMBER

9030 Old Georgetown Road

CITY, TOWN

Bethesda,

VICINITY OF

STATE

Maryland 20014

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,
REGISTRY OF DEEDS, ETC.

Montgomery County Courthouse

STREET & NUMBER

CITY, TOWN

Rockville,

STATE

Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

FEDERAL STATE COUNTY LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

M:30-12

CONDITION		CHECK ONE	CHECK ONE
<input checked="" type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input checked="" type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Charles Corby Mansion is located on the east side of U.S. Route 355, Rockville Pike, five miles north of the Maryland-Washington, D.C. line in Montgomery County, Maryland. It is a Colonial Revival house dating from the early twentieth century designed in the shape of a T with the leg of the T extending south from the central entrance of the building terminating in the garden facade. The principal (northern) entrance is accented by a semicircular stone portico with fluted Doric columns and a flat roof featuring an ornate balustrade. This one story entrance is flanked on either side by identical two-story blocks of three bays, each having a hip roof covered with slate shingles. Large stone-capped chimney stacks project from within the end walls, and carved wooden balustrades surround the entire roofline of each block. The garden (southern) entrance is emphasized by a central two-story Ionic portico having a slate deck and a pediment with richly carved modillions. This two-story, three-bay central pavillion has a hip roof of slate shingles and two interior chimneys projecting above the west wall and one stone-capped chimney on the east. There is a molded cornice with dentils surrounding the entire house. The brick walls are laid in Flemish bond and have white marble quoins at each corner. White marble trim also appears in the water table, window frames and sills, and a wide belt course between the first and second stories. A wrought iron balcony projects from the end wall of the west block and from the second story in the south portico. In each angle of the T is a one-story unit with parapet walls on four sides surrounded by fluted Doric pilasters.

The first floor of the house follows a four-room central hall plan with modifications. From the central entrance in the north facade, three French doors with transomes open into an entrance hall with marble floors, stone walls, and an ornate skylight of leaded glass. The hall is dominated by a stone foundation with a fluted base and stone claw-like feet supporting each tier. On the west wall are three French doors with transomes, and on the south wall are three similar ones of mirrors. Centered on the east wall is a French door with a transome. The double doors and transomes of the west, north, and east walls have panes of translucent glass with an intricate pattern. Fluted stone pilasters flank each door and four lamps of brass with stone bases similar to lampadaires stand against the north and south walls.

To the west of the entrance hall, a large organ room with a parquet floor fills the entire west block. This room is two storys high and has oak paneling for half its height, then stone continuing to the ceiling. A low chair rail and a rose marble baseboard surround the room. Exposed oak beams extend across the ceiling. On the west end wall, a massive carved stone fireplace is centered with French doors on either side leading to a balcony. Extending across the end of the room over the mantel and doors is an oak chamber originally for the organ pipes.

See Continuation Sheet #1

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

FOR NPS USE ONLY
RECEIVED
DATE ENTERED

**NATIONAL REGISTER OF HISTORIC PLACES
INVENTORY -- NOMINATION FORM**

Corby Estate
Montgomery County,
Maryland

CONTINUATION SHEET ITEM NUMBER 7 PAGE 1

DESCRIPTION (continued)

Supporting this projecting organ chamber are fluted Doric columns of oak. On the south wall, a central double door leads to the west sunroom. Three windows are evenly spaced on the north wall with one being under the organ chamber. Between the two windows within the room is an oak recess where the organ was located. On the east wall above the three French doors is a Palladian window. Ornate chandeliers are suspended from the ceiling, and similar wall sconces are under the organ chamber on the north and south walls.

To the rear of the entrance hall is a paneled stair hall. Walls of the one bay wide by two bay deep stair hall have a cornice with dentil rows and a baseboard of marble. A low chair rail surrounds the room. Along the entire south wall are three French doors with transomes. On the east wall is a sliding door flanked by fluted pilasters, and in the northeast corner is an additional French door. All the doors have window panes of translucent glass. Along the west wall is a dog-leg stair with rectangular step ends. The balusters are wrought iron with sections of ornamental patterns and form a spiral around the newel. On the north wall at the stair landing is a Palladian window with fluted pilasters. In the stair hall are two chandeliers, and sconces are located on the west and east walls as well as that of stair landing.

West of the stair hall is a drawing room and office which together formed the original drawing room. Both rooms have paneling with a low chair rail, marble baseboards and a simple cornice. Addition of the wall dividing the original drawing room resulted in a change in the location of a door to the west sun room. Now there are two French doors and an additional single door near the office. Centrally placed in the west wall of the office is a door flanked by fluted pilasters. The west wall of the original drawing room had three French doors with the center one opposite the door to the stair hall. These were flanked by single doors on either side. Along the south wall of the office is a window between arched bookcases. A small elevator, opening into the drawing room has been added by enclosing a corner of the west sun room. As with the drawing room, the original sun room has been divided and now has a wood floor over its slate deck.

Opposite the drawing room on the east side of the stair hall is the library completely paneled in oak. The room contains intricately carved patterns in oak in the fireplace mantel, the pilasters on the front of the fireplace, and the overmantel, which features a central block of a carved coat of arms. The same pattern is repeated in the pilasters flanking the west and north wall doorways. There is an oak cornice with egg and dart molding. On the west wall, bookshelves occupy the entire

See Continuation Sheet #2

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

M:30-12

FOR NPS USE ONLY

RECEIVED

DATE ENTERED

**NATIONAL REGISTER OF HISTORIC PLACES
INVENTORY -- NOMINATION FORM**

Corby Estate
Montgomery County,
Maryland

CONTINUATION SHEET

ITEM NUMBER

7

PAGE 2

DESCRIPTION (continued)

area on either side of the centrally located doorway. The fireplace on the east wall, with carved marble facing, is flanked by double paneled doors. On the north wall a short hall in the center terminates in a double sliding doorway. The south wall contains a large window identical to the window on the south wall of the office. Sconces are located on the south and north walls.

East of the library is another sun room. Part of it has been altered for a bathroom, closet area and bookshelves. The ceiling has been lowered and a wood floor placed over the slate deck. Originally this east sun room was enclosed entirely by glass as was the western one.

North of the library and east of the entrance hall is a paneled dining room. A handsome cornice with minute detail surrounds the room. On the east wall, a fireplace with carved marble mantle and a dog-eared overmantel has fluted pilasters on the front. To the south side of the fireplace is a French door with transome and side lights opening to the small room which resulted from the alterations in the east sunroom. On the north wall is a large window behind a screen of Ionic columns. Sconces are located on the front of the fireplace and on the south and north walls. To the east of the dining room is a butler's pantry with staircase on the east wall, having a dog-leg staircase with winders. At the foot of the stairway, a doorway leads to a room of modern alterations. Originally the kitchen, this room reflects little evidence of its past use. East of this is a modern kitchen (originally the summer kitchen) with a small enclosed porch.

On the second floor above the stair hall and library is the master bedroom with an adjoining sitting room. The door to the master bedroom on the north wall has side lights and transom. On the south wall is a large glass double door leading to a balcony in the south portico. Its paneled sitting room has been divided into two rooms and a hall. There is an elaborate cornice with diamond and rectangular designs and a low chair rail of rosette carving surround the original four walls of the sitting room. The north wall of the hall (north wall of original sitting room) has two elaborate pedimented doorways, one of which leads to a marbled bathroom-dressing room. The east wall of the original sitting room has a fireplace mantel with carved marble figurines and Wedgewood panels. Windows in these rooms have a cornice overhead similar to that at the ceiling. In another bedroom over the drawing room there is a bay window. There and in two other bedrooms, different styles of sconces are located on the walls.

See Continuation Sheet #3

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

M:30-12

FOR NPS USE ONLY
RECEIVED
DATE ENTERED

**NATIONAL REGISTER OF HISTORIC PLACES
INVENTORY -- NOMINATION FORM**

Corby Estate
Montgomery County,

CONTINUATION SHEET Maryland ITEM NUMBER 7 PAGE 3

DESCRIPTION (continued)

Currently the Metro Transit System's excavation for the subway system passes by the west side of the mansion and extends the entire length of the property. The excavated area is twelve feet from the nearest wall of the mansion leaving a ninety degree slope of over thirty feet.

With the purchase of the property by the American Speech and Hearing Association, interior alterations to the mansion and the addition of an 86-spaced parking area on the east side of the mansion will result. A 40,000 square foot building designed to accommodate up to 140 employees and appurtenant parking facilities will be constructed in the northwest corner of the property. If the planned resale of the mansion and fifteen acres occurs after the new building is completed, the Montgomery County government will become one of the primary interested parties for the purchase of the mansion. The Montgomery County government rates the Corby Estate as the most desirable site for a new performing arts-civic center facility.

8 SIGNIFICANCE

M: 30-12

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input checked="" type="checkbox"/> OTHER (SPECIFY) Local History
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES _____ BUILDER/ARCHITECT _____

STATEMENT OF SIGNIFICANCE

Corby Mansion was built for Charles Israel Corby, a successful businessman of Washington, D.C. Early in the twentieth century he and his brother, William, contributed much to the nationwide baking industry. William Corby was a partner in the baking firm of Fay and Stiles when Charles joined in 1890. By 1912 the business had enlarged and was incorporated as the Corby Baking Company with Charles I. Corby as president. The Corby Brothers were granted eight United States patents, and some foreign ones, for the first dough-molding machines which shaped dough into loaf forms. They eventually developed machines which could perform all the steps needed in the process of making bread. In 1898, they began wrapping their bread in waxed paper and, the next year, used refrigeration to control the fermentation period during manufacture. By 1901, the Corby Brothers began a scientific laboratory to study the problems related to bread-making and fermentation. They received a patent on July 11, 1905, for a machine which divided and weighed the dough. Their revolving dough-proofing cabinet saved much labor and was more sanitary than previous methods. The Corby's oven, built in 1914, baked more bread per pound of coal and doubled the output in the same amount of floor space formerly required. Thus Charles and William Corby did much to establish modern baking methods.

Charles Corby's mansion is a well-designed and executed example of Colonial Revival architecture. While it has a mix of elements from various styles, the basis of the design is from Georgian sources. The main block laid in Flemish bond has a white marble beltcourse and quoins. Inside, large central entrance and stair halls open onto the principal living and dining rooms of the first floor. There is a combination of Georgian and Federal treatment in the modillioned cornices, columns and pilasters and most of the mantelpieces. Federal influence can be seen in the semicircular entrance portico, the Palladian windows and, to some degree, in the projection of various rooms from a rectangular, central block. These projections are most evident when the mansion is seen from the garden. However, the extension of the kitchen wing and organ room are more evident in plan.

The Corby Mansion and John Russell Pope's Woodend (Wells Estate), now the Audubon Society Headquarters, are similar in form. The two of them are the best examples of the early twentieth century estates built in the area along Rockville Pike.

9 MAJOR BIBLIOGRAPHICAL REFERENCES

M:30-12

Proctor, John Clagett. Washington-Past and Present. Lewis Historical Society, 1929-1930, pp 41-43

The Washington Star: Baking Concern Buys Corby Plant. 1925

Proctor, pp 41-43.

Ibid

Feasability study for the acquisition of the Corby Mansion-Montgomery County government (1975-76).

Ibid

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY 33 acres

UTM REFERENCES

A	<input type="text"/>	<input type="text"/>	<input type="text"/>
	ZONE	EASTING	NORTHING

B	<input type="text"/>	<input type="text"/>	<input type="text"/>
	ZONE	EASTING	NORTHING

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE	CODE	COUNTY	CODE
STATE	CODE	COUNTY	CODE

11 FORM PREPARED BY

njm

NAME / TITLE

Roy H. Gauzza

ORGANIZATION

DATE

May 1977

STREET & NUMBER

TELEPHONE

CITY OR TOWN

STATE

Kensington,

Maryland 20795

12 STATE HISTORIC PRESERVATION OFFICER CERTIFICATION

THE EVALUATED SIGNIFICANCE OF THIS PROPERTY WITHIN THE STATE IS:

NATIONAL

STATE

LOCAL

As the designated State Historic Preservation Officer for the National Historic Preservation Act of 1966 (Public Law 89-665), I hereby nominate this property for inclusion in the National Register and certify that it has been evaluated according to the criteria and procedures set forth by the National Park Service.

STATE HISTORIC PRESERVATION OFFICER SIGNATURE

TITLE

DATE

FOR NPS USE ONLY

I HEREBY CERTIFY THAT THIS PROPERTY IS INCLUDED IN THE NATIONAL REGISTER

DATE

DIRECTOR, OFFICE OF ARCHEOLOGY AND HISTORIC PRESERVATION

TEST:

DATE

KEEPER OF THE NATIONAL REGISTER

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

AND/OR COMMON

Corby Estate

(now Strathmore Hall Arts Center - 1985)

2 LOCATION

STREET & NUMBER

10701 Rockville Pike (at Strathmore Ave.)

CITY, TOWN

Rockville

— VICINITY OF

CONGRESSIONAL DISTRICT

STATE

Maryland

COUNTY

Montgomery

3 CLASSIFICATION

CATEGORY

- DISTRICT
- BUILDING(S)
- STRUCTURE
- SITE
- OBJECT

OWNERSHIP

- PUBLIC
- PRIVATE
- BOTH
- PUBLIC ACQUISITION**
- IN PROCESS
- BEING CONSIDERED

STATUS

- OCCUPIED
- UNOCCUPIED
- WORK IN PROGRESS
- ACCESSIBLE**
- YES: RESTRICTED
- YES: UNRESTRICTED
- NO

PRESENT USE

- AGRICULTURE
- MUSEUM
- COMMERCIAL
- PARK
- EDUCATIONAL
- PRIVATE RESIDENCE
- ENTERTAINMENT
- RELIGIOUS
- GOVERNMENT
- SCIENTIFIC
- INDUSTRIAL
- TRANSPORTATION
- MILITARY
- OTHER:

4 OWNER OF PROPERTY

NAME

Sisters of the Holy Cross

Telephone #:

STREET & NUMBER

10701 Rockville Pike

CITY, TOWN

Rockville

— VICINITY OF

STATE, zip code

Maryland

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,
REGISTRY OF DEEDS, ETC.

Montgomery County Courthouse

Liber #:

Folio #:

STREET & NUMBER

CITY, TOWN

Rockville

STATE

Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

— FEDERAL — STATE — COUNTY — LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

M.30-12

CONDITION
 EXCELLENT
 GOOD
 FAIR
 DETERIORATED
 RUINS
 UNEXPOSED

CHECK ONE
 UNALTERED
 ALTERED

CHECK ONE
 ORIGINAL SITE
 MOVED DATE _____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This is a huge, opulent brick building, built to resemble a magnificent Georgian mansion. The house is built in the shape of a T, with the leg of the T extending south from the central entrance of the building. This central entrance is located in the (north) main facade, and is accented by a columned, flat-roofed, stone portico, that features an ornate balustrade on the roof. This one-story entrance is flanked on either side by two-story, three-bay blocks of identical design. Each block has a hip roof covered with slate shingles. Large chimney stacks project from within the end walls. Carved stone balustrades surround the entire roofline of each block. The molded cornices have dentil rows. The brick walls are laid in Flemish bond, and have white marble quoins at each corner. The white marble trim also appears in the water-table, window frames and sills, and a wide belt course between the first and second stories.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

M:30-12

PERIOD

AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW

- | | | | | |
|---|---|---|---|--|
| <input type="checkbox"/> PREHISTORIC | <input type="checkbox"/> ARCHEOLOGY-PREHISTORIC | <input type="checkbox"/> COMMUNITY PLANNING | <input type="checkbox"/> LANDSCAPE ARCHITECTURE | <input type="checkbox"/> RELIGION |
| <input type="checkbox"/> 1400-1499 | <input type="checkbox"/> ARCHEOLOGY-HISTORIC | <input type="checkbox"/> CONSERVATION | <input type="checkbox"/> LAW | <input type="checkbox"/> SCIENCE |
| <input type="checkbox"/> 1500-1599 | <input type="checkbox"/> AGRICULTURE | <input type="checkbox"/> ECONOMICS | <input type="checkbox"/> LITERATURE | <input type="checkbox"/> SCULPTURE |
| <input type="checkbox"/> 1600-1699 | <input type="checkbox"/> ARCHITECTURE | <input type="checkbox"/> EDUCATION | <input type="checkbox"/> MILITARY | <input type="checkbox"/> SOCIAL/HUMANITARIAN |
| <input type="checkbox"/> 1700-1799 | <input type="checkbox"/> ART | <input type="checkbox"/> ENGINEERING | <input type="checkbox"/> MUSIC | <input type="checkbox"/> THEATER |
| <input type="checkbox"/> 1800-1899 | <input type="checkbox"/> COMMERCE | <input type="checkbox"/> EXPLORATION/SETTLEMENT | <input type="checkbox"/> PHILOSOPHY | <input type="checkbox"/> TRANSPORTATION |
| <input checked="" type="checkbox"/> 1900- | <input type="checkbox"/> COMMUNICATIONS | <input type="checkbox"/> INDUSTRY | <input type="checkbox"/> POLITICS/GOVERNMENT | <input type="checkbox"/> OTHER (SPECIFY) |
| | | <input type="checkbox"/> INVENTION | | |

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

This is an elegant Georgian Revival mansion of the early-20th Century that is no doubt the "queen" of the Rockville Pike estate architecture of that period. It was reportedly built for Carl Corby, whose family made their fortune in Washington building and real estate businesses. It has been owned by a Catholic religious order in recent years, and the Montgomery County government is currently considering purchasing the property for a county arts center.

CONTINUE ON SEPARATE SHEET IF NECESSARY

M. 30-12

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Feasibility study for the acquisition of the Corby Mansion-Mont. Co. government (1975-76).

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE _____ COUNTY _____

STATE _____ COUNTY _____

11 FORM PREPARED BY

NAME / TITLE

Michael F. Dwyer, Senior Park Historian

ORGANIZATION

M-NCPPC

DATE

5/14/75

STREET & NUMBER

8787 Georgia Ave.

TELEPHONE

589-1480

CITY OR TOWN

Silver Spring


STATE

Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438



KENSINGTON, MD.
QUAD

M:30-12
CORBY
MANSION

M:30-12



NAME

CORBY ESTATE

(ESTATE FILE)

30-12

LOCATION

10701 ROCKVILLE PIKE, BETHESDA, MD.

FACADE

NW

PHOTO TAKEN

5/14/75

M. DWYER



M. 30-12

Corby Mansion

front facade



M-30-12

Corby Mansion
Garden facade



M 30-12

Corby Mansion



M 30-12

Corby Mansion



11 30-12

Corby Mansion



No. 30-13

(Cover, East)

Front Portico
Strathmore Hall
Montgomery City.

2/92