

WA-I-506 Brick Bungalow

Early 20th century

Hagerstown Vicinity

Private

The Brick Bungalow is a one and one-half story, three-bay by two-bay house. It has a gable roof with a central dormer. The main facade has a central entrance with a two-bay porch in the southernmost bays.

Magi No.

DOE yes no

Maryland Historical Trust State Historic Sites Inventory Form

1. Name (indicate preferred name)

historic

and/or common Brick bungalow

2. Location

street & number east side of Rt. 65, at intersection with College Road not for publicationcity, town Hagerstown vicinity of congressional district sixth

state Maryland county Washington

3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input checked="" type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input type="checkbox"/> private residence
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input type="checkbox"/> not applicable	<input checked="" type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

4. Owner of Property (give names and mailing addresses of all owners)

name

street & number

telephone no.:

city, town

state and zip code

5. Location of Legal Description

courthouse, registry of deeds, etc. Washington County Courthouse liber

street & number Washington Street folio

city, town Hagerstown

state Maryland

6. Representation in Existing Historical Surveys

title

date

 federal state county local

depository for survey records

city, town

state

7. Description

Survey No. WA-I-506

Condition

excellent
 good
 fair

deteriorated
 ruins
 unexposed

Check one

unaltered
 altered

Check one

original site
 moved date of move _____

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The brick bungalow is a one and one-half story, three-bay by two-bay house. It has a gable roof with a central dormer. The main facade has a central entrance with a two-bay porch in the southernmost bays. The date of construction is early 20th century.

The brick bungalow is located on the east side of Rt. 65 at the intersection with College Avenue. It is part of a farm complex that sits on a slight rise about 1/4 mile off of Rt. 65. The main facade faces west.

The brickwork is stretcher bond. The main facade has a three-section window in the southernmost bay and a two-section window in the northernmost bay. The porch has a hipped roof covered in sheet metal. An interior-end chimney rises from the south gable end.

There are several farm buildings that date from the same time period on the property. There is a concrete block barn with a gable roof. A large silo adjoins the barn. Also, there are rusticated concrete block sheds.

8. Significance

Survey No. WA-I-506


Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/ humanitarian
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> theater
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> transportation
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> other (specify)
		<input type="checkbox"/> invention		

Specific dates	Builder/Architect
-----------------------	--------------------------

check: Applicable Criteria: A B C D
and/or
Applicable Exception: A B C D E F G
Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.

Based on the MHT Survey Matrix, this is a mid-level site. Although of fairly recent construction, the farmhouse and farm buildings represent an early 20th century farm complex.



Funkstown WA-1-506

Fiery Siding
WA-1-506
Brick Bungalow
Funkstown Quad, 1953, PR 1971

Balls Road

Roxbury Sta.

STATE PENAL FARM

Lappans

Cem. St. Marks



1. Brick Bungalow WA-I-506
2. Washington County, Maryland
3. Joe Getty
4. May 1983
5. Maryland Hist. Trust, Annapolis, Md.
6. West Elevation; camera facing east
7. 1/1