

WA-I- 519 Brick Bungalow

1940s

Hagerstown Vicinity

Private

The Brick Bungalow is a one and one-half story, two-bay by three-bay brick structure on a concrete block foundation. It has a gable roof which is slightly flaired to form the roof of the front porch. The roof is covered with asphalt shingles and has a large gable dormer on the front. The main facade consists of the porch with a large side entrance with ornamented door frame and a four-section window. The property has a rectangular plan and appears to have been built in the 1940s.

Maryland Historical Trust State Historic Sites Inventory Form

1. Name (indicate preferred name)

historic Brick bungalow

and/or common

2. Location

street & number west side of Rt. 65, .3 mile south of I-70 not for publication

city, town Hagerstown vicinity of congressional district sixth

state Maryland county Washington

3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input type="checkbox"/> building(s)	<input type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input type="checkbox"/> private residence
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

4. Owner of Property (give names and mailing addresses of all owners)

name

street & number telephone no.:

city, town state and zip code

5. Location of Legal Description

courthouse, registry of deeds, etc. Washington County Courthouse liber

street & number Washington Street folio

city, town Hagerstown state Maryland

6. Representation in Existing Historical Surveys

title

date federal state county local

depository for survey records

city, town state

7. Description

Survey No. WA-I-~~499~~ 519

Condition		Check one	Check one	
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input type="checkbox"/> original site	
<input type="checkbox"/> good	<input type="checkbox"/> ruins	<input type="checkbox"/> altered	<input type="checkbox"/> moved	date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed			

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The brick bungalow is a one and one-half story, two-bay by three-bay brick structure on a concrete block foundation. It has a gable roof which is slightly flaired to form the roof of the front porch. The roof is covered with asphalt shingle and has a large gable dormer on the front. The main facade consists of the porch with a large side entrance with ornamented door frame and a four-section window. The property has a rectangular plan and appears to have been built in the 1940s.

The property is located on the west side of Rt. 65, .3 mile south of I-70. It is situated in a cluster of buildings on $\frac{1}{4}$ to $\frac{1}{2}$ acre lots of land that date from the mid-20th century to the present time.

The bungalow is a brick structure on a concrete block foundation. It has an asphalt shingle covered roof and a brick flue at the north gable end. The main facade has a porch with a stick railing and boxed posts. Within the porch is a doorway with a fanlight. On the roof is a large gabled dormer with a three-section window.

There are no significant outbuildings on the property.

8. Significance

Survey No. WA-I-~~495~~ 519

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/ humanitarian
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> theater
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> transportation
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> other (specify)
		<input type="checkbox"/> invention		

Specific dates

Builder/Architect

check: Applicable Criteria: A B C D
and/or

Applicable Exception: A B C D E F G

Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.

This site contains an excellent example of a mid-20th century bungalow. At the present time, its significance is minimal due to its recent date of construction.



1. Brick Bungalow WA-I-499 519
2. Washington County, Maryland
3. Joe Getty
4. May 1983
5. Maryland Hist. Trust, Annapolis, Md.
6. East Elevation; camera facing west
7. 1/1