

WA-I- 520 Frame Bungalow

Mid-20th century

Hagerstown Vicinity

Private

The Frame Bungalow is a one and one-half story, two-bay by two-bay structure on a concrete foundation. It has a gable roof that flairs out to form the front porch. The building is covered in German siding and has an asphalt shingle roof. The main facade consists of the porch a side entrance with a two-section window in the other bay. A large dormer with a shed roof begins at the peak of the main gable roof on the front of the house.

Maryland Historical Trust State Historic Sites Inventory Form

1. Name (indicate preferred name)

historic Frame bungalow

and/or common

2. Location

street & number west side of Rt. 65, .35 mile south of I-70 not for publication

city, town Hagerstown vicinity of congressional district sixth

state Maryland county Washington

3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input type="checkbox"/> building(s)	<input type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input type="checkbox"/> private residence
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

4. Owner of Property (give names and mailing addresses of all owners)

name _____

street & number _____ telephone no.: _____

city, town _____ state and zip code _____

5. Location of Legal Description

courthouse, registry of deeds, etc. Washington County Courthouse liber

street & number Washington Street folio

city, town Hagerstown state Maryland

6. Representation in Existing Historical Surveys

title _____

date _____ federal state county local

depository for survey records _____

city, town _____ state _____

7. Description

Survey No. WA-I-500 520

Condition		Check one	Check one
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input type="checkbox"/> original site
<input type="checkbox"/> good	<input type="checkbox"/> ruins	<input type="checkbox"/> altered	<input type="checkbox"/> moved date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed		

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The frame bungalow is a one and one-half story, two-bay by two-bay structure on a concrete foundation. It has a gable roof that flairs out to form the front porch. The building is covered in German siding and has an asphalt shingle roof. The main facade consists of the porch a side entrance with a two-section window in the other bay. A large dormer with a shed roof begins at the peak of the main gable roof on the front of the house.

The frame bungalow is located on the west side of Rt. 65, .35 mile south of I-70. It is situated in a cluster of buildings on $\frac{1}{4}$ to $\frac{1}{2}$ acre lots constructed from the middle of this century to the present time.

The bungalow has a gable roof that flairs out to cover the front porch in a typical bungalow fashion. The dormer has two windows each with eight-over-eight pane sash. The main facade otherwise has little modification except for a railing in front of the dormer and modern concrete and iron porch ornamentation. The northernmost side of the house has a small bay extending a few feet from the side of the house. Windows on the sides are similar in shape and construction to those on the front of the house. The shed addition in the rear is one story in height.

There are no significant outbuildings on the property.

8. Significance

Survey No. WA-I-500 520

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates

Builder/Architect

check: Applicable Criteria: A B C D
and/or

Applicable Exception: A B C D E F G

Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.

This site contains an excellent example of a mid-20th century bungalow. Based on the MHT Survey Matrix, this site is minimal due to its recent date of construction.



1. Frame Bungalow WA-I-500-520
2. Washington County, Maryland
3. Joe Getty
4. May 1983
5. Maryland Hist. Trust, Annapolis, Md.
6. East Elevation; camera facing west
7. 1/1