

WA-II-481 Brick Veneer House

Late 19th century

Lappans

Private

This house is a three-bay by one-bay house that appears to have been built in the late 19th century. It was remodeled in mid-20th century with a mult-colored brick veneer. The brick work is done in the beige brick with an occasional brown brick inserted in the stretcher bond pattern. The full-length one-story porch on the main facade is from the period of the remodeling as are the white and brown stripped aluminum awnings. Other elements of the house that appears to be late 19th century are the metal gable roof and the ell with a two-story porch on the inside of the ell.

Maryland Historical Trust State Historic Sites Inventory Form

1. Name (indicate preferred name)

historic

and/or common Brick veneer house

2. Location

street & number west side of Rt. 65, .1 mile north of Lappans Road not for publicationcity, town Lappans vicinity of congressional district sixth

state Maryland county Washington

3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input checked="" type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input type="checkbox"/> private residence
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input type="checkbox"/> not applicable	<input checked="" type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

4. Owner of Property (give names and mailing addresses of all owners)

name

street & number

telephone no.:

city, town

state and zip code

5. Location of Legal Description

courthouse, registry of deeds, etc. Washington County Courthouse liber

street & number Washington Street folio

city, town Hagerstown

state Maryland

6. Representation in Existing Historical Surveys

title

date

 federal state county local

depository for survey records

city, town

state

7. Description

Survey No. WA-II-481

Condition		Check one	Check one
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input type="checkbox"/> original site
<input type="checkbox"/> good	<input type="checkbox"/> ruins	<input type="checkbox"/> altered	<input type="checkbox"/> moved date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed		

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

This house is a three-bay by one-bay house that appears to have been built in the late 19th century. It was remodeled in mid-20th century with a mult-colored brick veneer. The brick work is done in the beige brick with an occasional brown brick inserted in the stretcher bond pattern. The full-length one-story porch on the main facade is from the period of the remodeling as are the white and brown stripped aluminum awnings. Other elements of the house that appears to be late 19th century are the metal gable roof and the ell with a two-story porch on the inside of the ell.

The house is located on the west side of Rt. 65, .1 mile north of Lappans Road, in the Village of Lappans. The house is located close to the crossroads and thus is linked closely with the village. The main facade faces east.

The main facade has a central entrance with one-over-one windows on each side of the entrance. Three two-over-two windows are in the second story. On the sides are one window on each story towards the front of the house and two small windows in the gable end. The roof has a double boxed cornice that slightly returns on the corners. There is a wide interior-end chimney on the north gable end and a smaller chimney on the south gable end both rising from the peak of the roof. The ell has an enclosed porch on the first story and an open porch with stick railing on the second story. The other side of the ell has three windows on the first story and two windows on the second story. The structure is built on a stone foundation.

The property has no significant outbuildings.

8. Significance

Survey No. WA-II-481

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates

Builder/Architect


check: Applicable Criteria: A B C D
and/or

Applicable Exception: A B C D E F G

Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.

This structure has been significantly altered by white brick veneer, a remodeling technique that was popular in the 1950-60s. Otherwise the basic form of the house would make it a contributing building in the Lappans Survey District.



WA-II-481

Fiery Siding

Balls Road

ANTIETAM

CREEK

WA-II-481
Brick Veneer House
Funkstown Quad, 1953, BR 1971

Roxbury Sta

Water Tank

STATE PENAL FARM

Lappans

Cem
St Marks
Ch

Roxbury

Devils
Backbone

Breathedsville

Beaver

Emmertsville

Fairplay

4386
4385
35
4384
4381
2'30"
4380

W 5463 III SE (WILLIAMSPORT)
N 5463 III SE (WILLIAMSPORT)
W 5463 III SE (WILLIAMSPORT)

68

65

63

55

5/4

5/3

50

495

489

63

BM

481

64

500

500

500

500

500

500

OHIO

OHIO

ANR



1. Brick Veneer House WA-II-481
2. Washington County, Maryland
3. Joe Getty
4. May 1983
5. Maryland Hist. Trust, Annapolis, Md.
6. South & east elevations; camera facing
northwest
7. 1/1