

Magi No.

DOE yes no

Maryland Historical Trust State Historic Sites Inventory Form

1. Name (indicate preferred name)

historic Frame house

and/or common

2. Location

street & number south side of Sandy Hook Road, .04 mile east of Clark Road not for publication

city, town Sandy Hook _____ vicinity of _____ congressional district sixth

state Maryland _____ county Washington

3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input checked="" type="checkbox"/> private residence
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input checked="" type="checkbox"/> not applicable	<input checked="" type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

4. Owner of Property (give names and mailing addresses of all owners)

name

street & number _____ telephone no.:

city, town _____ state and zip code _____

5. Location of Legal Description

courthouse, registry of deeds, etc. Washington County Courthouse _____ liber

street & number Washington Street _____ folio

city, town Hagerstown _____ state Maryland

6. Representation in Existing Historical Surveys

title

date _____ federal state county local

depository for survey records

city, town _____ state

7. Description

Survey No. WA-III-087

Condition		Check one	Check one
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input checked="" type="checkbox"/> original site
<input checked="" type="checkbox"/> good	<input type="checkbox"/> ruins	<input checked="" type="checkbox"/> altered	<input type="checkbox"/> moved date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed		

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The frame house is a two-story frame structure constructed in a rectangular plan. It is a three-bay by one-bay structure on a stone foundation. It has a one-story rear addition. The exterior is covered in asphalt shingles. The main facade is symmetrically arranged with a central entrance and a full-length, one-story porch. The structure has a gable roof and interior-end brick chimneys.

The property is located on the south side of Sandy Hook Road, approximately .04 mile east of Clark Road, in Sandy Hook. The house sits slightly back from the road. The main facade faces south.

The two-story structure is constructed of frame covered in asphalt shingles. It is on a rough-laid fieldstone foundation painted white. The main facade is symmetrically arranged with a central entrance. Windows and doors have plain trim with molded cornice. The windows sash is four vertical panes in the upper sash and a single pane in the lower sash. These windows are located in the outer bays of the first story and the three bays of the second story. The full-length, one-story porch has a hipped roof supported by square posts. The porch railing is covered in asphalt shingles. There are corner boards at the corners of the structure. The gable ends have a four-pane window in the gable. The roof has a boxed cornice and is covered in asphalt shingles. Interior-end brick chimneys rise from each gable. The one-story rear addition is constructed of frame covered in vertical board siding. Its exterior appearance reveals all modern materials although a earlier addition might be underneath the modern materials.

There are no significant outbuildings on the property.

8. Significance

Survey No. WA-III-087

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates

Builder/Architect

check: Applicable Criteria: A B C D
and/or

Applicable Exception: A B C D E F G

Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.

This site is a contributing structure in the Sandy Hook Survey District.

FREDERICK & INGTON

COMMONWEALTH OF VIRGINIA
DIVISION OF MINERAL RESOURCES
JAMES L. CALVER, STATE GEOLOGIST

HARPERS FERRY, VA-MD-W VA
QUADRANGLE
USGS 7.5 minute map
1:24 000
1969

767 768 (KEEDYSVILLE) 769





1. WA-III-087
2. Washington Co., Md.
3. Joe Getty
4. ~~April 1983~~ 7/82
5. Md. Hist. Trust, Annapolis, Md.
6. South elev. (camera facing north)
7. 1/1