

(Capsule)

Bungalow, Outbuildings, Chaney Road

The old and modern exist together on this farm with a post and beam tobacco barn and a pre-fabricated 1920's bungalow. The bungalow was popular in the 20's and 30's and this one is typical with its gabled roof and projections, large dormer, deep eaves, and front and back porches.

recent alterations and additions.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

Bungalow, Outbuildings, Chaney Road

AND/OR COMMON

2 LOCATION

STREET & NUMBER

Chaney Road

CITY, TOWN

Chaney

CONGRESSIONAL DISTRICT

___ VICINITY OF

STATE

Maryland

COUNTY

Calvert

3 CLASSIFICATION

CATEGORY

- DISTRICT
- BUILDING(S)
- STRUCTURE
- SITE
- OBJECT

OWNERSHIP

- PUBLIC
- PRIVATE
- BOTH

PUBLIC ACQUISITION

- IN PROCESS
- BEING CONSIDERED

STATUS

- OCCUPIED
- UNOCCUPIED
- WORK IN PROGRESS
- ACCESSIBLE
- YES: RESTRICTED
- YES: UNRESTRICTED
- NO

PRESENT USE

- AGRICULTURE
- MUSEUM
- COMMERCIAL
- PARK
- EDUCATIONAL
- PRIVATE RESIDENCE
- ENTERTAINMENT
- RELIGIOUS
- GOVERNMENT
- SCIENTIFIC
- INDUSTRIAL
- TRANSPORTATION
- MILITARY
- OTHER:

4 OWNER OF PROPERTY

NAME

Telephone #:

STREET & NUMBER

CITY, TOWN

___ VICINITY OF

STATE, zip code

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,
REGISTRY OF DEEDS, ETC.

Liber #:

Folio #:

STREET & NUMBER

CITY, TOWN

STATE

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

___ FEDERAL ___ STATE ___ COUNTY ___ LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

CT-81

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

A neighbor who is in her eighties and with good memory remembers that this house was **pre-fabricated**, brought in sections, and assembled C. 1925. It is empty now and in poor condition.

Bungalows were popular in Calvert County during the 20's and 30's and this is one of two basic types. Where some are nearly square with a hipped roof, this one is somewhat elongated and has a gabled roof. Like most bungalows, the roof has large overhanging eaves, a large dormer and front (S) and back (N) porches. In this instance, the eaves are bracketed.

A distinctive feature of this house are the numerous and different size windows. On the first floor and in the dormer are large-pane triple windows. The glass in these is wavy and large center window with narrower flanking windows is faintly suggestive of "Chicago" windows. In the upper story gables, there are smaller double windows and scattered on the end (E & W) facades are tiny single windows. The obvious effect is a bright interior. The overhanging eaves, an exterior chimney, the dormer and the gabled projection on the west end (dining room) give the building a sculptured or carved out appearance which is quite different from the monolithic appearance which some other buildings have.

Although this style would lend itself to the urban or suburban scene in this instance, it sufficed too for a farm house. Like any farm house of the period, it had dependencies. These have been demolished prior to and since this house was surveyed. Until April of 1976, the fact that there was no interior plumbing was documented by the hand pump out back (N) and the privy which was about 30' off of the northeast corner of the house.

Also behind the house and further to the north was a building which had open construction of a corn house on its west end and the more closed in appearance of a meat house or animal shelter on the other. It was long and narrow with a gabled end roof that also had deep overhanging eaves running the length of the building. The roof was covered with metal. The east gable was covered with vertical butt joined weatherboard and the west gable had open spaced siding, and a loft door.

Approximately fifteen yards east of this building is a tobacco barn which is still in use. Like many barns in this area, it appears large because of its additions and there is a smaller original barn "inside". The original barn in this instance measures 32' x 24'.

It is constructed of hand hewn timbers joined by mortise and tenon with trunnels. The plates are continuous and it has three transverse sills. The third sill divides the barn approximately into 1/3 and 2/3; these sills measure C. 6" x 8" in thickness although the third transverse beam is 11" x 7". There are diagonal braces $3\frac{1}{2}$ " x $6\frac{1}{2}$ " in thickness where each sill joins an upright.

It appears that original hardware is remaining and that original siding is still on the end preserved by a shed (E). Sawed and nailed materials in other portions of the building, underblock stripping room and a new roof suggest

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

2-81

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The old and modern exist together on this farm with a post and beam tobacco barn and a pre-fabricated 1920's bungalow. The bungalow was popular in the 20's and 30's and this one is typical with its gabled roof and projections, large dormer, deep eaves, and front and back porches.

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

11 FORM PREPARED BY

NAME / TITLE

ORGANIZATION

DATE

STREET & NUMBER

TELEPHONE


CITY OR TOWN

STATE

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438



CT-81

ANTERIOR GEOLOGICAL SURVEY WASHINGTON D C
 OWINGS 3.1 MI
 WEST BEACH (JUNC. MD. 261) 7.3 MI

ROAD CLASSIFICATION

BRISTOL, MD.

1957

FMS 601 SW SEP 65 VR33



CT-81

B-3



Bldg. in foreground demolished April, 1976

CT-81

B 7