

T-363

NATIONAL REGISTER OF HISTORIC PLACES
INVENTORY - NOMINATION FORM

(Type all entries - complete applicable sections)

STATE: Maryland	
COUNTY: Talbot	
FOR NPS USE ONLY	
ENTRY NUMBER	DATE

1. NAME

COMMON:
Italianated-on-the-Bay

AND/OR HISTORIC:

2. LOCATION

STREET AND NUMBER:
West side of Rte. 33, north of Wittman, north of St. John's Church

CITY OR TOWN:
Wittman

STATE: Maryland CODE: COUNTY: Talbot CODE:

3. CLASSIFICATION

CATEGORY (Check One)	OWNERSHIP	STATUS	ACCESSIBLE TO THE PUBLIC
District <input type="checkbox"/> Building <input checked="" type="checkbox"/>	Public <input type="checkbox"/> Private <input checked="" type="checkbox"/> Both <input type="checkbox"/>	Occupied <input type="checkbox"/> Unoccupied <input checked="" type="checkbox"/> Preservation work in progress <input type="checkbox"/>	Yes: Restricted <input type="checkbox"/> Unrestricted <input type="checkbox"/> No: <input type="checkbox"/>
Site <input type="checkbox"/> Structure <input type="checkbox"/> Object <input type="checkbox"/>	Public Acquisition: In Process <input type="checkbox"/> Being Considered <input type="checkbox"/>		

PRESENT USE (Check One or More as Appropriate)

Agricultural <input type="checkbox"/>	Government <input type="checkbox"/>	Park <input type="checkbox"/>	Transportation <input type="checkbox"/>	Comments <input type="checkbox"/>
Commercial <input type="checkbox"/>	Industrial <input type="checkbox"/>	Private Residence <input type="checkbox"/>	Other (Specify) <input type="checkbox"/>	_____
Educational <input type="checkbox"/>	Military <input type="checkbox"/>	Religious <input type="checkbox"/>	_____	_____
Entertainment <input type="checkbox"/>	Museum <input type="checkbox"/>	Scientific <input type="checkbox"/>	_____	_____

4. OWNER OF PROPERTY

OWNERS NAME:
Alexander S. Johnson + Katherine L.J. Lyons

STREET AND NUMBER:
Box 66 - 811 Douglas Ave.

CITY OR TOWN: Monroe STATE: Ohio CODE: 45050

5. LOCATION OF LEGAL DESCRIPTION

COURTHOUSE, REGISTRY OF DEEDS, ETC:
Talbot County Courthouse

STREET AND NUMBER:
North Washington Street

CITY OR TOWN: Easton STATE: Maryland CODE:

ACREAGE

APPROXIMATE ACREAGE OF NOMINATED PROPERTY:

6. REPRESENTATION IN EXISTING SURVEYS

TITLE OF SURVEY:

DATE OF SURVEY: Federal State County Local

DEPOSITORY FOR SURVEY RECORDS:

STREET AND NUMBER:

CITY OR TOWN: STATE: CODE:

STATE:
COUNTY:
ENTRY NUMBER
DATE

FOR NPS USE ONLY

7. DESCRIPTION	
CONDITION	<div style="text-align: right; font-size: small;">(Check One)</div> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated <input type="checkbox"/> Ruins <input checked="" type="checkbox"/> Unexposed <input type="checkbox"/>
INTEGRITY	<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <div style="text-align: right; font-size: small;">(Check One)</div> Altered <input checked="" type="checkbox"/> Unaltered <input type="checkbox"/> </div> <div style="width: 45%;"> <div style="text-align: right; font-size: small;">(Check One)</div> Moved <input type="checkbox"/> Original Site <input checked="" type="checkbox"/> </div> </div>
DESCRIBE THE PRESENT AND ORIGINAL (if known) PHYSICAL APPEARANCE	
<p>All that is left of this 18th century house is a brick cellar and four partly stuccoed and plastered walls of the first and second floors. In the mid-19th century the building was raised to two and one-half stories, the floor levels were changed and the east-west gable roof was built with brackets, giving the house an Italianate appearance. At this time the floor plan was changed to the present south stairhall and north parlour. At one time two story additions covered the south side and the south end of the west side. There was a hip roofed porch across the east side.</p> <p>The cellar is entered by an arch through the chimney block on the west side. The north leg of this arch forms part of an east-facing chimney base, while the south leg is the triangular base for a southwest-facing corner chimney. This suggests an original two room floor plan. Two cellar lights on the east each have nine square vertical bars set diagonally in plan, and have three centered arches rising into the watertable on the exterior.</p> <p>The brickwork on the east is Flemish bond and on the south, 3:1 common bond. The original door and window openings have been altered. The east gable end has a door with transom and sidelights on the south leading into the hall. Also there are two 6/6 sash windows on the first floor. There are three 6/6 sash windows on the second floor and two 4/2 sash windows in the upper half story. The windows and door have crude jack arch heads. On the north side there are two windows on the first floor and two on the second.</p> <p>The rebuilt chimney has a small fireplace on the first floor and stove flues on the upper floors. On the second floor there are two bedrooms over the parlour, and a walk-in closet with shelves at the east end of the stairhall. The single attic room sits over the space of the two bedrooms and closet combined. The attic door, with six deep panels, may be the only surviving woodwork from the original house.</p> <p>The mouldings are quirk ogee with chamfer and Greek ovoid. The interior architraves are flat beaded boards with corner blocks.</p> <p>The house is in ruins.</p>	

SIGNIFICANCE

PERIOD (Check One or More as Appropriate)

Pre-Columbian 16th Century 18th Century 20th Century
 15th Century 17th Century 19th Century

SPECIFIC DATE(S) (If Applicable and Known)

AREAS OF SIGNIFICANCE (Check One or More as Appropriate)

Aboriginal	<input type="checkbox"/>	Education	<input type="checkbox"/>	Political	<input type="checkbox"/>	Urban Planning	<input type="checkbox"/>
Prehistoric	<input type="checkbox"/>	Engineering	<input type="checkbox"/>	Religion/Phi-	<input type="checkbox"/>	Other (Specify)	<input type="checkbox"/>
Historic	<input type="checkbox"/>	Industry	<input type="checkbox"/>	lasaphy	<input type="checkbox"/>	_____	
Agriculture	<input type="checkbox"/>	Invention	<input type="checkbox"/>	Science	<input type="checkbox"/>	_____	
Art	<input type="checkbox"/>	Landscape	<input type="checkbox"/>	Sculpture	<input type="checkbox"/>	_____	
Commercer	<input type="checkbox"/>	Architecture	<input type="checkbox"/>	Social/Human-	<input type="checkbox"/>	_____	
Communications	<input type="checkbox"/>	Literature	<input type="checkbox"/>	itarian	<input type="checkbox"/>	_____	
Conservation	<input type="checkbox"/>	Military	<input type="checkbox"/>	Theater	<input type="checkbox"/>	_____	
Architecture	<input checked="" type="checkbox"/>	Music	<input type="checkbox"/>	Transportation	<input type="checkbox"/>	_____	

STATEMENT OF SIGNIFICANCE (Include Personages, Dates, Events, Etc.)

This farmhouse, located near the Bay, is an interesting product of 19th century remodeling of an 18th century brick house. It appears that the building had a "hall and parlour" plan originally, however, this should be re-checked to determine if it indeed had such a plan. Possibly it bears some similarity to Lostock in its original form?!

The remodeled building is also of interest because it is a good example of a late 19th century Italianate house. Unlike most of this period which were built from scratch, the form of this differs due to the fact that part of the base is earlier. It at one time had a porch across its facade and a large addition on its south side.

9. MAJOR BIBLIOGRAPHICAL REFERENCES

10. GEOGRAPHICAL DATA

LATITUDE AND LONGITUDE COORDINATES DEFINING A RECTANGLE LOCATING THE PROPERTY			O R	LATITUDE AND LONGITUDE COORDINATES DEFINING THE CENTER POINT OF A PROPERTY OF LESS THAN ONE ACRE		
CORNER	LATITUDE	LONGITUDE		LATITUDE	LONGITUDE	
	Degrees Minutes Seconds	Degrees Minutes Seconds		Degrees Minutes Seconds	Degrees Minutes Seconds	
NW	° ' "	° ' "		° ' "	° ' "	
NE	° ' "	° ' "		° ' "	° ' "	
SE	° ' "	° ' "		° ' "	° ' "	
SW	° ' "	° ' "		° ' "	° ' "	

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE:	CDDE	COUNTY:	CDDE

11. FORM PREPARED BY

NAME AND TITLE: Michael Bourne, Restoration Consultant & Merry Stinson

ORGANIZATION: Maryland Historical Trust DATE: April, 1977

STREET AND NUMBER: Shaw House, 21 State Circle

CITY OR TOWN: Annapolis STATE: Maryland CDDE:

12. STATE LIAISON OFFICER CERTIFICATION **NATIONAL REGISTER VERIFICATION**

<p>As the designated State Liaison Officer for the National Historic Preservation Act of 1966 (Public Law 89-665), I hereby nominate this property for inclusion in the National Register and certify that it has been evaluated according to the criteria and procedures set forth by the National Park Service. The recommended level of significance of this nomination is:</p> <p>National <input type="checkbox"/> State <input type="checkbox"/> Local <input type="checkbox"/></p> <p>Name _____</p> <p>Title _____</p> <p>Date _____</p>	<p>I hereby certify that this property is included in the National Register.</p> <p>_____ Chief, Office of Archeology and Historic Preservation</p> <p>Date _____</p> <p>ATTEST:</p> <p>_____ Keeper of The National Register</p> <p>Date _____</p>
--	---



11 x 1.14

50% 363

Italianated
east

"Italianated-on-the-Bay"

T-363

M. Stinson



T-363

Italianated
~~east~~ southwest

"Italianated-ON-THE-Bay"

M. Jensen