

1. STATE Maryland
 COUNTY Kent County
 TOWN _____ VICINITY _____
 STREET NO. Spring Avenue

ORIGINAL OWNER _____
 ORIGINAL USE Outbuilding
 PRESENT OWNER Thomas Eliason
 PRESENT USE Vacant
 WALL CONSTRUCTION Brick
 NO. OF STORIES 1

HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY

2. NAME Brick Outbuilding K-74

DATE OR PERIOD 18th Century
 STYLE Colonial
 ARCHITECT _____
 BUILDER _____

3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION OPEN TO PUBLIC NO

This outbuilding belonged to a house which is now destroyed and stands in a parking area. It is a rectangular small building with one door and an "A" roof. It is laid in common bond and in the gable opposite the door is a small window. There is a plain box cornice. The original door and frame are intact but in very bad condition. The sill has rotted and the batten door hangs from only one original hinge. The door has a patten of rose head nails exposed to the weather.

5. PHYSICAL CONDITION OF STRUCTURE Endangered NO Interior Exterior POOR

6. LOCATION MAP (Plan Optional) 7. PHOTOGRAPH

8. PUBLISHED SOURCES (Author, Title, Pages) INTERVIEWS, RECORDS, PHOTOS, ETC.

9. NAME, ADDRESS AND TITLE OF RECORDER
 Michael Bourne
 Maryland Historical Trust

DATE OF RECORD Feb. 15, 1968


SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE



Repairing
County
gent for
illoughby
ver's Au-
r, grind-
ain-fans,
lard Fer-
sale at
e Stock
Teacher.
Dealer.

KENT CO.
Scale 10 Feet to an Inch

No
K-74



KENT COUNTY RAIL ROAD



Chesterbarn

Brick vent building - K-74

609-29

MOB 68



Chestertown -

Outbuilding

K-74

607-211

1703 68



Chestertown

Out building - k-74

607-22

MOB 68



Buttler door with nail heads - outbuilding - K-74

NOB 68

607 - m