

**MARYLAND HISTORICAL TRUST
DETERMINATION OF ELIGIBILITY FORM**

NR Eligible: yes
no

Property Name: Ware Neck Farm Inventory Number: D-110
 Address: 5465 Handley Road Historic district: yes no
 City: Cambridge Zip Code: 21613 County: Dorchester
 USGS Quadrangle(s): Cambridge
 Property Owner: James F. Handley Tax Account ID Number: 002847
 Tax Map Parcel Number(s): 61 Tax Map Number: 31
 Project: US 50: Cambridge Maintenance Shop DO348A21 Agency: State Highway Administration
 Agency Prepared By: EHT Traceries, Inc.
 Preparer's Name: Carrie Albee Date Prepared: 6/13/2006

Documentation is presented in: Michael Bourne, Maryland Historical Trust Worksheet, D-110, 1975; on-site interview with James Handley and Shirley Denton, 25 May 2006; United States Federal Census; FamilySearch.org.

Preparer's Eligibility Recommendation: Eligibility recommended Eligibility not recommended
 Criteria: A B C D Considerations: A B C D E F G

Complete if the property is a contributing or non-contributing resource to a NR district/property:
 Name of the District/Property: _____
 Inventory Number: _____ Eligible: yes no Listed: yes no
 Site visit by MHT Staff yes no Name: _____ Date: _____

Description of Property and Justification: *(Please attach map and photo)*
 Ware Neck Farm is a 52-acre agricultural parcel located in Dorchester County, east of Cambridge. The property, first surveyed by Michael Bourne in 1975, is located at the north end of Handley Road and extends northward to the Choptank River and eastward to Hurst Creek. The primary building on the property is an early-nineteenth-century, brick dwelling that exhibits a number of twentieth-century additions. Several agricultural buildings, including a pump house, smokehouse, corncrib, a grainery, are arranged in a line extending eastward from the rear of the main dwelling. The property is reflective of the nineteenth-century agricultural history of Dorchester County, however, extensive alterations made to the primary dwelling and other changes made to the property have compromised its physical integrity. Based upon the evaluation detailed below, the property is recommended not eligible for listing in the National Register of Historic Places under Criteria A, B, C, or D.

An on-site interview with the current property owner, Mr. James Handley, and his daughter, Ms. Shirley Denton, was conducted by Anne E. Bruder, Architectural Historian with SHA, and Carrie Albee, Architectural Historian with EHT Traceries, Inc., on Thursday, May 25, 2006. In this interview, Mr. Handley outlined what he knew of the history of the property, beginning with Margaret Spriggs, who was said to have owned the property in the eighteenth century. Mr. Handley indicated that his family

MARYLAND HISTORICAL TRUST REVIEW	
Eligibility recommended <input type="checkbox"/>	Eligibility not recommended <input checked="" type="checkbox"/>
Criteria: <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	Considerations: <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G
MHT Comments:	
<u>Jim Tuley</u> Reviewer, Office of Preservation Services	<u>8/4/06</u> Date
<u>[Signature]</u> Reviewer, National Register Program	<u>8/7/06</u> Date

acquired the property in the late nineteenth century. He stated that the property was given to his grandparents, James P. Handley and Sarah C. Handley, by Sarah C. Handley's parents as a wedding gift. Genealogical research confirmed that James P. Handley and Sarah Cornelia Seward were married on January 18, 1882 (FamilySearch.org). The property has remained in the family since that time. His father, Raymond, was born on the property around 1892. At her death, Sarah C. Handley divided the property, then approximately 360 acres, roughly evenly between six children, with each child inheriting approximately 60 acres. The current 52 acres is the remaining portion of the 60 acres that Mr. James Handley's father received of the original 360 acres.

Subdivision of the Ware Neck Farm in the twentieth century resulted in the greatest period of growth of a small residential enclave known as Jacktown, located to the south along Old Route 50. The unplanned development of Jacktown includes a number of dwellings that are similar in form and/or detailing, suggesting the influences of several speculative developers or builders. Between 1920 and 1945, approximately twenty-five (25) single-family dwellings had been constructed in Jacktown, primarily along Moose Lodge Road and Old Route 50. Infill development took place in the middle part of the twentieth century. This was sparked by the establishment of better roads that brought tourists to the region and allowed residents to transverse the county, thus providing an opportunity for better jobs. Additionally, the subdivision and ultimate sale of acres historically associated with the farm resulted in the construction of additional single-family houses to the south of the main Federal-era house. The vast majority of the construction between 1945 and 1975 occurred in the 1950s, when Ware Neck Farm was subdivided. Moreover, the subdivision resulted in the construction of four residential buildings constructed along Sand Road to the immediate northwest of Ware Neck Farm. The dwellings, dating from circa 1930 to 1979, were constructed by members of the Handley family. The family continues to own the property, leasing two of the four parcels.

The property was evaluated for eligibility for the National Register of Historic Places under Criterion A as an agricultural property reflective of the significant agricultural history and character of Dorchester County. The 52-acre parcel remains largely employed in agricultural production, currently soybeans and sunflowers. Several historic agricultural outbuildings remain intact on the property, arranged in a line extending east from the original dwelling. Among these are a pump house, a smokehouse, a corncrib, and a grainery. However, these outbuildings are no longer central to the operation of the farm. Further, several non-historic outbuildings are also present, including a large implement or tractor shed. Although the remaining 52 acres still retains its open, agricultural character and direct physical relationship with the Choptank River and Hurst Creek, the physical integrity of the property has been substantially diminished by the mid- and late-twentieth-century residential development of Jacktown and the buildings on Sand Road. Several non-historic dwellings are located immediately to the west and east of the property, and directly south of the farm are light-industrial operations. The later construction and non-sympathetic uses have compromised the integrity of location, setting, design, and feeling of the agricultural property. Thus, Ware Neck Farm is not eligible for the National Register of Historic Places under Criterion A.

The property was evaluated for eligibility for the National Register of Historic Places under Criterion B for its association with the Handley family. The current owner indicated that the property had come into the Handley family at the marriage of James P. Handley to Sarah Cornelia Seward, which took place in 1882, and has remained in the family since that time. The Handley family has been in Dorchester County since at least the first federal census in 1790. However, no historical significance is known to be attributed to the Handley family. The current property owner also indicated that the original owner of the property was Margaret Spriggs. Spriggs was not identified through basic research into census and genealogical sources, and she has no known historical significance. Therefore, Ware Neck Farm is disqualified for listing in the National Register of Historic Places under Criterion B.

The property was evaluated for eligibility for the National Register of Historic Places under Criterion C as an early-nineteenth-century dwelling. Although the main block of the early-nineteenth-century structure is intact and visually distinguishable, the dwelling as currently configured has been extensively altered on both the exterior and the interior. A two-story brick addition was constructed onto the west elevation of the original main block of the building in the early twentieth century. Further substantial

MARYLAND HISTORICAL TRUST REVIEW	
Eligibility recommended _____	Eligibility not recommended _____
Criteria: ___A ___B ___C ___D	Considerations: ___A ___B ___C ___D ___E ___F ___G
MHT Comments:	
_____	_____
Reviewer, Office of Preservation Services	Date
_____	_____
Reviewer, National Register Program	Date

mid- and late-twentieth-century wood-frame additions are present on the north and east elevations of the masonry structure. An early-twentieth-century photograph of the dwelling, in the possession of the current owner, shows the building as it looked prior to these additions. A one-story wood-frame kitchen wing on the east elevation is shown in the photograph, but this wing was removed in the construction of the existing two-story east addition. The late-nineteenth-century one-story porch depicted in the photograph has also been removed and replaced with a late-twentieth-century portico. The extensive alterations to the primary dwelling have resulted in a loss of integrity of design, materials, workmanship, and feeling sufficient for listing in the National Register of Historic Places under Criterion C.

The property was not evaluated for eligibility for the National Register of Historic Places under Criterion D for its information potential. Based upon the research undertaken and the on-site, above-ground investigation, the property is not known to have any significance under Criterion D.

MARYLAND HISTORICAL TRUST REVIEW

Eligibility recommended _____ Eligibility not recommended _____

Criteria: ___A ___B ___C ___D Considerations: ___A ___B ___C ___D ___E ___F ___G

MHT Comments:

Reviewer, Office of Preservation Services

Date

Reviewer, National Register Program

Date

MARYLAND INVENTORY OF HISTORIC PROPERTIES
ADDENDUM

MIHP Number: D-110

Property Name: Ware Neck Farm
Property Address: 5465 Handley Road, Cambridge, MD 21613

Surveyor: Anne E. Bruder, SHA
Carrie Albee, EHT Tracerics, Inc.

Survey Date: May 25, 2006

This addendum provides an additional physical description of the primary dwelling and associated secondary structures on the site, as well as history of the property derived from an interview with the current property owner, Mr. James F. Handley, and his daughter, Shirley Denton.

Section 7: Description

The 52-acre parcel is located at the north end of Handley Road, and extends north to the Choptank River and east to Hurst Creek. The property is currently planted with soybeans and sunflowers. A fenced paddock for horses is also present, located to the east of the dwelling.

The primary dwelling on the site appears to date to the late eighteenth or early nineteenth century. The original main block of the house was constructed as a two-and-a-half-story, side-gable structure of brick with a two-bay-wide façade facing south. The façade now features a one-story portico that appears to have been added in the latter part of the twentieth century. The single-bay brick addition, standing two stories in height with a side-gabled roof, was built during the early twentieth century on the west elevation of the main block. This addition gives the main block of the building a central-entry plan, rather than the side-entry plan as originally constructed. It has a brick interior chimney at the west end. Projecting from the east elevation is a large two-story, wood-frame addition with a steeply pitched side-gabled roof. The addition, reflecting influences of the Victorian-era, is finished with overhanging boxed cornices with an ogee-molded profile, raked cornice in the gable ends, and returns. A tall corbelled interior brick chimney projects from the roof at the east end. Based on the form, chimney, and cornice, this addition appears to have been added in the late-nineteenth century. A two-story, wood-frame addition with a shed roof projects from the south elevation of this addition, obscuring any Victorian-era ornamentation and fenestration on the addition's façade. This shed roof addition appears to date to the 1960s or 1970s. The foundation of the Victorian-era addition has been parged, presumably to obscure the construction of the shed-roofed addition. Both the Victorian-era addition and the shed-roofed addition are clad in aluminum siding and have 1/1 metal-sash windows and 12/12 windows.

Additionally, the fenestration on the north elevation of the Victorian-era addition has been altered and obscured by the application of the aluminum siding. The second story currently has a fixed picture window flanked by 1/1 metal-sash windows, and paired metal casement windows. A secondary entry has been created from a former window opening on the second story of the east side elevation of the Victorian-era addition. A wood-frame, flat-roof bedroom suite addition, dating to the 1960s or 1970s, extends from the north rear elevation. Set on a solid masonry foundation of concrete, the addition is clad in aluminum siding.

While on site, the property owner produced a black-and-white photograph of the dwelling, apparently taken around the turn of the twentieth century. The photograph showed the dwelling prior to the construction of any of the additions described above. The house had a one-story, side-gable wing on the east side elevation, described by the current property owner as a "summer kitchen" that was demolished when the current east addition was constructed. The kitchen wing was once a freestanding three-bay-wide structure connected to the main block of the building by a one-story addition. Also present was a one-story porch that wrapped around the southwest corner and featured decorative millwork characteristic of the late nineteenth century.

The 1975 survey form described the building as having 9/6 windows on the first story and 6/6 windows on the second story. However, on-site investigation indicated that the oldest portion of the building has 6/6 windows, and the early-twentieth-century west addition has 12/8 windows. Later twentieth-century additions have 1/1 windows.

The interior of the dwelling, as noted in the 1975 survey, was extensively renovated in the early twentieth century, presumably with the construction of the west addition. The stair hall is located in the rear of the main block, rather than directly across from the main entrance. Ms. Denton indicated that this stair may have been moved. The dining room features a chair rail. The dining room and parlor are separated by an arched opening, and the two rooms have matching fireplaces and chimneys on the east wall. These fireplaces, and one in the west bedroom, have been boarded up. Each wood fireplace surround is unique in form. Wood floors appear to be original, including the wood floor in the west addition.

The second floor features four bedrooms arranged around the stair landing. The flooring is not original. Ms. Denton indicated that the flooring had been removed for repair and then was lost in a hurricane flood and had subsequently been replaced. The locations of the three fireplaces on the second floor correspond to those of the first floor. A stair leading from the landing to the attic is present on the north side of the dwelling. Access to the apartment over the present kitchen is gained through the northeast bedroom. According to Ms. Denton, the attic and basement each have three rooms.

Arranged in a line extending east from the dwelling is a series of associated outbuildings. Closest to the house is a one-story, wood-frame pump house, and east of that is a one-story wood-frame smokehouse. These two buildings are similar in appearance, with front-gabled, asphalt-shingled roofs and flush, vertical-board cladding, and may date to

the late nineteenth or early twentieth century. East of the smokehouse is a one-story, concrete-block garage dating to the mid-twentieth century. Mr. Handley indicated that this garage replaced an earlier wood shed. East of the garage is one-story, wood-frame corncrib, possibly dating to the late nineteenth century. East of the corncrib is a one-story, prefabricated shed. East of the shed is a large wood-frame, side-gable building described by Mr. Handley as a grainery. Exterior investigation of the grainery revealed pegged rafters and metal strap-hinges on the south door consistent with a late-eighteenth- or early-nineteenth-century date of construction. East of the grainery is a one-story implement or tractor shed dating to the 1960s, according to Mr. Handley. East of the implement shed and completing the row is a large wood-frame livestock barn that appears to date to the early twentieth century.

Section 8: Significance

An on-site interview with the current property owner, Mr. James Handley, and his daughter, Ms. Shirley Denton, was conducted by Anne E. Bruder, Architectural Historian with SHA, and Carrie Albee, Architectural Historian with EHT Tracerics, Inc., on Thursday, May 25, 2006. In this interview, Mr. Handley outlined what he knew of the history of the property, beginning with Margaret Spriggs, part Native American, who was said to have had the primary dwelling constructed on the property in the eighteenth century. Mr. Handley indicated that his family acquired the property in the late nineteenth century. He stated that the property was given to his grandparents, James P. Handley and Sarah C. Handley, by Sarah C. Handley's parents as a wedding gift. Genealogical research confirmed that James P. Handley and Sarah Cornelia Seward were both born circa 1860 and were married on January 18, 1882.¹ The property has remained in the family since that time. His father, Raymond, was born on the property in 1892, and his mother was born in the early twentieth century (HeritageQuestOnline.com).² At her death, Sarah C. Handley divided the property, then approximately 360 acres, roughly evenly between six children, with each child inheriting approximately 60 acres. The current 52 acres is the remaining portion of the 60 acres that Mr. James Handley's father received of the original 360 acres.

When asked about the origin of the name "Ware Neck Farm," the name attributed to the property on the 1975 survey form, Mr. Handley indicated that he had never heard the name used to describe his property and that he did not know to what the name referred.


¹ Genealogical Search, FamilySearch.org, 13 June 2006.

² Information taken from the 1900 and 1930 US Census, HeritageQuestOnline.com, through Enoch Pratt Free Library website, accessed 26 May 2006.

D-110
Ware Neck Farm
5465 Handley Road
Baltimore Co., MD
5-25-2006



First Floor




Not to Scale

D-110
Ware Neck Farm
5465 Handley Road
Chester Co., MD
9-25-2006




Second Floor





District - 14 Account Number - 002847




Property maps provided courtesy of the Maryland Department of Planning ©2004.
For more information on electronic mapping applications, visit the Maryland Department of Planning
web site at www.mdp.state.md.us/webcom/index.html

Ware Neck Farm (D-110)
5465 Handley Road
Cambridge, Dorchester County, Maryland
Map 31 Parcel 61

Ware Neck Farm (D-110)
5465 Handley Road
Cambridge, Dorchester County, Maryland

Cambridge USGS Map

North ↑





D-110

Ware Neck Farm

5465 Handley Road

Dorchester Co., MD

EHT Traceries

5-25-2006

MDSHPO

Main House View NE

#1 of 7



D-110

Ware Neck Farm

5465 Handley Road

Dorchester Co., MD

EHT Traceries

5-25-2006

MDSHPO

Main House, South Facade.

#2 of 7



D-110

Ward Neck Farm
5465 Handley Road
Dorchester Co., MD

EHT Traceries

5-25-2000

MDSHPD

Main House, View W

#3 of 7



D-110

Wave Neck Farm

5465 Hambley Road

Dorchester Co., MD

EHT Traceries

S-25-2006

MDSHPO

Main House, View SE

#4 of 7



D-110

Ware Neck Farms
5465 Handley Road
Dorchester Co., MD

EHT Traceries

5-25-2006

MDSHP0

Outbuildings, View NE
#5 of 7



D-110
Ware Neck Farm
5465 Handley Road
Dorchester Co., MD
EHT Traceries
5-25-2006
MDSHPO
Outbuildings, View SE
#6 of 7



D-110

Ware Neck Farm
5465 Handley Road
Dorchester Co., MD
EHT Traceries
5-25-2006

MDSHDC

Agricultural Fields, View N to Choptank River

#7 of 7

MARYLAND HISTORICAL TRUST WORKSHEET

NOMINATION FORM
for the
NATIONAL REGISTER OF HISTORIC PLACES, NATIONAL PARKS SERVICE

SEE INSTRUCTIONS

1. NAME

COMMON:
Ware Neck Farm

AND/OR HISTORIC:

2. LOCATION

STREET AND NUMBER:
Old Rt. 50, .5 miles east of Bucktown Rd, & Rt. 50, NE, .6 mi.

CITY OR TOWN:
Cambridge

STATE: Maryland COUNTY: Dorchester

3. CLASSIFICATION

CATEGORY (Check One)		OWNERSHIP		STATUS	ACCESSIBLE TO THE PUBLIC
<input type="checkbox"/> District	<input checked="" type="checkbox"/> Building	<input type="checkbox"/> Public	Public Acquisition:	<input checked="" type="checkbox"/> Occupied	Yes:
<input type="checkbox"/> Site	<input type="checkbox"/> Structure	<input checked="" type="checkbox"/> Private	<input type="checkbox"/> In Process	<input type="checkbox"/> Unoccupied	<input type="checkbox"/> Restricted
	<input type="checkbox"/> Object	<input type="checkbox"/> Both	<input type="checkbox"/> Being Considered	<input type="checkbox"/> Preservation work in progress	<input type="checkbox"/> Unrestricted
PRESENT USE (Check One or More as Appropriate)					
<input checked="" type="checkbox"/> Agricultural	<input type="checkbox"/> Government	<input type="checkbox"/> Park	<input type="checkbox"/> Transportation	<input type="checkbox"/> Comments	
<input type="checkbox"/> Commercial	<input type="checkbox"/> Industrial	<input checked="" type="checkbox"/> Private Residence	<input type="checkbox"/> Other (Specify)	_____	
<input type="checkbox"/> Educational	<input type="checkbox"/> Military	<input type="checkbox"/> Religious	_____	_____	
<input type="checkbox"/> Entertainment	<input type="checkbox"/> Museum	<input type="checkbox"/> Scientific	_____	_____	

4. OWNER OF PROPERTY

OWNER'S NAME:
Raymond Handley

STREET AND NUMBER:
RFD 2

CITY OR TOWN: Cambridge STATE: Maryland 21613

5. LOCATION OF LEGAL DESCRIPTION

COURTHOUSE, REGISTRY OF DEEDS, ETC:
Dorchester County Courthouse

STREET AND NUMBER:
High Street

CITY OR TOWN: Cambridge STATE: Maryland 21613

Title Reference of Current Deed (Book & Pg. #): 100/311

6. REPRESENTATION IN EXISTING SURVEYS

TITLE OF SURVEY:

DATE OF SURVEY: Federal State County Local

DEPOSITORY FOR SURVEY RECORDS:

STREET AND NUMBER:

CITY OR TOWN: STATE:

7. DESCRIPTION

CONDITION	(Check One)					
	<input type="checkbox"/> Excellent	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Deteriorated	<input type="checkbox"/> Ruins	<input type="checkbox"/> Unexposed
	(Check One)			(Check One)		
	<input checked="" type="checkbox"/> Altered	<input type="checkbox"/> Unaltered	<input type="checkbox"/> Moved	<input checked="" type="checkbox"/> Original Site		

DESCRIBE THE PRESENT AND ORIGINAL (if known) PHYSICAL APPEARANCE

The house at Ware Neck is one of the significant Federal farmhouses along the Choptank River. It is a two bay square building with a one bay, two story wing on the west and a three bay, two story wing on the east.

Flemish bond was used on the south wall of the two bay portion (the earliest part). Its windows have 9/6 on the first story and 6/6 on the second story. The entrance on the west side has a simple porch of twentieth century date. On the east gable the chimneys are connected by a curtain wall above the roof giving the impression of great mass. It is very similar to 204 High Street, Cambridge as well as the Mitchell House, Kent County.

The west addition was built around the turn of the century and is laid in Common bond. It consists of one room on each of the two floors. Its windows have segmental arches and 2/2 sash. The entire building has been painted barn red.

The interior consists of a central stair hall with two rooms on the east, in the original section, and one room on the west. Two rooms and porch are included in the east wing. Original trim exists in good state of preservation in the oldest part of the house.

SEE INSTRUCTIONS

8. SIGNIFICANCE			
PERIOD (Check One or More as Appropriate)			
<input type="checkbox"/> Pre-Columbian	<input type="checkbox"/> 16th Century	<input type="checkbox"/> 18th Century	<input type="checkbox"/> 20th Century
<input type="checkbox"/> 15th Century	<input type="checkbox"/> 17th Century	<input checked="" type="checkbox"/> 19th Century	
SPECIFIC DATE(S) (If Applicable and Known)			
AREAS OF SIGNIFICANCE (Check One or More as Appropriate)			
<input type="checkbox"/> Aboriginal	<input type="checkbox"/> Education	<input type="checkbox"/> Political	<input type="checkbox"/> Urban Planning
<input type="checkbox"/> Prehistoric	<input type="checkbox"/> Engineering	<input type="checkbox"/> Religion/Phi-	<input type="checkbox"/> Other (Specify)
<input type="checkbox"/> Historic	<input type="checkbox"/> Industry	losophy	_____
<input type="checkbox"/> Agriculture	<input type="checkbox"/> Invention	<input type="checkbox"/> Science	_____
<input checked="" type="checkbox"/> Architecture	<input type="checkbox"/> Landscape	<input type="checkbox"/> Sculpture	_____
<input type="checkbox"/> Art	Architecture	<input type="checkbox"/> Social/Human-	_____
<input type="checkbox"/> Commerce	<input type="checkbox"/> Literature	itarian	_____
<input type="checkbox"/> Communications	<input type="checkbox"/> Military	<input type="checkbox"/> Theater	_____
<input type="checkbox"/> Conservation	<input type="checkbox"/> Music	<input type="checkbox"/> Transportation	_____
STATEMENT OF SIGNIFICANCE			
<p>Ware Neck is significant architecturally for its represents the late Federal period farmhouse with later extensions. It is one of few houses of the period which exist along the Choptank River east of Cambridge. Its interior is also noteworthy.</p> <p>Locally, it is considered of significance since the tract was owned by some of the prominent early families of Dorchester County. The Laskowski Papers, however, fail to identify the proper sequence of owners and thus it would be necessary to re-run the chain of title, in order to establish the owner/builder.</p>			

SEE INSTRUCTIONS

9. MAJOR BIBLIOGRAPHICAL REFERENCES

Laskowski Papers, 1955, p. 313

10. GEOGRAPHICAL DATA

LATITUDE AND LONGITUDE COORDINATES DEFINING A RECTANGLE LOCATING THE PROPERTY				O R	LATITUDE AND LONGITUDE COORDINATES DEFINING THE CENTER POINT OF A PROPERTY OF LESS THAN TEN ACRES				
CORNER	LATITUDE				LONGITUDE				
	Degrees	Minutes	Seconds	Degrees	Minutes	Seconds	Degrees	Minutes	Seconds
NW	°	'	"	°	'	"	°	'	"
NE	°	'	"	°	'	"	°	'	"
SE	°	'	"	°	'	"	°	'	"
SW	°	'	"	°	'	"	°	'	"

APPROXIMATE ACREAGE OF NOMINATED PROPERTY:

Acreage Justification:

District 14, Map 31, p. 61

SEE INSTRUCTIONS

11. FORM PREPARED BY

NAME AND TITLE: Michael Bourne, Architectural Consultant		DATE Nov., 1975
ORGANIZATION Maryland Historical Trust		
STREET AND NUMBER: Shaw House, 21 State Circle		
CITY OR TOWN: Annapolis	STATE Maryland	21401

12. State Liaison Officer Review: (Office Use Only)

Significance of this property is:

National State Local

Signature _____

.12 X 1.54

100%

D-110



Ware Neck Farm (taken from Eldon Wharf)

D-110

M. Bowne Nov 1975