

QA-42
Charles Vonville Farm
Sudlersville vicinity
Private

circa 1830-50

The Vonville House is one of perhaps 50 gambrel roof dwellings recorded in this county. This popular roof form is combined with a center passage, single pile plan and a two part wing. The gambrel roof of the west half of the wing is an unusual feature and may be a later alteration. The Greek Revival interior trim suggests a date of construction of circa 1830-50. The east end of the wing loft was probably originally a segregated chamber with access only from the kitchen. This loft is no longer accessible.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

AND/OR COMMON

Charles Vonville Farm

2 LOCATION

STREET & NUMBER

North side Race Track Road

CITY, TOWN

Sudlersville

VICINITY OF

CONGRESSIONAL DISTRICT

1st

STATE

Maryland

COUNTY

Queen Anne's

3 CLASSIFICATION

| CATEGORY | OWNERSHIP | STATUS | PRESENT USE |
|---|---|---|---|
| <input type="checkbox"/> DISTRICT | <input type="checkbox"/> PUBLIC | <input checked="" type="checkbox"/> OCCUPIED | <input type="checkbox"/> AGRICULTURE |
| <input checked="" type="checkbox"/> BUILDING(S) | <input checked="" type="checkbox"/> PRIVATE | <input type="checkbox"/> UNOCCUPIED | <input type="checkbox"/> MUSEUM |
| <input type="checkbox"/> STRUCTURE | <input type="checkbox"/> BOTH | <input type="checkbox"/> WORK IN PROGRESS | <input type="checkbox"/> COMMERCIAL |
| <input type="checkbox"/> SITE | PUBLIC ACQUISITION | ACCESSIBLE | <input type="checkbox"/> EDUCATIONAL |
| <input type="checkbox"/> OBJECT | <input type="checkbox"/> IN PROCESS | <input checked="" type="checkbox"/> YES: RESTRICTED | <input checked="" type="checkbox"/> PRIVATE RESIDENCE |
| | <input type="checkbox"/> BEING CONSIDERED | <input type="checkbox"/> YES: UNRESTRICTED | <input type="checkbox"/> ENTERTAINMENT |
| | | <input type="checkbox"/> NO | <input type="checkbox"/> RELIGIOUS |
| | | | <input type="checkbox"/> GOVERNMENT |
| | | | <input type="checkbox"/> INDUSTRIAL |
| | | | <input type="checkbox"/> MILITARY |
| | | | <input type="checkbox"/> OTHER |

4 OWNER OF PROPERTY

NAME

Avondale Ltd.

Telephone #:

STREET & NUMBER

RT#2, Box 742

CITY, TOWN

Chestertown

___ VICINITY OF

STATE, zip code

Maryland 21620

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,

REGISTRY OF DEEDS, ETC. Queen Anne's County Courthouse

Liber #: MWM 169

Folio #: 153

STREET & NUMBER

Courthouse Square

CITY, TOWN

Centreville

STATE

Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

___ FEDERAL ___ STATE ___ COUNTY ___ LOCAL

DEPOSITORY FOR SURVEY RECORDS

CITY, TOWN

STATE

QA-42

7 DESCRIPTION

| CONDITION | | CHECK ONE | CHECK ONE |
|--|---------------------------------------|---|---|
| <input type="checkbox"/> EXCELLENT | <input type="checkbox"/> DETERIORATED | <input type="checkbox"/> UNALTERED | <input checked="" type="checkbox"/> ORIGINAL SITE |
| <input type="checkbox"/> GOOD | <input type="checkbox"/> RUINS | <input checked="" type="checkbox"/> ALTERED | <input type="checkbox"/> MOVED DATE _____ |
| <input checked="" type="checkbox"/> FAIR | <input type="checkbox"/> UNEXPOSED | | |

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Vonville Farm is located on the north side of Race Track Road approximately one mile east of Elevator Road and two miles southeast of Sudlersville.

The house on the Vonville Farm is of frame construction, 1 1/2 stories high, three bays wide and one room deep, with a single flush chimney at the east end of the gambrel roof. An original chimney on the west gable wall has been removed. A small story-and-a-half wing extends one bay to the east, with a gambrel roof set slightly lower than the roof of the main house. A second small wing with a pitched gable roof extends to the east.

The principal facade of the main house faces south to the road. The door is offset to left of center with a four-light transom above, one 6/6 to the west and another 6/6 to the east. There are three 6/6 shed roof dormers on the second floor. These are symmetrically placed on the roof, in contrast to the asymmetry of the first floor openings.

The building rests on a continuous foundation of concrete block and is covered with asbestos siding, a plain box cornice and asphalt shingle roofing.

CONTINUE ON SEPARATE SHEET IF NECESSARY

CONTINUATION SHEET

7.1 DESCRIPTION

There are no openings in the west gable wall. The rakeboards have been removed; the siding is asbestos shingle.

On the rear or north facade, there is a single door without transom offset to right of center, and one 6/6 window to east and west on the first floor. Three 6/6 shed roof dormers are ranged across the second story. A bulkhead cellar entrance is located under the east window. The foundation, siding, cornice and roof all match the front facade. The door on this facade is an unusual three-panel example with flattened Greek ogee panel molds.

The east gable wall is almost entirely concealed by the wing.

The south facade of the gambrel roof wing has no original openings on the first floor. A 6/6 shed roof dormer is centered on the second story. The east gable wall is covered by the later wing. On the north facade, there is a door in the east bay and a 6/6 window in the west bay, with a single 6/6 shed dormer centered on the second story.

The later wing has a 6/6 window in the center of each facade. On the south gable wall, a single 6/6 window is located in the south bay of the first story; there are two four-light windows in the upper gable.

CONTINUATION SHEET

7.2 DESCRIPTION

The interior of the main house originally consisted of a center passage plan. The wall between the center stair passage and the west room has been opened up and now consists of a wide door opening framed with turn-of-the-century posts and low paneled knee walls. A patch in the west wall of the west room clearly indicates the location of the demolished gable chimney. Beaded baseboard and Greek Revival window trim survives in this room and the stair passage; the architrave trim also survives in the east room. This trim consists of "paneled" fascia pieces with flattened Greek ogee panel molds with a flat band in between and plain corner blocks. The stair rises against the east wall of the passage. It is an open-string stair with a turned newel, a simple rail and square section balusters. A beaded batten door with Greek architrave trim opens into a closet under the stair with original beaded shelving.

On the second floor, the center passage is partitioned to form a small, unheated chamber to the south. This small chamber also provided the only access to the east room. A door was later cut through from the east room to the stair landing, permitting more privacy. A door in the east wall of the east room may always have provided the only access to the wing. The trim on this door is the same Greek ogee molding found on all of

CONTINUATION SHEET

7.3 DESCRIPTION

the second floor door openings. Seams in the floor of the west room outline the position of the demolished west chimney. A small opening in the ceiling of the passage chamber permits a limited view of the roof.

The first story of the two wings has been renovated and opened up for a modern kitchen. The second floor of the gambrel wing consists of a single room, with the only access from the east room of the main house. The loft of the pitched roof wing has been sealed off. From the back porch, part of the loft interior is visible. The rafters are smoke-blackened and show evidence of whitewash, and it seems probable this loft was a segregated room with separate access via a steep ladder-type stair.

| PERIOD | AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW | | | |
|---|--|---|---|--|
| <input type="checkbox"/> PREHISTORIC | <input type="checkbox"/> ARCHEOLOGY-PREHISTORIC | <input type="checkbox"/> COMMUNITY PLANNING | <input type="checkbox"/> LANDSCAPE ARCHITECTURE | <input type="checkbox"/> RELIGION |
| <input type="checkbox"/> 1400-1499 | <input type="checkbox"/> ARCHEOLOGY-HISTORIC | <input type="checkbox"/> CONSERVATION | <input type="checkbox"/> LAW | <input type="checkbox"/> SCIENCE |
| <input type="checkbox"/> 1500-1599 | <input type="checkbox"/> AGRICULTURE | <input type="checkbox"/> ECONOMICS | <input type="checkbox"/> LITERATURE | <input type="checkbox"/> SCULPTURE |
| <input type="checkbox"/> 1600-1699 | <input checked="" type="checkbox"/> ARCHITECTURE | <input type="checkbox"/> EDUCATION | <input type="checkbox"/> MILITARY | <input type="checkbox"/> SOCIAL/HUMANITARIAN |
| <input type="checkbox"/> 1700-1799 | <input type="checkbox"/> ART | <input type="checkbox"/> ENGINEERING | <input type="checkbox"/> MUSIC | <input type="checkbox"/> THEATER |
| <input checked="" type="checkbox"/> 1800-1899 | <input type="checkbox"/> COMMERCE | <input type="checkbox"/> EXPLORATION/SETTLEMENT | <input type="checkbox"/> PHILOSOPHY | <input type="checkbox"/> TRANSPORTATION |
| <input checked="" type="checkbox"/> 1900- | <input type="checkbox"/> COMMUNICATIONS | <input type="checkbox"/> INDUSTRY | <input type="checkbox"/> POLITICS/GOVERNMENT | <input type="checkbox"/> OTHER (SPECIFY) |
| | | <input type="checkbox"/> INVENTION | | |

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The Vonville House is one of perhaps 50 gambrel roof dwellings recorded in this county. This popular roof form is combined with a center passage, single pile plan and a two part wing. The gambrel roof of the west half of the wing is an unusual feature and may be a later alteration. The Greek Revival interior trim suggests a date of construction of circa 1830-50. The east end of the wing loft was probably originally a segregated chamber with access only from the kitchen. This loft is no longer accessible.

CONTINUE ON SEPARATE SHEET IF NECESSARY

QA-42

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE COUNTY

STATE COUNTY

11 FORM PREPARED BY

NAME / TITLE

Orlando Ridout V, Historic Sites Surveyor

ORGANIZATION

Queen Anne's County Historical Society

DATE

10/16/81

STREET & NUMBER

TELEPHONE

CITY OR TOWN

Centreville

STATE


Maryland

Field Notebook QA-25; Recorded June 23, 1980.

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438



MILLINGTON

RIVER

Unicorn

Hackett Corners

Stevens Corners

Rondtown

Dudley Corners

Sudlersville

Duhamel Corners

Peters Corners

Benton Corners

F I R S T

QA-42
Charles Vonville Farm

Schenk Corners

Stevens Corner

St Daniels Ch

Barclay

Maryin Memorial Ch

Carson Corners

Cleaves Forks

Kane Crossroads



QA-42

Charles Vonville Farm
Sudlersville vicinity
Orlando Ridout V 1981
Rear facade from north



QA-42

Charles Vonville Farm
Sudlersville vicinity
Orlando Ridout V 1981
Front facade from south