

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Survey No. M: 23-150

1. Name of Property (indicate preferred name)

historic

other House Ruin on Howard Chapel Road

2. Location

street & number Howard Chapel Road (Next to the Patuxent River)

not for publication

city, town Unity

vicinity

county Montgomery County

3. Owner of Property (give names and mailing addresses of all owners)

name Maryland Department of Natural Resources

street & number Tawes State Office Building

telephone

city, town Annapolis

state and zip code Maryland, 21401

4. Location of Legal Description

courthouse, registry of deeds, etc.

tax map and parcel

city, town

liber and folio

5. Primary Location of Additional Data

- Individually Listed in the National Register/Maryland Register
- Contributing Resource in National Register District
- Contributing Resource in Local Historic District
- Determined Eligible for the National Register/Maryland Register
- Recorded by HABS/HAER
- HSR or Research report at MHT
- Other:

6. Classification

Category	Ownership	Current Function	Resource Count		
<input type="checkbox"/> district	<input checked="" type="checkbox"/> public	<input type="checkbox"/> agriculture	<input type="checkbox"/> landscape	Contributing	Noncontributing
<input checked="" type="checkbox"/> building(s)	<input type="checkbox"/> private	<input type="checkbox"/> commerce/trade	<input type="checkbox"/> recreation/ culture	_____	_____
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> defense	<input type="checkbox"/> religion	_____	_____
<input type="checkbox"/> site		<input type="checkbox"/> domestic	<input type="checkbox"/> social	_____	_____
<input type="checkbox"/> object		<input type="checkbox"/> education	<input type="checkbox"/> transportation	_____	_____
		<input type="checkbox"/> funerary	<input type="checkbox"/> work in progress	_____	_____
		<input type="checkbox"/> government	<input type="checkbox"/> unknown	_____	_____
		<input type="checkbox"/> health care	<input checked="" type="checkbox"/> vacant/not in use	_____	_____
		<input type="checkbox"/> industry	<input type="checkbox"/> other:	_____	_____
				Number of Contributing Resources previously listed in the Inventory	

7. Description

Survey No. M: 23-150

Condition

<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated
<input type="checkbox"/> good	<input checked="" type="checkbox"/> ruins
<input type="checkbox"/> fair	<input type="checkbox"/> altered

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

*See Attached

Inventory Number: M: 23-150

House Ruin on Howard Chapel Road

Montgomery Co., MD

C. Mazurek

November 1996

Section 7.1

This house ruin on the west side of Howard Chapel Road is located on the Montgomery County side of the Patuxent River. The house is a total ruin, but there are some elements of the structure left to characterize its essential construction. The plan was originally a one room log structure with a fieldstone chimney on the exterior, and a fieldstone foundation. Later a one room, two story, frame addition was added to the structure as were a porch and a side room that served as a bathroom. The distinctive element of this house is the stone chimney which has two openings on either side for a fireplace and appears to be original to the log construction. Surrounding the house are fieldstone terraces that probably served as a garden and are now overgrown with vegetation. This house appears to date from the early nineteenth century.

8. Significance

Survey No. M: 23-150

Period	Areas of Significance	Check and justify below		
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> health/medicine	<input type="checkbox"/> performing arts
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> archeology	<input type="checkbox"/> education	<input type="checkbox"/> industry	<input type="checkbox"/> philosophy
<input checked="" type="checkbox"/> 1800-1899	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> engineering	<input type="checkbox"/> invention	<input type="checkbox"/> politics/government
<input type="checkbox"/> 1900-1999	<input type="checkbox"/> art	<input type="checkbox"/> entertainment/ recreation	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
	<input type="checkbox"/> commerce	<input type="checkbox"/> ethnic heritage	<input type="checkbox"/> law	<input type="checkbox"/> science
	<input type="checkbox"/> communications	<input checked="" type="checkbox"/> exploration/ settlement	<input type="checkbox"/> literature	<input type="checkbox"/> social history
	<input type="checkbox"/> community planning		<input type="checkbox"/> maritime history	<input type="checkbox"/> transportation
	<input type="checkbox"/> conservation		<input type="checkbox"/> military	<input type="checkbox"/> other:

Specific dates

Builder/Architect

Evaluation for:

National Register Maryland Register not evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, and a narrative discussion of the history of the resource and its context. (For compliance reports, discuss evaluation on a DOE Form - see manual).

*See Attached

Inventory Number: M: 23-150

House Ruin on Howard Chapel Road

Montgomery Co., MD

C. Mazurek

November 1996

Section 8.1

This house appears to date from the early nineteenth century and is significant for its log construction and fieldstone chimney which were typical of building construction during the early settlement of the Patuxent River area of Montgomery County.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Survey No. M: 23-150

Name

Continuation Sheet

Number 8 Page 2

HISTORIC CONTEXT:

MARYLAND COMPREHENSIVE PRESERVATION PLAN DATA

Geographic Organization: Piedmont

Chronological/Developmental Period(s): Agricultural-Industrial Transition

Prehistoric/Historic Period Theme(s): Architecture, Landscape Architecture, Community Planning

Resource Type:

Category: Building


Historic Environment: Rural

Historic Function(s) and Use(s):


Known Design Source: None



MONTGOMERY CO., MD; VICINITY OF UNITY
DRAWN BY C. MAZUREK; NOV 25, 1996
* 3/32 SCALE, GROSS MEASUREMENTS
(OTHER FEATURES ONLY APPROXIMATED)



*HOUSE IS A TOTAL RUIN



9. Major Bibliographical References

Survey No. M: 23-150

10. Geographical Data

Acreage of surveyed property _____

Quadrangle name SANDY SPRINGS

Quadrangle scale 1:24,000

Verbal boundary description and justification

11. Form Prepared By

name/title C. Mazurek, Historic Sites Surveyor

organization Maryland Department of Natural Resources

date 11/96

street & number Tawes State Office Building

telephone 410 974-3771

city or town Annapolis

state and zip code Maryland 21401

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust
DHCD/DHCP
100 Community Place
Crownsville, MD 21032-2 023
410-514-7646

M: 23-150

Branch

HOUSE
RUIN ON
HOWARD
CHapel RD.

WILLIAM BELT
FARM

MONTEGOMERY CO
HOWARD CO

Millard
Creek

495

487

500

521

500

487

500

492

410

565

525

595

483

Cem

BM

501

BM Unity

492

541

520

BM 520

Sunshine

585

450

450

TRIADDELPHIA

481

471

471

452

486

438

Headings

468

446

477

432

471

478

460

446

453

Camp Ben

U.S.G.S. MAP

SANDY SPRINGS, MD.

BM

458

Brighton

489



HOUSE RUIN

M: 23-150

MONTGOMERY CO., MD

C. MAZUREK

NOV 96

MD Dept of NATURAL RESOURCES

SOUTH ELEVATION OF HOUSE AMONG BRUSH

1 OF 8



HOUSE RUIN

M:23-150

MONTGOMERY CO., MD

C. MAZUREK

NOV 96

MD DEPT. OF NATURAL RESOURCES

NORTH VIEW OF COLLAPSED INTERIOR
STAIRCASE

3 OF 8



M:23-150

HOUSE RUIN

MONTGOMERY CO., MD

C. MAZUREK

NOV 96

MD DEPT. OF NATURAL RESOURCES

NORTH ELEVATION

3 OF 8



HOUSE RUIN

M:23-150

MONTGOMERY CO., MD

C. MAZUREK

NOV 96

MD DEPT OF NATURAL RESOURCES

EAST ELEVATION

4 OF 8



HOUSE RUIN

M:23-150

MONTGOMERY CO., MD

C. MAZUREK

NOV 96

MD Dept of NATURAL RESOURCES

SOUTH ELEVATION

5 OF 8



HOUSE RUIN

M:23-150

MONTGOMERY CO., MD

C. MAZUREK

NOV 96

MD Dept of NATURAL RESOURCES

CLOSE UP of FRAMING MATERIALS. NORTH
VIEW

6 OF 8



HOUSE RUIN

M:23-150

MONTGOMERY CO., MD

C. MAZUREK

Nov 96

MD DEPT OF NATURAL RESOURCES

STONE CHIMNEY - NORTH VIEW

7 OF 8



HOUSE RUIN

M:23-150

MONTGOMERY CO., MD

C. MAZUREK

Nov 96

MD Dept. OF NATURAL RESOURCES

STONE CHIMNEY - SOUTH VIEW

8 OF 8