

**MARYLAND HISTORICAL TRUST  
DETERMINATION OF ELIGIBILITY FORM**

Property Name: Structure X12001 (bridge) Inventory Number: HA-2019  
 Address: MD 23 MD 23 over a branch of Deer Creek Historic district: yes  no  
 City: \_\_\_\_\_ Zip Code: \_\_\_\_\_ County: Harford  
 USGS Quadrangle(s): \_\_\_\_\_  
 Property Owner: \_\_\_\_\_ Tax Account ID Number: \_\_\_\_\_  
 Tax Map Parcel Number(s): \_\_\_\_\_ Tax Map Number: \_\_\_\_\_  
 Project: Rehabilitate Structure X12001 Agency: FHWA/SHA  
 Agency Prepared By: Stacie Webb, SHA  
 Preparer's Name: \_\_\_\_\_ Date Prepared: \_\_\_\_\_  
 Documentation is presented in: Project File  
 Preparer's Eligibility Recommendation: \_\_\_\_\_ Eligibility recommended  Eligibility not recommended  
 Criteria: A B C D Considerations: A B C D E F G  
*Complete if the property is a contributing or non-contributing resource to a NR district/property:*  
 Name of the District/Property: \_\_\_\_\_  
 Inventory Number: \_\_\_\_\_ Eligible: yes Listed: yes  
 Site visit by MHT Staff yes  no Name: \_\_\_\_\_ Date: \_\_\_\_\_

Description of Property and Justification: *(Please attach map and photo)*

Based on the information provided by SHA, Structure X12001, which carries MD 23 over a Branch of Deer Creek in Harford County, does not appear to meet National Register Criteria for individual listing. The concrete slab bridge is only 11 foot long and appears to date to between 1912 and 1930. This simple structure was constructed in a period in which the States Roads Commission increasingly relied upon the use of standardized plans. However, the bridge is not an example of standardized design for small structures as it combines (probably) preexisting field stone abutments and wing walls with a concrete slab super structure. The stone abutments and wing walls are in poor condition and will be repaired as part of the proposed undertaking. Thus this bridge does not appear to be a good example of its type and is unlikely to be eligible under Criterion C. In addition, it has no known association with significant events or people and is unlikely to be eligible under Criteria A or B. Lastly, it is not located within the Lower Deer Creek Valley Historic District or any other known historic district.

Note that this structure is not included in the bridge inventory as structures under 20 feet were considered to be "culverts" by FHWA criteria and were thus excluded from the bridge survey.

**MARYLAND HISTORICAL TRUST REVIEW**

Eligibility recommended \_\_\_\_\_ Eligibility not recommended   
 Criteria: A B C D Considerations: A B C D E F G


**MHT Comments:**

E. Hannold  
 Reviewer, Office of Preservation Services

Thursday, March 14, 1996  
 Date

O. Ridout V  
 Reviewer, National Register Program

Friday, March 15, 1996  
 Date



HA- 2019  
Structure X12001  
MD 23 over Branch of Deer Creek  
Harford County  
Norrisville Quad

HA-2019

Structure No. X12001




Looking North toward Structure



East Elevation


Attachment 3  
- MD 23 over Branch of Deer Creek  
X12001  
Photographs

HA-2019



Slab

New wall




Slab

New wall

Attachment 4 Branch of Deer Creek  
— Md 23

X 12001 Photographs

HA-2019



Attachment 5  
Md 23 over Branch of Deer Cr.  
x12001  
Photographs