

File No. 7969 Continued.

CORRESPONDENCE.

property here, by them dredging this Bush Street sewer. They dredge a channel in the middle of this slip of water, and naturally the earth left remaining on the side washes back, and at the same time is carrying the earth from underneath our building along with it, and if you continue to dredge this slip; you will have to drive some piles and sheathing along our bulkhead, or we will certainly hold you liable for any further damage. At the present time our building at the end has sunk considerably, and several feet back from the bulkhead it has developed a crack in both sides of the wall, where it is sinking. Kindly give this your immediate attention.

Yours truly,
(Signed) William Becker & Co.,
Per E. D. B.

File No. 7969.

DEPARTMENT OF PUBLIC IMPROVEMENTS
SUB-DEPARTMENT: HARBOR BOARD
BALTIMORE, MD.

Baltimore, May 7th, 1908.

Mr. W. Cabell Bruce,
City Solicitor.

Dear Sir:-

6131

Enclosed please find copy of letter from J. E. Satter,
Assistant Engineer, in reference to the Becker Company building and bulkhead Bush Street dock; also a small sketch showing the location of building, etc., in reference to the bulkhead.

Yours truly,
(Signed) O. F. Lackey,
Harbor Engineer.